Weekend (\$

TOTAL

Lump Sum / I.B.I: (\$

# **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 20106

#### **Telefax**

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/TP/1386/2019/NS

**Date** : 21-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SMC 9395 G

**AIG Asia Pacific Insurance Pte Ltd** 

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Wenting Janell

Address : 15 Dedap Link

Singapore 809560

Telephone:HP +65 96573839Type of Claim:Third Party ClaimPolicy No.:1900105260

Vehicle No : SDP 9111 Y

Model Code : Audi A3 SEDAN 1.0 TFSI 8V

Model / Year : Jun-19
Engine No : CHZ C29277

Chassis No : WAUZZZ8V1KA064690

Mileage : Date In : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 19-Nov-19

Place of Accident : Entrance To CTE (From Yio Chu Kang Road)

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Estimated Labour Charges for Accident Vehicle SDP 9111 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00 /	
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00	
3	To dismantle and renew rear bumper and rear lid. Align to position. Re-organise rear crash management components. Reinstall all parts removed.		\$ 2,100.00 500	1
4	To respray rear bumper and rear lid.		\$ 1,700.00 //	0
5	To renew rear windscreen.	S/N	\$ 480.00 X	
6	To carry out diagnostic check.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 5,032.00	

# **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### **Telefax**

# Material List for Accident Vehicle Regn No. SDP 9111 Y

S/N	Parts Description		<u>Damaged Parts</u> S/Nett	& Prices Remarks
3/11				
1	REAR BUMPER / JK		\$ 1,708.00	
2	REAR BUMPER FIXING PARTS		\$ 175.00	
3	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 24.00	
4	REAR BUMPER SPOILER - LH		\$ 216.00	
5	REAR LIGHT REFLECTOR - LH / RH 💢	2	\$ 54.00	
6	REAR PARKING AID SENSOR - INNER / OUTER	XI	\$ 462.00	
7	REAR BUMPER SIDE REINFORCEMENT BEAM 🤈		\$ 522.00	
8	REAR BUMPER BRACKET - LH 2		\$ 25.00	
9	REAR BUMPER BRACKET - RH		\$ 26.00	
10	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 120.00	
11	REAR LID		\$ 1,864.00	
12	REAR LID ATTACHMENT PARTS X		\$ 267.00	
13	REAR LID BALL STUD	2	\$ 37.00	
14	PACKING ADHESIVE / //C		\$ 18.00	
15	AUDI EMBLEM / 1'C		\$ 113.00	
16	A3 INSCRIPTION / NC		\$ 87.00	
17	REAR WINDSCREEN ×		\$ 742.00	
18	PRIMER ×		\$ 19.00	
19	SPOILER FIXING PARTS X		\$ 152.00	
20	REAR WINDSCREEN SEALANT X	S/N	\$ 200.00	
21	REAR NO PLATE ×	S/N	\$ 40.00	
22	SUNDRIES ?		\$ 400.00	
	TOTAL SPARE PARTS CHARGES	:	\$ 7,271.00	

# **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

**Telefax** 

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name

Steve (LKK) WIL Mg-L 25/11/19, 1.90 pm 5 days P/P Pg Be fe Spg

Surveyed Date Authorised Date

Excess Cost

Remarks

Liability

**Please Note** 

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	436B
Vehicle Details	
Vehicle No.:	SDP9111Y
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Nov 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSIS TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	CHZC29277
Chassis No.:	WAUZZZ8V1KA064690
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$21,553.00
Original Registration Date:	17 Jun 2019
First Registration Date:	17 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$22,175.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jun 2029
PARF Rebate Amount:	\$16,631.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jun 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,009.00
COE Rebate Amount:	\$28,690.00
Total Rebate Amount:	\$45,321.00

The information contained herein is correct as at 25 Nov 2019

OK