

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:12

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85015168 Date : 20/05/2020 Order : SKX1153D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKX1153D (V 27897) Regn Date: 26/11/2015 Mileage: 63881 WIP No.: 19345
Model: A4 1.8T FSI+MU 8K203H NEW ATTR Chassis: WAUZZZ8K6FA181239 Engine: CJE 114348 Dept: U
You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT FENDER. TO REPAIR FRONT BUMPER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8K0821106J	FENDER Less 020%	1.00	903.50	722.80
X	AN 0161857	POP-RIVET Less 020%	4.00	3.00	9.60
X	A8K0853824C	STONEGUARD Less 020%	1.00	66.20	52.96
X	A8V0853046	ADHES.TAPE Less 020%	1.00	50.00	40.00

Parts 825.36
Labour 0.00
Sublet 2,652.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,477.36

7% GST 243.42

Grand Total 3,720.78



Received by

For & on behalf of
Premium Automobiles Pte Ltd