

CC3/11/19020627/11/19/03

Tang

AIG

Meriman

ASSIGNMENT

From

Date: 20/1/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspected Vehicle No.

SMN 6352S

at Workshop no's

Premium

at

281 Alexandra Road

Insured

Policy No.

1900149286

Claims No.

055075307656

22/1/19

Sum Insured

Excess:

784800

(Client's Record)

Make of Veh:

2pm (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	
N/S	O/S

Bal or Market Value.

4 200K

IDAC Accident Report:

Consistent? - Yes or No

GIA / PR Seen:

Consistent? - Yes or No

Est. Repairs:

5

days

Res: Yes or No

Est. Sum:

%

3 Val: Yes or No

CA / (REV) / REP / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SMN 6352S

20/1/19 Aug

Type

M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Audi A5

Yr

1984

Colour

Grey

AC

Insured / Std / Nil / NA

Sp Reading

URadio

Insured / Std / Nil / NA

Engine

C/N

WAM 222 FS6KA 063036

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

mm

R/Bal

mm

L/Bal

mm

L/Bal

mm

D.O.A.

D.O.L

Survey held at

Premium Alexandra

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Roof

Top

or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMN 6352S - X

21/1/19 @ 11.43am went to Victor via Meriman.
 22/1/19 @ 11.17am Victor informed CIA via Meriman.
 22/1/19 @ 11.33am informed Tray CIA 5 ex: \$800 by email.
 10/03/2020 10.45am confirmed with Mr. Tan for final fig to 9546.56, 5 days.
 (Red to 77386.44, 70%)

Date / Time



Prof. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Res. paid:

Total Fee:

Site Insp. 05:

Ins. Insp. 05:

Total Fee 05:

MER-01

9546.56

Tayf

REF:

ALG

CC3/A1919020627/T19d3

ASSIGNMENT

From:

Date:

20/11/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMN 6352 S

at Workshop m/s

Premium

of

281 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

2pm (waiting)

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value:

4 200K 1782

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMN 6352 S

yr Regn. 2019 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A5

C.C.

1984

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

2190

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAY 222 FS6KA 063036

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

Premium Alexandra 20/11/19 2pm

Des. of Damages

Frnt

Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + RS \$

Photos

Others

T.O/L

Report Format:

Lump Sum / L&B

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wheel and (\$

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 14 November 2019 8:32 AM
To: 'Admin A'; 'Admin-D (LKKAuto)'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIMS FOR SMN 6352 S DOA: 12/11/2019
Attachments: SMN 6352 S 12112019 GIA.PDF

Dear all,

Kindly assist to register this case mentioned. Herein attached with the GIA Report for your reference.

For the estimate repair will forward to you once is available.

Please arrange the survey on 20/11/2019, Wednesday@2pm. Owner waiting at 3S (Alexandra).

Thanks

Best Regards,
TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 March 2020 10:45 AM
To: Boo seng yak; SUR; Carrine Leong; Chang Chee Sing;
jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SMN6352S - OD AIG - SURVEYED 20 NOV 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$9,546.56 before excess \$800.00 & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Friday, 14 February 2020 5:58 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SMN6352S - OD AIG - SURVEYED 20 NOV 19

Hi Taufikh and all,

Revised estimate, photographs and resurvey docs attached.

Please confirm repair cost of \$9546.56 @ 5 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 22 November 2019 11:33 AM
To: Claims; SUR
Subject: RE: OD CLAIMS FOR SMN 6352 S DOA: 12/11/2019

Dear TRoy,

Instructed by our client, please proceed to repair the insured vehicle **SMN 6352S (Excess \$800)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 21 November 2019 11:14 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR SMN 6352 S DOA: 12/11/2019

Dear Shiau Chan,

Herein attached the DL and COI for your information.

Thanks

Best Regards,

TRoy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 19990271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	13 Nov 2019 18:40	Clim Veh Model Changed		[] Merimen Administrator
2	13 Nov 2019 18:40	Clim Created	Reg No: SMN6352S. Policy No: 1900149286. Acct Date: 2019/11/12. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification, C reated from SAS:MPA119150427	[I] Merimen Administrator
3	21 Nov 2019 09:39	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Nivitha Govindasamy
4	21 Nov 2019 09:39	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Nivitha Govindasamy
5	21 Nov 2019 09:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	21 Nov 2019 09:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/02	[A] Nivitha Govindasamy
7	21 Nov 2019 09:39	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	21 Nov 2019 09:39	Clim Registration Modified	Rep:1137->200611.	[A] Nivitha Govindasamy
9	21 Nov 2019 09:39	Clim Veh Model Changed	(206496) AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A).	[A] Nivitha Govindasamy
10	21 Nov 2019 09:39	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
11	21 Nov 2019 11:03	Adj Rpt Initiated		[A] SHIAU CHAN
12	21 Nov 2019 11:03	Clim Dtl Modified	JPJ Reg. Date: -> 2019/08/21.	[A] SHIAU CHAN
13	21 Nov 2019 11:03	Clim Details Notified		[A] SHIAU CHAN
14	21 Nov 2019 11:43	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/12/02	[A] SHIAU CHAN
15	21 Nov 2019 11:43	Adj Mandate Request	Cur.Req:23435.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	21 Nov 2019 17:59	Clim Registration Modified	Init.Est.->4,000 - 5,000. Excess: -> 800.00. Excess Waived: -> 800.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
17	21 Nov 2019 17:59	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	22 Nov 2019 11:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/02. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
19	22 Nov 2019 11:17	Adj Mandate Set	Approved:10274.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2352304	21 Nov 2019 11:03:01	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMN6352S		11.77

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Syed-Yusoff, Saliha

Date: 21 Nov 2019

Preliminary Advice

Vehicle No	: SMN6352S	Accident Date	: 12/11/2019
Make	: AUDI A5	Policy No.	: 1900149286
Assignment Date	: 21/11/2019	Excess	: S\$0.00
Date of Inspection	: 20/11/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,933.00
Revised Amount	:S\$	10,274.00
Check Items (Estimated)	:S\$	13,161.00
Total	:S\$	23,435.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	178,000.00
COE / PARF Rebate	:S\$	73,046.00
Salvage Value	:S\$	
Margin for Repair	:S\$	104,954.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	046F
Vehicle Details	
Vehicle No.:	SMN6352S
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	CVK084991
Chassis No.:	WAUZZZF56KA063036
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$38,148.00
Original Registration Date:	21 Aug 2019
First Registration Date:	21 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$45,408.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2029
PARF Rebate Amount:	\$34,056.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,001.00
COE Rebate Amount:	\$38,990.00
Total Rebate Amount:	\$73,046.00

The information contained herein is correct as at 21 Nov 2019

OK

**Divine Splash: Quality
Paint at Affordable Pri...**

**Should I get rid of COE
car and Change ?**

**GK Detailing - The
Approved Applicator fo...**

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A



2.88% P.A, \$0 Down, \$0 Admin,
Mthly from \$468, 2 Years
Warranty engine, gearbox
GV Credit StarAd

■ Free VICOM evaluation
 ■ Free grooming and 6 months maintenance
 ■ In-house workshop ensures quality service
 ■ Member of SVTA and hire purchase association
 ■ 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

2 vehicles

AUDI A5

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	AUDI A5		Any	Any	2019	Any	Any	Any	Available
	Audi A5 Sportback 2.0A TFSI S-tronic Design		\$175,800	\$16,360 /yr	29-Mar-2019	1,984 cc	11,000 km	Luxury	Available
	Tastefully Modified A5 For Sale Due To Family Reasons. Powerful And Practical Sports Car With 250bhp And 390nm Torque. Ceramic Coat And 3M Crystalline Film From Day 1. Exceptional Fuel Efficiency Of 12.8km/l. 5 Years Warranty And 3 Years Servicing By Premium Auto...								DIRECT OWNER
	Posted: 21-Nov-2019 Tags: 2019 Audi A5, 2019 audi a5, Audi A5, audi a5, Audi, A5, a5, Used Audi								
	Audi A5 Cabriolet 2.0A TFSI S-tronic Design		\$214,999	\$19,660 /yr	28-Feb-2019	1,984 cc	250 km	Sports	Available
	Only 250km Mileage Clocked! Audi Management Unit! Latest A5 Cabriolet With Luscious Tango Red Exterior/Black Hood & Interior! High In-house Loan Approval! 5 Years Audi Agent Warranty Till Feb 2024 (Unlimited Mileage)! Fully Audi Agent Servicing Since Day One! Ban...								PREMIUM AD
	Premium Automobiles Posted: 16-Nov-2019 Tags: 2019 Audi A5, 2019 audi a5, Audi A5, audi a5, Audi, A5, a5, Used Audi								

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used AUDI A5, AUDI A5 Singapore, used AUDI A5 Singapore, used AUDI A5, used vehicles Singapore or even buy used AUDI A5 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 19216

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1363/2019/NS
Date : 15-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chia Swee Cheong
Address : 17 Coronation Road
Singapore 269423
Telephone : (HP) +65 82220920
Type of Claim : Own Damage Claims
Policy No. : 1900149286
Vehicle No : **SMN 6352 S**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 21/8/2019
Engine No : CVK 084991
Chassis No : WAUZZZF56KA063036
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Nov-19
Place of Accident : Newton Road

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 6352 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓✓	
2	To remove and reinstall aircond condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 ? ^{x nn} _{plurfo}	
3	To dismantle and renew front bumper, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,200.00 1000/	
4	To respray front bumper and bonnet.	\$ 2,500.00 1100x	
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 9,772.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 6352 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,073.00	de 1658.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	? X nn
3	FRONT BUMPER SECURING STRIP	\$ 32.00	re 25.40
4	FRONT BUMPER GRILLE - CENTRE	\$ 178.00	Cue 142.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	X
6	FRONT BUMPER SPOILER	\$ 489.00	X } nn
7	FRONT BUMPER AIR GUIDE - LH	\$ 56.00	? X }
8	RADIATOR GRILLE	\$ 2,131.00	Cue 1704.80
9	ULTRASOUND SENSOR SUPPORT - LH / RH	2 \$ 96.00	LH - re nn, RH X nn
10	RADIATOR GRILLE COVER - UPPER	\$ 174.00	? X nn
11	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 431.00	X nn
12	FRONT BUMPER CARRIER	\$ 733.00	? 580 ✓ bt
13	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	? 90.40 ✓ de
14	FRONT BUMPER GUIDE SECTION - LH	\$ 33.00	? X }
15	FRONT BUMPER COVER	\$ 116.00	X } nn
16	CAUTION SIGN STICKER	NEC \$ 13.00	X }
17	AIRCON STICKER	NEC \$ 7.00	X }
18	LOCK CARRIER BRACKET	\$ 125.00	? 100 ✓ Cue ✓
19	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	? X nn
20	FRONT PARKING AID SENSOR - OUTER / INNER	2 \$ 462.00	? X nn
SUB TOTAL SPARE PARTS		: \$	<u>7,889.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 6352 S

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
21	FRONT PARKING AID SEAL RING	4	\$	12.00	nei X
22	HORN - LH HIGH TONE		\$	37.00	? X
23	SPRING SHACKLE - LH		\$	26.00	? X
24	WHEEL SPOILER - LH / RH		\$	66.00	X
25	WHEEL SPOILER TRIM - LH / RH		\$	32.00	X
26	FRONT WHEEL HOUSING LINER - LH / RH		\$	256.00	X
27	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	82.00	X
28	BONNET		\$	2,602.00	bl / 2081.60
29	BONNET ATTACHMENT PARTS		\$	111.00	? X } not
30	BONNET LID HINGE - LH / RH	2	\$	762.00	X
31	BONNET IMPACT PROTECTION - CENTRE / LH / RH	3	\$	75.00	nei 59.44
32	BONNET SOUND ABSORBER		\$	311.00	nei 248.80
33	BONNET GAS FILLED STRUT	2	\$	217.00	X
34	BONNET STRIKER - LH		\$	46.00	X
35	BONNET BOWDEN CABLE - CENTRE		\$	53.00	X
36	BONNET LID LOCK		\$	196.00	X
37	BONNET BOWDEN CABLE - CENTRE		\$	53.00	X
38	BONNET RELEASE LEVER		\$	12.00	X
39	BONNET LID LOCK CABLE		\$	67.00	X
40	LED HEADLIGHT - LH		\$	7,204.00	? X
SUB TOTAL SPARE PARTS		:		<u>\$ 12,220.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 6352 S

S/N	Parts Description		Damaged Parts & Prices		Remarks
			S/Nett		
41	LIFT CYLINDER - LH	\$	181.00	? X	} n/x
42	HEADLIGHT CORRUGATED PIPE	\$	78.00	? X	
43	LOCK CARRIER	\$	928.00	? X	
44	COOLANT REGULATOR SUPPORT	2 \$	69.00	X	
45	EXTERNAL TEMPERATURE SENSOR	\$	54.00	X ? X	
46	TEMPERATURE SENSOR BRACKET	\$	17.00	? X	} n/x
47	READY MIX COOLANT	4 \$	165.00	X	
48	RADIATOR AIR GUIDE - LH / RH	2 \$	56.00	? RH-X n/x	
49	RADIATOR AIR GUIDE - UPPER	\$	15.00	? X	} n/x
50	RADIATOR AIR GUIDE - LH / RH	2 \$	30.00	? X	
51	RADIATOR AIR GUIDE - LOWER	\$	19.00	? X	
52	FRONT NO PLATE	S/N \$	40.00	bt =	
53	SUNDRIES	\$	400.00	? 15.78 ✓ n/x	
TOTAL SPARE PARTS		:	\$ 22,161.00		
TOTAL LABOUR CHARGES		:	\$ 9,772.00		
GRAND TOTAL		:	\$ 31,933.00		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :


21/11/14
Tanpin 97495449
20/11/14 @ 2pm
Not Authorised
EX: to be advise
35 days
Resurvey before paint
sur@hkauto.com

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 19216

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1363/2019/NS
Date : 15-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Taufikh

*5 days exclude 1 Sunday
jb 14 Feb 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chia Swee Cheong
Address : 17 Coronation Road
Singapore 269423
Telephone : (HP) +65 82220920
Type of Claim : Own Damage Claims
Policy No. : 1900149286
Vehicle No : **SMN 6352 S**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 21/8/2019
Engine No : CVK 084991
Chassis No : WAUZZZF56KA063036
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Nov-19
Place of Accident : Newton Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 6352 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To remove and reinstall aircond condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,400.00	
3	To dismantle and renew front bumper, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	5,200.00	\$ 1,000.00
4	To respray front bumper and bonnet.	\$	2,500.00	\$ 1,100.00
5	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 9,772.00	\$ 2,772.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 6352 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,073.00	\$ 1,658.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	
3	FRONT BUMPER SECURING STRIP	\$ 32.00	\$ 25.44
4	FRONT BUMPER GRILLE - CENTRE	\$ 178.00	\$ 142.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	
6	FRONT BUMPER SPOILER	\$ 489.00	
7	FRONT BUMPER AIR GUIDE - LH	\$ 56.00	
8	RADIATOR GRILLE	\$ 2,131.00	\$ 1,704.80
9	ULTRASOUND SENSOR SUPPORT - LH / RH	2 \$ 96.00	
10	RADIATOR GRILLE COVER - UPPER	\$ 174.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 431.00	
12	FRONT BUMPER CARRIER	\$ 733.00	\$ 586.00
13	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	\$ 90.40
14	FRONT BUMPER GUIDE SECTION - LH	\$ 33.00	
15	FRONT BUMPER COVER	\$ 116.00	
16	CAUTION SIGN STICKER	NEC \$ 13.00	
17	AIRCON STICKER	NEC \$ 7.00	
18	LOCK CARRIER BRACKET	\$ 125.00	\$ 100.00
19	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	
20	FRONT PARKING AID SENSOR - OUTER / INNER	2 \$ 462.00	
SUB TOTAL SPARE PARTS		\$ 7,889.00	\$ 4,307.44

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 6352 S

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remarks
				\$ 4,307.44
21	FRONT PARKING AID SEAL RING	4	\$ 12.00	
22	HORN - LH HIGH TONE		\$ 37.00	
23	SPRING SHACKLE - LH		\$ 26.00	
24	WHEEL SPOILER - LH / RH		\$ 66.00	
25	WHEEL SPOILER TRIM - LH / RH		\$ 32.00	
26	FRONT WHEEL HOUSING LINER - LH / RH		\$ 256.00	
27	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 82.00	
28	BONNET		\$ 2,602.00	\$ 2,081.60
29	BONNET ATTACHMENT PARTS		\$ 111.00	
30	BONNET LID HINGE - LH / RH	2	\$ 762.00	
31	BONNET IMPACT PROTECTION - CENTRE / LH / RH	3	\$ 75.00	\$ 59.44
32	BONNET SOUND ABSORBER		\$ 311.00	\$ 248.80
33	BONNET GAS FILLED STRUT	2	\$ 217.00	
34	BONNET STRIKER - LH		\$ 46.00	
35	BONNET BOWDEN CABLE - CENTRE		\$ 53.00	
36	BONNET LID LOCK		\$ 196.00	
37	BONNET BOWDEN CABLE - CENTRE		\$ 53.00	
38	BONNET RELEASE LEVER		\$ 12.00	
39	BONNET LID LOCK CABLE		\$ 67.00	
40	LED HEADLIGHT - LH		\$ 7,204.00	
SUB TOTAL SPARE PARTS			\$ 12,220.00	\$ 6,697.28

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 6352 S

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
		c/f		\$ 6,697.28
41	LIFT CYLINDER - LH		\$ 181.00	
42	HEADLIGHT CORRUGATED PIPE		\$ 78.00	
43	LOCK CARRIER		\$ 928.00	
44	COOLANT REGULATOR SUPPORT	2	\$ 69.00	
45	EXTERNAL TEMPERATURE SENSOR		\$ 54.00	
46	TEMPERATURE SENSOR BRACKET		\$ 17.00	
47	READY MIX COOLANT	4	\$ 165.00	
48	RADIATOR AIR GUIDE - LH / RH	2	\$ 56.00	\$ 22.00
49	RADIATOR AIR GUIDE - UPPER		\$ 15.00	
50	RADIATOR AIR GUIDE - LH / RH	2	\$ 30.00	
51	RADIATOR AIR GUIDE - LOWER		\$ 19.00	
52	FRONT NO PLATE	S/N	\$ 40.00	\$ 40.00
53	SUNDRIES		\$ 400.00	\$ 15.28
TOTAL SPARE PARTS			\$ 22,161.00	\$ 6,774.56
TOTAL LABOUR CHARGES			\$ 9,772.00	\$ 2,772.00
GRAND TOTAL			\$ 31,933.00	\$ 9,546.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant