

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 19321

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1372/2019/NS
Date : 19-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Sin Fai Lam Stephen Ralphy Yoon Nian
Address : 5 Balmoral Road
#09-01
Singapore 259786
Telephone : HP +65 82188279
Type of Claim : Own Damage Claims
Policy No. : 2100482526-03
Vehicle No : **SLG 186 T**
Model Code : Audi A6 1.8 TFSI S -Tronic
Model / Year : 19/9/2016
Engine No : CYG 010911
Chassis No : WAUZZZ4G8GN115383
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Nov-19
Place of Accident : One Raffles Quay Taxi Drop Off

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLG 186 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 1250	
3	To respray front bumper and rhs front fender.	\$ 2,500.00 1100.	
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 x	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 186 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,443.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 45.00	?
3	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 319.00	X NN
4	FRONT BUMPER COVER	\$ 46.00	X NN
5	FRONT WHEEL SPOILER - RH	\$ 242.00	X NN
6	STONE CHIP GUARD	\$ 66.00	X NN
7	ADHESIVE TAPE	\$ 50.00	X NN
8	FRONT FENDER - RH	\$ 1,269.00	bt ✓
9	FRONT FENDER ATTACHMENT PARTS	\$ 92.00	?
10	FRONT FENDER DTONE GUARD FILM - RH	\$ 110.00	ner ✓
11	FRONT FENDER BRACE - RH	\$ 75.00	?
12	FRONT WHEEL HOUSING LINER - RH	\$ 256.00	X NN
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 66.00	X NN
14	HEADLIGHT MOUNTING - RH	\$ 107.00	?
15	FRONT BUMPER BRACE - RH	\$ 27.00	?
16	FRONT BUMPER GUIDE PIECE - RH	\$ 34.00	?
17	LED HEADLIGHT - RH	\$ 8,607.00	cut ✓
18	LIFT CYLINDER - RH	\$ 216.00	X NN
19	FRONT ALUMINIUM RIM - RH	\$ 733.00	X NN
20	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		\$ 15,103.00	
TOTAL LABOUR CHARGES		\$ 6,252.00	
GRAND TOTAL		\$ 21,355.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	:	Tanpin 97495740
Surveyed Date	:	Not to advise
Authorised Date	:	20/11/14 @ 230pm
Excess Cost	:	
Liability	:	Ex: to be advise
Remarks	:	Remuneration before point. Sur @ 1111 auto.com - 05 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel.6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant