

ASS. REC. BY:

REF: es/FCI/19020639/Rtd3 ⁿ²

Special Instruction:

Insured: Result
CWS

ASSIGNMENT (Office)

From (Person): Jason tea

of FCI

Date/Time: 4:49pm @ 20/11/19

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 5720C

Insured: SHC 2178Y

at Workshop m/s Cycle & Carriage Kion

Tel: 65684555

of 209 Penden Gardens

Policy No: _____

Claim No: D1900-7327MFSH

Sum Insured: _____

Excess: _____

Make of Veic:
(Client's Record)

D.O.A. 17/11/2019

CA / REV / REP. / REV 24 HRS 109

H.O.D. Endorsement: _____

Date/Time: 9:50am @ 21/11/19

Person Contacted: Don Bong

Vehicle: IN/OUT

Date/Time	Action/Instruction	Initials
	SMC5720C - X	
	SHC 2178Y - 22/11/19 608551 / Alwbsq2	
<u>22/11 @ 5:37 pm</u>	<u>sent preli advise via email.</u>	
	<u>Confirm part by part \$10634/- 12days (red: 5383' 33%)</u>	



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007327MFSH

Date: 22/11/2019

Our Ref: CS/FCI19020639/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMC 5720C

Please be informed that we had conducted the inspection of the abovementioned vehicle 21/11/2019 at the premises of M/s Cycle and Carriage have the following to report: -

Workshop Estimate Amount	: S\$ <u>16,017.00</u>
Revised Estimate Amount	: S\$ <u>4,334.00</u>
"Check" Items Amount	: S\$ <u>3,493.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the n/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-11-2019	Our Ref No. D19007327MFSH
Accident Date	17-11-2019	Claim Type. Third Party
Insured Vehicle	SHC2178Y	Third Party Vehicle. SMC5720C
Survey Location	209 PANDAN GARDENS	
Contact Person.	DON BONG	
Contact No.	65684555/ 0	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT: WE AGREED TO DIRECT SETTLEMENT. PLEASE VERIFY DAMAGE CONSISTENCY.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE KIA PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 10 January 2020 4:08 PM
To: Songcuan JR Lauro Araos; Rasul (LKKAuto)
Cc: Andre Chow En De; Loi Ai Ting; Jojo Cheng; Don Bong Kiong Hua
Subject: RE: SMC5720C (KIA) - FINALIZE TP CLAIM (FIRST CAPITAL)

Dear Sir,

Confirm part by part \$10,634.00 before GST, 12days

Please sent your relevant document directly to MS First Capital

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>
Sent: Tuesday, 7 January 2020 4:37 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Jojo Cheng <jojo.cheng@cyclecarriage.com.sg>; Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>
Subject: SMC5720C (KIA) - FINALIZE TP CLAIM (FIRST CAPITAL)

Dear Rasul,

Pls. refer to attached files and photos.

Kindly confirm finalized amount of \$ 10,634.00 before Gst.

Thank you so much.

Best regards,

Larry Songcuan
Customer Service



Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4658 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 22 November 2019 5:37 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007327MFSH/1
Attachments: PRELI ADVISED OF SMC 5720C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMC 5720C**
Number of days (estimated) : 12 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 21 November 2019 9:52 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007327MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 20 November 2019 4:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007327MFSH/1



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Teo Qijie (Zhang Qijie)
Period of Insurance : 11 Jul 2018 To 10 Jul 2020
Engine No. : G4FGJH696514
Chassis No. : KNAFX411MJ5766453

Vehicle No. : SMC5720C
Policy No. : 1800075382
Endorsement No. :
Issued Date : 24 Jul 2018

ABOUT THE COVER

Make/Model : KIA Cerato K3 1.6 EX
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 180) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Teo Qijie (Zhang Qijie) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
- Cycle & Carriage Authorized Service Centre Add: 241 Alexandra Road Singapore 159931 64278800
- Cycle & Carriage Authorized Service Centre (For windscreen claim only) Add: 330 Ulu Rd 3 Singapore 408650 67481000

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 180), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0504624050

FULCOKJCP2 - CORPORATE
 22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TEO QIJIE (ZHANG QIJIE)	Cust No/Name LCV06133/TEO QIJIE (ZHANG QIJIE)
BLK 412 EUNOS ROAD 5 #04-112 SINGAPORE 400412	Reg No/Reg Date SMC5720C / 11/07/201
Contact No	Date In/Mileage / 13018
	Chassis No KNAFX411MJ5766453
	Engine No G4FGJH696514
	Make/Model KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV06133	CRDVCH	18/11/2019/ 10:46	QUD	247 / DonBong	62047

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON LH REAR DOOR, LH FRONT DOOR, CUT/WELD LH REAR FENDER, REPAIR REAR BUMPER FACE				3380.00 2750 ✓
E PNT88000 REMOVE AND INSTALL PARKING SENSOR				60 80.00 ✓
E PNT88000 REMOVE AND TRANSFER LH REAR DOOR PANEL TRIM, DOOR GLASS, MECHANSIM AND OTHERS TO FACILITATE REPAIR WORK				200.00 ✓
E PNT88000 REMOVE AND TRANSFER LH FRONT DOOR PANEL TRIM, DOOR GLASS, MECHANSIM AND OTHERS TO FACILITATE REPAIR WORK				200.00 ✓
E PNT88000 REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR WORK				X 240.00
M SUNDRY SUPPLY REAR WINDSCREEN SEALANT				X 80.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, LH REAR FENDER, LH REAR DOOR, LH FRONT DOOR, LH SIDE SILL AND AFFECTED PORTION				2520.00 1680 ✓
M SUNDRY APPLY BODY SEALANT				180 240.00 ✓
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 50.00 ✓
M SUNDRY PERFORM RUST PREVENTION				100 160.00 ✓
A 30000001 REMOVER AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK				550.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✓
M SUNDRY SUPPLY LH REAR SPORT RIM SSW266				400.00 ✓
M SUNDRY LABOUR RENEW LH REAR SPORT RIM AND INCLUDING BALANCING				30.00 ✓

Estimate

Confirm & accepted by

Authorized signatory and company stamp

• Repairs to be carried out in accordance with the manufacturer's instructions
 • Parts to be replaced as per the manufacturer's instructions
 • The work to be carried out on a "Without Prejudice" basis
 • The cost of the work to be carried out is to be agreed in writing
 • The cost of the work to be carried out is to be agreed in writing
 • The cost of the work to be carried out is to be agreed in writing

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TEO QIJIE (ZHANG QIJIE)	Cust No/Name LCV06133/TEO QIJIE (ZHANG QIJIE)
BLK 412 EUNOS ROAD 5 #04-112 SINGAPORE 400412	Reg No/Reg Date SMC5720C / 11/07/201
Contact No	Date In/Mileage / 13018
	Chassis No KNAFX411MJ5766453
	Engine No G4FGJH696514
	Make/Model KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV06133	CRDVCH	18/11/2019/ 10:46	QUD	247 / DonBong	62047

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 20000001 RENEW REAR UNDERCARRIAGE DAMAGES				550.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY SUNDRIES				50.00
M PANEL ASSY-QUARTER OUTER, LH <i>bt</i>	1.00	1133.00	00.00	1133.00
M PANEL ASSY-RR COMB LAMP HSG, LH <i>? x500</i>	1.00	166.00	00.00	166.00
M FILM-ANTI CHIPPG LH <i>? #nyan</i>	1.00	27.00	00.00	27.00
M PANEL ASSY-REAR DOOR, LH <i>bt</i>	1.00	1309.00	00.00	1309.00
M MOTOR ASSY-POWER WDO REG RR, LH <i>? x500</i>	1.00	155.00	00.00	155.00
M REGULATOR ASSY-RR DR WDO LH <i>? x500</i>	1.00	327.00	00.00	327.00
M GLASS ASSY-REAR DOOR, LH <i>? x500</i>	1.00	181.00	00.00	181.00
M BLACK TAPE-RR DR FRAME UP, LH <i>ne</i>	1.00	11.00	00.00	11.00
M BLACK TAPE-RR DR FRAME RR, LH <i>ne</i>	1.00	8.00	00.00	8.00
M W/STRIP ASSY-RR DR BELT O/S LH <i>ne</i>	1.00	89.00	00.00	89.00
M BASE ASSY-FR DR O/S HANDLE LH <i>? x500</i>	1.00	52.00	00.00	52.00
M LATCH ASSY-REAR DOOR, LH <i>? x500</i>	1.00	309.00	00.00	309.00
M CHECKER ASSY-REAR DOOR, LH <i>? x500</i>	1.00	32.00	00.00	32.00
M PANEL ASSY-FRONT DOOR, LH <i>bt</i>	1.00	1529.00	00.00	1529.00
M BLACK TAPE-FRT DOOR FRAME UP, <i>ne</i>	1.00	13.00	00.00	13.00
M BLACK TAPE-FR DR RR, LH <i>ne</i>	1.00	12.00	00.00	12.00
M MOULDING-REAR WINDOW GLASS <i>? x500</i>	1.00	27.00	00.00	27.00
M HUB ASSY-RR WHEEL <i>? x500</i>	1.00	340.00	00.00	340.00
M TORSION AXLE COMPLETE <i>? x500</i>	1.00	1096.00	00.00	1096.00
M SHOCK ABSORBER ASSY-REAR <i>? x500</i>	1.00	231.00	00.00	231.00

SURVEYOR NAME: ASUL-Hy 90010068
 SURVEYOR SIGNATURE: [Signature]
 DATE: 21/11/19 @ 1620
 REMARKS: 12 days

Confirm & accepted by

Remove before paint

Nett	16,017.00
7% GST on	16017.00
Total Payable	17,138.19

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



TP CLAIM
FIRST CAPITAL
LVK - PASUL

VEHICLE NO : SMC 5720 C

MODEL : 14A / CERATO K3 1.6 A EX

WIP : 62047

Material	: \$	<u>4,104.00</u>
Labour	: \$	<u>6,530.00</u>
Sub-Total	: \$	<u>10,634.00</u>
Less 2% Disc	: \$	<u>—</u>
Less Excess	: \$	<u>—</u>
Total	: \$	<u>10,634.00</u>
GST 7%	: \$	<u>744.38</u>
Grand Total	: \$	<u>11,378.38</u>
Finalise By/Date	:	<u>Amuly on 07/01/20</u>


REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 12 WORKING DAYS 6 days (3 wk. ends)

* TP VEHICLE NO : SHC2178Y

* claim loss of RENTAL.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TEO QIJIE (ZHANG QIJIE) BLK 412 EUNOS ROAD 5 #04-112 SINGAPORE 400412 Contact No Mobile: 98443877 21/11/2019	Cust No/Name LCV06133/TEO QIJIE (ZHANG QIJIE) Reg No/Reg Date SMC5720C / 11/07/2018 Date In/Mileage 21/11/2019/ 13018 Chassis/Package KNAFX411MJ5766453 /KC17P(F) Engine No G4FGJH696514 Make/Model KIA/CERATO K3 1.6 A EX CAP Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	07/01/2020/ 15:58	TLD	884 / Lauro Songcuan	62047

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X PANEL ASSY-QUARTER OUTER,LH ✓	1.00	1133.00	00.00	1133.00
X PANEL ASSY-REAR DOOR,LH ✓	1.00	1309.00	00.00	1309.00
X BLACK TAPE-RR DR FRAME UPR,LH ✓	1.00	11.00	00.00	11.00
X BLACK TAPE-RR DR FRAME RR,LH ✓	1.00	8.00	00.00	8.00
X W/STRIP ASSY-RR DR BELT O/S LH ✓	1.00	89.00	00.00	89.00
X PANEL ASSY-FRONT DOOR,LH ✓	1.00	1529.00	00.00	1529.00
X BLACK TAPE-FRT DOOR FRAME UPR, ✓	1.00	13.00	00.00	13.00
X BLACK TAPE-FR DR RR,LH ✓	1.00	12.00	00.00	12.00

Z TEXT

TP CLAIM FIRST CAPITAL - SHC2178Y
SURVEY: RASUL 21.11.2019
DOA:17.11.2019
12 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,104.00		Nett	10,634.00
Labour	5,790.00	7% GST on	10634.00	744.38
Standard Menu	0.00			
Specialist Job	430.00		Total Payable	11,378.38
Diagnostics Job	0.00			
Sundry/Others	310.00			
Total(w/o GST)	10,634.00			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19020639/R11d3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-01-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2178Y	Veh. Inspected	SMC 5720C
Policy No.		Coverage (\$)	0.00
Claim No.	D19007327MFSH	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	20/11/2019
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO K3 1.6A	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAFX411MJ5766453	Colour	BLACK
Odometer	13018	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEXEN	6 mm
L/H Front Tyre	205/55 R16	NEXEN	6 mm
R/H Rear Tyre	205/55 R16	NEXEN	6 mm
L/H Rear Tyre	205/55 R16	NEXEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/11/2019	Inspection Date	21/11/2019
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 5720C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL ASSY-QUARTER OUTER LH (SN)	BENT	1,133.00	1,133.00
1	PANEL ASSY-RR COMB LAMP HSG,LH (SN)	SERVICEABLE	166.00	-
1	FILM-ANTI CHIPPG LH (SN)	NOT NECESSARY	27.00	-
1	PANEL ASSY-REAR DOOR,LH (SN)	BENT	1,309.00	1,309.00
1	MOTOR ASSY-POWER WDO REG RR,LH (SN)	SERVICEABLE	155.00	-
1	REGULATOR ASSY-RR DR WDO LH (SN)	SERVICEABLE	327.00	-
1	GLASS ASSY-REAR DOOR,LH (SN)	SERVICEABLE	181.00	-
1	BLACK TAPE-RR DR FRAME UPR,LH (SN)	NECESSARY	11.00	11.00
1	BLACK TAPE-RR DR FRAME RR,LH (SN)	NECESSARY	8.00	8.00
1	W/STRIP ASSY-RR DR BELT O/S LH (SN)	NECESSARY	89.00	89.00
1	BASE ASSY-FR DR O/S HANDLE LH (SN)	SERVICEABLE	52.00	-
1	LATCH ASSY-REAR DOOR,LH (SN)	SERVICEABLE	309.00	-
1	CHECKER ASSY-REAR DOOR,LH (SN)	SERVICEABLE	32.00	-
1	PANEL ASSY-FRONT DOOR,LH (SN)	BENT	1,529.00	1,529.00
1	BLACK TAPE-FRT DOOR FRAME UPR (SN)	NECESSARY	13.00	13.00
1	BLACK TAPE-FR DR RR,LH (SN)	NECESSARY	12.00	12.00
1	MOULDING-REAR WINDOW GLASS (SN)	SERVICEABLE	27.00	-
1	HUB ASSY-RR WHEEL (SN)	SERVICEABLE	340.00	-
1	TORSION AXLE COMPLETE (SN)	SERVICEABLE	1,096.00	-
1	SHOCK ABSORBER ASSY-REAR (SN)	SERVICEABLE	231.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	LH REAR SPORT RIM SSW266 (SN)	SCRATCHED	400.00	400.00
			7,497.00	4,534.00
LABOUR				
RENEW ACCIDENT DAMAGED PARTS ON LH REAR DOOR,LH FRONT DOOR,CUT/WELD LH REAR FENDER,REPAIR REAR BUMPER FACE.			3,300.00	2,750.00
REMOVE AND INSTALL PARKING SENSOR.			80.00	60.00
REMOVE AND TRANSFER LH REAR DOOR PANEL TRIM,DOOR GLASS,MECHANISM AND OTHERS TO FACILITATE REPAIR WORK.			200.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND TRANSFER LH FRONT DOOR PANEL TRIM, DOOR GLASS, MECHANISM AND OTHERS TO FACILITATE REPAIR WORK.		200.00	200.00
	REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR WORK.	NOT NECESSARY	240.00	-
	SUPPLY REAR WINDSCREEN SEALANT.	NOT NECESSARY	80.00	-
	PAINT WORK SPRAY REAR BUMPER, LH REAR FENDER, LH REAR DOOR, LH FRONT DOOR, LH SIDE SILL AND AFFECTED PORTION.		2,520.00	1,680.00
	APPLY BODY SEALANT.		240.00	180.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	PERFORM RUST PREVENTION.		160.00	100.00
	REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK.		550.00	550.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.		120.00	120.00
	LABOUR RENEW LH REAR SPORT RIM AND INCLUDING BALANCING.		30.00	30.00
	RENEW REAR UNDERCARRIAGE DAMAGES.	NOT NECESSARY	550.00	-
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
			8,520.00	6,100.00
GRAND TOTAL			16,017.00	10,634.00
RECOMMENDED COST OF REPAIRS				10,634.00

Report Ref No. CS/FCI19020639/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.