

威利摩多 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

21, NOV 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building
#07-16 S 079120

*Not within
11 days @ 2350h
Pursuing After Point
4 days*

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: GBF8103D
Accident involving vehicle no: SKX4028M/GBF8103D
DOA: 19/11/2019 AT Serangoon North Avenue 4 carpark

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SKX4028M
To supply--

Description	Qty	Amount
Front fender,Lh	1 <i>RT</i>	773.40 ✓
Front wheel bearing	1 <i>RT</i>	119.43 <i>X</i>
Front wheel bearing hup	1 <i>RT</i>	179.90 <i>X</i>
Front absorber,Lh	1 <i>RT</i>	425.50 <i>X</i>
Linkage,Lh	1 <i>RT</i>	178.70 <i>X</i>
Lower arm	1 <i>RT</i>	459.33 <i>X</i>
Rim,Lh	1 <i>RT</i>	280.00 <i>250h</i>
Headlamo	1 <i>RT</i>	1,050.00 <i>X</i>
Parts		3,466.26
Parts less 25%		866.57
		2,599.69
<i>RT buyer</i>	<i>CR</i>	

To remove damaged parts and attachments.
Repair/reshape dented areas
Straighten front pillar
Replace/align above parts into position.
To spray paint
To remove/replace undercarriage parts
Redo wheel alignment

400l
950.00
400l
800.00
350.00 *160l*
80.00 *60l*

4,779.69

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-58/60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CITY AUTO PTE LTD

BLK 8 SIN MING IND. EST., #01-58/60/62
 SINGAPORE 575643

Phone Number: 6453-1235

Fax Number: 6453-7944

Customer:	KA HUP	Date:	11/22/2019 1:05 PM
Company:		VIN	
License NO:	SKX 4028M	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

TOYOTA, WISH ZNE10G(2WD), 03-03 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3°15'	2°20'	3°49'	3°18'
		Right	3°33'	2°20'	3°49'	3°36'
	Camber	Left	-1°30'	-1°15'	0°15'	-1°30'
		Right	-0°48'	-1°15'	0°15'	-0°48'
	Toe	Left	0°06'	0°05'	0°05'	0°03'
		Right	0°18'	0°05'	0°05'	0°03'
Total		0°24'	0°11'	0°11'	0°06'	
Rear	Camber	Left	-1°12'	-2°15'	-0°45'	-1°12'
		Right	-2°00'	-2°15'	-0°45'	-2°00'
	Toe	Left	0°06'	0°01'	0°13'	0°06'
		Right	0°06'	0°01'	0°13'	0°06'
		Total	0°18'	0°03'	0°25'	0°12'
	Thrust Angle		0°00'	---		0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	11°41'	11°20'	11°20'	11°41'
		Right	11°32'	11°20'	11°20'	11°32'
Included Angle		Left	10°11'	---	---	10°11'
		Right	10°44'	---	---	10°44'
Toe Out On Turns		Left	---	---	---	---
		Right	---	---	---	---
Max Turn Inside		Left	---	---	---	---
		Right	---	---	---	---
Toe Curve Change		Left	---	---	---	---
		Right	---	---	---	---
Setback		Front	-2mm	---	---	-2mm
		Rear	-5mm	---	---	-5mm
Track Width Diff.			11mm			11mm
Wheel Base Diff.			3mm			3mm
Front Ride Height		Left	---	---	---	---
		Right	---	---	---	---
Rear Ride Height		Left	---	---	---	---
		Right	---	---	---	---

威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

22,NOV 2019

AIG Asia Pacific Insurance PL

CC: LKK Auto Consultants

Supplementary parts for vehicle no: SKX4028M

To supply—

1	pc	Front bumper	CM \$	574.90	—
1	pc	Bumper retainer	Orl \$	55.30	—

				\$	630.20