

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 29 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX433843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:A29127060AT2 ACC DATE:18/11/19 TOW IN:18/11/19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP				162.00
3	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
4	B	BP-MECH2 R/I AIRCOND PIPE VACCUM AND REGAS				324.00
5	B	BP-MECH2 REPL DASHBOARD				1296.00
6	B	BP-LAB2 R/I WHOLE INTERIOR TO FAC REPAIR				1180.80
7	B	BP-MECH2 REPL WHOLE WIRING HARNESS TO FAC REPAIR				1296.00
8	B	BP-MECH2 REPL SEAT BEAUT ASSY				648.00
9	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				180.00
10	B	BP-MECH2 REPL AIRBAG ECU AND SENSOR AND RESET AIR BAG SYSTEM				648.00
11	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				3240 6480.00
12	B	BP-RES2 RESPRAY ACC AFF AREA				3717 5210.00
13	Z	BP-SLANT SUPPLY SEALANT (NETT)				160 200.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	PLEASE TEAR ALONG PERFORATED LINE 4135802 4135802

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	1	S88300-0D530 AIR CON KIT (NEW VIOS 2016) ?	1.00	3026.60		3026.60
15	2	SPC593-0D007 S1 LED FOG LAMP SET ?	1.00	387.80		387.80
16	3	S12611-0Y110 COVER, ENGINE, NO.1 ?	1.00	205.30	25.00	153.97
17	4	S16400-0Y191 RADIATOR ASSY <i>by</i>	1.00	2052.20	25.00	1539.15
18	5	S16523-0M050 CUSHION, RADIATOR SU <i>ne</i>	2.00	6.10	25.00	9.14
19	6	S16361-0M110 FAN ?	1.00	241.20	25.00	180.90
20	7	S16711-0Y160 SHROUD, FAN ?	1.00	264.70	25.00	198.52
21	8	S16363-0Y050 MOTOR, COOLING FAN ? ?	1.00	562.50	25.00	421.87
22	9	S16571-0Y101 HOSE, RADIATOR, NO.1 ?	1.00	51.60	25.00	38.70
23	0	S90916-T2042 BELT, V-RIBBED ?	1.00	147.80	25.00	110.85
24	1	T17167-0Y050 INSULATOR, EXHAUST ?	1.00	103.70	25.00	77.77
25	2	T17168-0Y050 INSULATOR, EXHAUST ?	1.00	103.70	25.00	77.77
26	3	S17700-0Y190 CLEANER ASSY, AIR W/ <i>gn</i>	1.00	1077.90	25.00	808.42
27	4	S17771-0Y080 BRACKET, AIR CLEANER ?	1.00	30.30	25.00	22.72
28	5	S17751-0Y261 INLET, AIR CLEANER ?	1.00	69.90	25.00	52.42
29	6	S17882-0Y140 HOSE, AIR CLEANER, N <i>de</i>	1.00	103.00	25.00	77.25
30	7	S81110-0DF00 HEADLAMP ASSY, RH <i>bro</i>	1.00	1285.00	25.00	963.75
31	8	S81150-0DF00 HEADLAMP ASSY, LH <i>bro</i>	1.00	1285.00	25.00	963.75
32	9	S82115-0U291 WIRE, ENGINE ROOM MA ?	1.00	3378.70	25.00	2534.02
33	0	S82121-0DY51 WIRE, ENGINE ?	1.00	2577.20	25.00	1932.90
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135803

TO SECURITY GUARD

4135803

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97960991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 .60D/SJS1638K/211111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	1	S82140-0D130 WIRE ASSY, INSTRUMEN ?	1.00	19.00	25.00	14.25
35	2	S82661-52050 COVER, RELAY BLOCK ?	1.00	22.50	25.00	16.87
36	3	S82741-0D100 BLOCK, ENGINE ROOM R ?	1.00	138.20	25.00	103.65
37	4	S82662-0D520 COVER, RELAY BLOCK, ?	1.00	55.00	25.00	41.25
38	5	S84307-0D170 CABLE SUB-ASSY, SPIR ?	1.00	1077.90	25.00	808.42
39	6	S89175-0D060 BRACKET, AIR BAG SEN	1.00	30.30	25.00	22.72
40	7	S89173-09C00 SENSOR, AIR BAG, FR	1.00	374.60	25.00	280.95
41	8	S89170-0DB10 SENSOR ASSY, AIR BAG	1.00	1203.80	25.00	902.85
42	9	S89831-02260 SENSOR, SIDE AIR BAG	2.00	691.00	25.00	1036.50
43	0	S85315-0D220 JAR ASSY, WINDSHIELD	1.00	145.80	25.00	109.35
44	1	S74431-0D210 TRAY, BATTERY ?	1.00	59.80	25.00	44.85
45	2	S74404-0D170 CLAMP SUB-ASSY, BATT ?	1.00	33.30	25.00	24.97
46	3	S63310-0DC20 AO HEADLINING ASSY, ROO	1.00	1827.20	25.00	1370.40
47	4	S55302-0D240 CO PANEL SUB-ASSY, INST	1.00	884.50	25.00	663.37
48	5	S73960-0D160 AIR BAG ASSY, INSTR ?	1.00	3883.10	25.00	2912.32
49	6	S45130-0D410 CO PAD ASSY, STEERING W	1.00	2867.40	25.00	2150.55
50	7	S52721-0D290 MOULDING, FR BUMPER	1.00	72.40	25.00	54.30
51	8	S53112-0D540 GRILLE, RADIATOR, LW	1.00	269.50	25.00	202.12
52	9	S53113-0D020 GRILLE, RADIATOR, LW	1.00	90.90	25.00	68.17
53	0	S52119-0U932 COVER, FR BUMPER, L/	1.00	495.70	25.00	371.77
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135804

TO SECURITY GUARD

4135804

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 .60D/SJS1638K/211111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
54	1	S52127-0D680 COVER, FR BUMPER HOL ?	1.00	88.50	25.00	66.37
55	2	S52128-0D430 COVER, FR BUMPER HOL mis	1.00	88.50	25.00	66.37
56	3	S52535-0D230 RETAINER, FR BUMPER ne	1.00	100.40	25.00	75.30
57	4	S52536-0D230 RETAINER, FR BUMPER ne	1.00	100.40	25.00	75.30
58	5	S52161-0K040 PIECE, RR BUMPER ne	10.00	4.10	25.00	30.70
59	6	S81483-0D030 COVER, DAYTIME RUNNI ?	1.00	74.70	25.00	56.02
60	7	S81484-0D010 COVER, DAYTIME RUNNI ?	1.00	74.70	25.00	56.02
61	8	S52021-0D140 REINFORCEMENT SUB-AS repair	1.00	399.50	25.00	299.62
62	9	S53111-0D912 GRILLE, RADIATOR, OU ca	1.00	71.30	25.00	53.47
63	0	S53123-0D260 MOULDING, RADIATOR G ca	1.00	39.40	25.00	29.55
64	1	S53124-0D380 MOULDING, RADIATOR G ca	1.00	35.00	25.00	26.25
65	2	S53114-0D020 GRILLE, RADIATOR, IN ca	1.00	239.80	25.00	179.85
66	3	S53119-0D010 PROTECTOR, RADIATOR ca	1.00	14.60	25.00	10.95
67	4	S53301-0D280 HOOD SUB-ASSY bu	1.00	924.70	25.00	693.52
68	5	S53801-0D100 FENDER SUB-ASSY, FR bt	1.00	765.30	25.00	573.97
69	6	S53802-0D100 FENDER SUB-ASSY, FR repair	1.00	765.30	25.00	573.97
70	7	S53341-0D310 INSULATOR, HOOD de	1.00	280.80	25.00	210.60
71	8	S90467-09050 CLIP ne	6.00	2.90	25.00	13.02
72	9	S53866-0D220 SEAL, FR FENDER TO C ?	1.00	56.50	25.00	42.37
73	0	S53867-0D220 SEAL, FR FENDER TO C ne	1.00	56.50	25.00	42.37
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135805

TO SECURITY GUARD

4135805

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
10	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
74	1	S53875-0D660 LINER, FR FENDER, RH	1.00	222.80	25.00	167.10
75	2	S53876-0D660 LINER, FR FENDER, LH	1.00	222.80	25.00	167.10
76	3	S53208-0D901 SUPPORT SUB-ASSY, HO	1.00	149.90	25.00	112.42
77	4	S53141-0D040 COVER, RADIATOR	1.00	273.50	25.00	205.12
78	5	T90541-15111 CUSHION	2.00	6.20	25.00	9.30
79	6	S53210-0D929 SUPPORT ASSY, RADIAT	1.00	978.70	25.00	734.02
80	7	S53285-0D370 SEAL, RADIATOR SIDE	1.00	80.10	25.00	60.07
81	8	S53286-0D370 SEAL, RADIATOR SIDE	1.00	80.10	25.00	60.07
82	9	S53287-0D260 EXTENSION, RADIATOR	1.00	64.60	25.00	48.45
83	0	S53288-0D250 EXTENSION, RADIATOR	1.00	72.40	25.00	54.30
84	1	S53714-0D200 EXTENSION, FR FENDER	1.00	51.20	25.00	38.40
85	2	S53713-0D200 EXTENSION, FR FENDER	1.00	51.20	25.00	38.40
86	3	S53510-0D770 LOCK ASSY, HOOD	1.00	135.60	25.00	101.70
87	4	S53410-0D400 R/FRT BONNET HINGE	1.00	58.90	25.00	44.17
88	5	S53420-0D400 L/FRT BONNET HINGE	1.00	58.90	25.00	44.17
89	6	S53452-0D090 HOLDER, HOOD STAY	1.00	20.30	25.00	15.22
90	7	T90480-T0002 GROMMET	1.00	6.60	25.00	4.95
91	8	S57201-0D021 EXTENSION SUB-ASSY,	1.00	182.80	25.00	137.10
92	9	S57202-0D031 EXTENSION SUB-ASSY,	1.00	182.80	25.00	137.10
93	0	S73220-0D500 AO BELT ASSY, FR SEAT,	1.00	995.10	25.00	746.32
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135806

TO SECURITY GUARD

4135806

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 :60D/SJS1638K/211111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
94	1	S90975-T2008 EMBLEM, SYMBOL	1.00	58.40	25.00	43.80
95	2	S73210-0D510 A0 BELT ASSY, FR SEAT,	1.00	995.10	25.00	746.32
96	3	S62170-0D080 AIR BAG ASSY, CURTAIN	1.00	1485.60	25.00	1114.20
97	4	S62180-0D080 AIR BAG ASSY, CURTAIN	1.00	1485.60	25.00	1114.20
98	5	T62189-42010 SPACER, CURTAIN	4.00	2.20	25.00	6.60
99	6	S62211-0D840 A0 GARNISH, FR PILLAR,	1.00	129.10	25.00	96.82
100	7	S62212-0D840 A0 GARNISH, FR PILLAR,	1.00	129.10	25.00	96.82

Handwritten notes:
Rasul
Hp 90010068
12 days
22/11/19 @ 1545
EXCESS = 500
Rasul
Resin before paint

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	52,002.53
	Please acknowledge receipt of vehicle	Parts 34,097.73 Labour 17,824.80 Materials 80.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	3,640.18
			Less	0.00
			Amount Due	55,642.71

PLEASE TEAR ALONG PERFORATED LINE

4135807

TO SECURITY GUARD

4135807

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019

TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape