

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Acknowledged by Repairer
Signature: *[Signature]*
Date: CHEE WHEE, RAYMOND
105 JALAN RAJAH
#08-79
Singapore 320105

Quotation

Non binding - Preview

Page 1/2

Document no.
Document date 21-11-2019
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 39999
Job order number 2019002762/ 1
Job order date 21-11-2019
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SKU4932T	1634G5	30-07-2015	VWVZZZ16ZFM029853	JETTA TSI High 90 D7F	62,785

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs. <i>NEC</i>	280.00 ✓	#1	280.00	299.60
	Diagnostic and Programming	1	pcs. <i>NEC</i>	480.00 ✓	#1	480.00	513.60
5C6827025E	Rear Trunk Lid	1	pcs. <i>X R</i>	1,885.72	#1	1,885.72	2,017.72
8D0853419D	Packing Adhesive	1	pcs. <i>X SVC</i>	27.03	#1	27.03	28.92
	RR NUMBER PLATE PACKING						
WHT007341	Rivitted Cap Nut	4	pcs. <i>X SVC</i>	1.88	#1	7.52	8.05
5C6853630F ULM	Vw Sign Chrome Colored/BI	1	pcs. <i>/ NEC</i>	81.94 ✓	#1	81.94	87.68
5C6853687 739	Inscription Brilliant Chr	1	pcs. <i>/ NEC</i>	58.14 ✓	#1	58.14	62.21
	NAME PLATE - JETTA						
5C6853675APGQF	Inscription Chrome/Red	1	pcs. <i>/ NEC</i>	61.92 ✓	#1	61.92	66.25
	NAME PLATE - TSI						
5C6807421H GRU	Cover For Bumper Primed	1	pcs. <i>/ DB</i>	1,344.03 ✓	#1	1,344.03	1,438.11
5C6807433J	Spoiler	1	pcs. <i>? X SVC</i>	460.31 <i>X SVC</i>	#1	460.31 <i>X</i>	492.53
5C6807305	Bumper	1	pcs. <i>? X SVC</i>	603.37 <i>X SVC</i>	#1	603.37 <i>X</i>	645.61
	REINFORCEMENT						
5C6807863B	Attachment Strip	1	pcs. <i>? X SVC</i>	72.88 <i>X SVC</i>	#1	72.88 <i>X</i>	77.98
	RR BUMPER CENTRE BRACKET						
5C6807393E	Guide Piece	1	pcs. <i>X SVC</i>	78.37	#1	78.37	83.86
	TAILLIGHT LOWER BRACKET LH						
5C6807394E	Guide Piece	1	pcs. <i>X SVC</i>	78.37	#1	78.37	83.86
	TAILLIGHT LOWER BRACKET RH						
5C6807375	Guide Piece	1	pcs. <i>? X SVC</i>	78.37 <i>X SVC</i>	#1	78.37 <i>X</i>	83.86
	BUMPER SIDE BRACKET LH						
5C6807376	Guide Piece	1	pcs. <i>? X SVC</i>	78.37 <i>X SVC</i>	#1	78.37 <i>X</i>	83.86
	BUMPER SIDE BRACKET RH						
N 10621301	Expanding Nut	6	pcs. <i>/ NEC</i>	1.36 ✓	#1	8.16	8.73
5C6945106B	Reflector	1	pcs. <i>? X SVC</i>	68.93 <i>X SVC</i>	#1	68.93 <i>X</i>	73.76
	REFLECTOR RH						
	LABOUR	1.50	pcs.	840.00	#1 <i>1260</i>	5,040.00	5,392.80
	Spray Painting	2.5	pcs.	800.00	#1 <i>1600</i>	4,000.00	4,280.00
	REVERSE SENSOR	1	pcs. <i>? X SVC</i>	400.00 <i>X SVC</i>	#1	400.00 <i>X</i>	428.00
	TRANSFER BOOT LID MECHANISM	1	pcs. <i>X SVC</i>	840.00	#1	840.00	898.80
	CHINA TAIPING DIRECT SETTLEMENT						
	DOA : 19/11/2019						
	TP VEH : SJR2896E						
	SURVEY BY :						

Quotation valid till 28-11-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	15,273.43	7%	1,122.34	16,033.43	17,155.77
Total	760.00	15,273.43		1,122.34	16,033.43	17,155.77

[Signature]
4/12/19

Sun Pin (LKK)
03/12/2019
SunPin@lkkauto.com
8661 2627

Repair day - 4 days.
P/P
before paint.