



CYCLE & CARRIAGE

TP CLAIM
CHINA TAMPING
Rasul

VEHICLE NO : SMG 3779B

MODEL : KIA/SORENTO 2.2 A D SX

WIP : 62214

Material	:	\$	<u>2,982.00</u>
Labour	:	\$	<u>2,900.00</u>
Sub-Total	:	\$	<u>5,882.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>5,882.00</u>
GST 7%	:	\$	<u>411.74</u>
Grand Total	:	\$	<u>6,293.74</u>
Finalise By/Date	:	<u>Ammy on 10/01/20</u>	



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk. end)
+ 2 days P.H.

* TP VEHICLE NO: SKU87J

* claim GIA search fee \$2.00

* claim loss of use.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ONG KYE FONG, JERRY	Cust No/Name LCV07758/ONG KYE FONG, JERRY
BLK 310C PUNGGOL WALK	Reg No/Reg Date SMG3779B / 18/12/2018
#02-610	Date In/Mileage 20/12/2019/ 24786
SINGAPORE 823310	Chassis/Package KNAPH81BMJ5465514 /KC17P
Contact No Mobile: 81395198	Engine No D4HBJH373815
20/12/2019	Make/Model KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	10/01/2020/ 11:13	TLK	884 / Lauro Songcuan	62214
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW REAR BUMPER, REAR TAILGATE & AFFECTED AREAS				1100.00 ✓
E PNT98000	SPRAY PAINT ON REAR BUMPER & REAR TAILGATE				840.00 ✓
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				160.00 ✓
E PNT88000	TRANSFER REAR TAILGATE ATTACHMENT TO NEW PANEL				120.00 ✓
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST				80.00 ✓
M SUNDRY	APPLY BODY SEALANT ON AFFECTED AREAS				80.00 ✓
M SUNDRY	PERFORM RUST PREVENTION ON AFFECTED PORTIONS				60.00 ✓
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				60.00 ✓
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				180.00 ✓
M SUNDRY	SUNDRIES				20.00 ✓
E PNT88000	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR → <i>supp</i>				120.00 X
M SUNDRY	APPLY SEALANT FOR REAR WINDSCREEN → <i>supp</i>				80.00 X
X	W/STRIP-TAIL GATE OPNG ✓	1.00	128.00	00.00	128.00 ✓
X	LOGO ASSY-KIA SUB ✓	1.00	69.00	00.00	69.00 ✓
X	EMBLEM-SORENTO ✓	1.00	28.00	00.00	28.00 ✓
X	EMBLEM-ECO DYNAMICS ✓	1.00	37.00	00.00	37.00 ✓
X	CAP-RR HOOK ✓	1.00	5.00	00.00	5.00 ✓
X	COVER-RR BUMPER LWR ?	1.00	565.00	00.00	565.00 ?
X	PANEL ASSY-TAIL GATE ✓	1.00	1445.00	00.00	1445.00 ✓
X	COVER-RR BUMPER,UPR → <i>Supp.</i>	1.00	605.00	00.00	605.00 X

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
ONG KYE FONG, JERRY	Cust No/Name	LCV07758/ONG KYE FONG, JERRY
BLK 310C PUNGGOL WALK #02-610 SINGAPORE 823310	Reg No/Reg Date	SMG3779B / 18/12/2018
Contact No Mobile: 81395198 20/12/2019	Date In/Mileage	20/12/2019/ 24786
	Chassis/Package	KNAPH81BMJ5465514 /KC17P
	Engine No	D4HBJH373815
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	10/01/2020/ 11:13	TLK	884 / Lauro Songcuan	62214

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X CLIP → <i>supp</i>	10.00	1.00	00.00	10.00
X SKID PLATE-RR BUMPER ?	1.00	90.00	00.00	90.00
Z TEXT TP CLAIM CHINA TAIPING - SKU87J DOA: 15/11/2019 SURVEY: RASUL 20/12/2019 07 DAYS				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	2,982.00	Nett	5,882.00
Labour	2,660.00	7% GST on	411.74
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	6,293.74
Sundry/Others	240.00		
Total(w/o GST)	5,882.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **CHINA TAIPING**

Supplementary For Registration No.: **SMG 3779 B**

<u>Materials</u>		<u>Cost (\$)</u>
1	Cover- RR Bumper, UPR	605.00
2	Clip (10 pcs)	10.00
		<u>615.00</u>
<u>Labour</u>		
1	Remove & Install Rear Windscreen Glass to Facilitate Repair	120.00
2	Apply Sealant for Rear Windscreen	80.00
		<u>200.00</u>
Materials & Labour		815.00
7% Gst		57.05
Total		<u>872.05</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258