

ASS. REC. BY:

REF: C/TPD19020758/Pg

Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

From (Person): Kamalish Kamte

of SPF

Date/Time: 21/11/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SMA 1288X

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF06000028412/1

Claim No: TP/1P/60507/2019

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 26/9/2019.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ()	Estimate
	SMA 1288X - X	

Signature

C33
Key in

Vehicles to be inspected: SHB8692U - Driver (Involved party)

IO In-Charge: SIO Saleha

h) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBH640L (TP/IP/59353/2019)

On 19 September 2019 (Thursday) at about 5.09 pm, motor cycle was travelling along Buangkok East Drive towards Buangkok Dr, on the right of 3 lanes, when the deceased's motor cycle lost control and collided onto the right kerb at a gradual left bend. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene at 5.26pm by Paramedic Nabila.

Vehicles to be inspected: FBH640L - Rider (Deceased)

IO In-Charge: SIO Saleha

i) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBE735M (TP/IP/59379/2019)

On 20 September 2019, at about 2.14 a.m., the Deceased (Rider of motor cycle) was believed to be travelling on Lane 1 of 4-lanes along SLE towards CTE (10km), when she collided onto a portable directional sign, collided onto a few cones and skidded. Due to the impact, Deceased's motorcycle landed on Lane 2. There were ongoing road works at that time but there was no contact with the stationary LTA TMA truck. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene at 2.34 am by Paramedic Christine.

Vehicles to be inspected: FBE735M - Rider (Deceased)

IO In-Charge: SIO Saleha

j) Case IAFP-IB-20191115 - Mechanical Inspection of Motor Car, SMA1288X (TP/IP/60507/2019)

On 26 September 2019 at about 1.10 a.m., the Deceased (pedestrian) was walking on the left lane of the 3 lanes of Jalan Bukit Merah and suddenly knelt down on the road facing oncoming traffic. The Witness, who was travelling on the left lane of the 3 lanes of Jalan Bukit Merah towards Queensway, saw the Deceased walking onto the left lane and kneel on the road. He immediately came to a stop before the Deceased and switched on the hazard lights and called for the Police. The defendant (motor car) who was travelling on the centre of the 3 lanes of Jalan Bukit Merah towards Queensway, then made left turn into the carpark entrance of Blk 110 Jalan Bukit Merah and ran over the Deceased. Due to the accident, the Deceased was conveyed to the Singapore General Hospital (SGH) however, he succumbed to his injuries and was pronounced dead on the same day at 2.33 a.m.

Vehicles to be inspected: SMA1288X - Driver (Potential defendant)

IO In-Charge: SIO Saleha

k) Case IAFP-IB-20191115 - Mechanical Inspection of Motor Car, SMJ1564B (TP/IP/69597/2019)

l) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, JRR7688 (TP/IP/69597/2019)

On 9 November 2019 (Saturday) at about 4.33 a.m., the Involved Party (SMJ1564B) was driving his motor car on the extreme right lane of the 4 lanes of BKE towards Woodlands checkpoint. Somewhere after KJE, he suddenly felt an impact from the rear right portion and saw the Deceased's motorcycle (without any rider), approaching from the right side of his motor car. The motorcycle continued to veer to the left