

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 20330

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1394/2019/TNS
Date : 22-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Daniels Chandra
Address : 69 Compassvale Bow
#09-35
Singapore 544993
Telephone : (HP) +65 81110163
Type of Claim : Own Damage Claims
Policy No. : 1900058460
Vehicle No : **SMJ 5889 M**
Model Code : Audi Q2 1.0 TFSI S Tronic
Model / Year : 12/3/2019
Engine No : CHZ C27200
Chassis No : WAUZZZGA7KA037802
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Nov-19
Place of Accident : Buangkok Green & Yio Chu Kang Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMJ 5889 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Reccomendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper assy and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,000.00 500	
3	To respray front bumper.	\$ 1,000.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 3,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 5889 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repair</i>	\$ 1,706.00	+
2	FRONT BUMPER FIXING PARTS	\$ 314.00	+
3	FRONT BUMPER GRILLE - CENTER <i>} NEA</i>	\$ 179.00	+
4	FRONT BUMPER SPOILER <i>Repair</i>	\$ 273.00	+
5	FRONT BUMPER AIR GUIDE GRILLE - LH <i>NEA</i>	\$ 154.00	+
6	FRONT BUMPER END CAP - LH <i>?</i>	\$ 31.00	+
7	FRONT BUMPER ADAPTER - LH <i>} NEA</i>	\$ 32.00	+
8	FRONT BUMPER ADAPTER - RH	\$ 38.00	+
9	RADIATOR GRILLE <i>wt</i>	\$ 1,301.00	✓
10	RADIATOR GRILLE STRIKER PLATE <i>NEA</i>	\$ 114.00	+
11	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$ 71.00	?
12	FRONT BUMPER CARRIER <i>NEA</i>	\$ 625.00	+
13	FRONT BUMPER GUIDE SECTION - LH <i>NEA</i>	\$ 32.00	+
14	FRONT BUMPER COVER <i>?</i>	\$ 91.00	+
15	CAUTION SIGN STICKER <i>} NEA</i>	NEC \$ 13.00	+
16	AIRCON STICKER	NEC \$ 7.00	+
17	FRONT WHEEL COVER - LH / RH <i>NEA</i>	2 \$ 588.00	✓
18	LED HEADLIGHT - LH <i>NEA</i>	\$ 4,491.00	+
19	HEADLIGHT MOUNTING - LH <i>NEA</i>	\$ 107.00	+
20	FRONT NO PLATE <i>NEA</i>	S/N \$ 40.00	✓
21	SUNDRIES <i>?</i>	\$ 300.00	?

TOTAL SPARE PARTS : \$ 10,507.00

TOTAL LABOUR CHARGES : \$ 3,552.00

GRAND TOTAL : \$ 14,059.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King .
Surveyed Date : 25/11/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 Days .

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant