

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0075/2019/GW
Date : 23-Nov-19

Vehicle NOT IN workshop . Kindly arrange for survey.

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

Hi Rasul,
Total 6 working days

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr. Phua YongSheng
Address : Blk 34
#01-301
Singapore 310034
Telephone : 88151489
Type of Claim : Third Party Claims
Policy No. : 519099466
Vehicle No : **SJU 122 C**
Model Code : Audi A3 SB 1.0 TFSI
Model / Year : 29-Mar-17
Engine No : CHZ314961
Chassis No : WAUZZZ8V2HA103411
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Allan Wu
Accident Date : 16-Nov-19
Place of Accident : OSCP at 62 B lorong 4 Toa Payoh

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Repair quotation for Accident Vehicle SJU 122 C

S/n	Nature of Jobs		Estimated Charges		Remarks
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 100.00	\$	100.00
2	To dismantle front bumper. To renew lhs front fender. Re-organise crash management components. Reinstall all parts removed.		\$ 700.00	\$	400.00
3	To respray front bumper, lhs front fender and lhs front door.		\$ 600.00	\$	600.00
4	To renew lhs front rim and carry out wheel alignment.	S/N	\$ 120.00	\$	120.00
5	To carry out diagnostic check.	S/N	\$ 150.00	\$	150.00
SUB- TOTAL LABOUR CHARGES		:	<u>\$ 1,670.00</u>	\$	<u>1,370.00</u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SJU 122 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
			Parts -20%
1	FRONT BUMPER GUDIE SECTION-LH	\$ 35.00	
2	FRONT FENDER-LH	\$ 778.00	\$ 622.40
3	FRONT FENDER ATTACHMENT PARTS-LH	\$ 65.00	\$ 52.00
4	FRONT FENDER UPPER BRACKET-LH	\$ 25.00	
5	FRONT FENDER BRACKET-LH	\$ 43.00	
6	FRONT FENDER SEAL-LH	\$ 31.00	
7	FRONT FENDER BRACE-LH	\$ 88.00	
8	FRONT FENDER CLOSING ELEMENT-LH	\$ 54.00	
9	FRONT WHEEL HOUSING LINER-LH	\$ 158.00	
10	FRONT WHEEL HOUSING LINER ATTACHEMENT PART-LH	\$ 52.00	
11	FRONT ALUMINIUM RIM-LH	\$ 651.00	\$ 520.80
12	RUBBER VALVE	\$ 13.00	\$ 10.40
13	LED HEADLIGHT-LH	\$ 5,029.00	
14	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		\$ 7,222.00	\$ 1,205.60
TOTAL LABOUR CHARGES		\$ 1,670.00	\$ 1,370.00
GRAND TOTAL		\$ 8,892.00	\$ 2,575.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
[Tel:6474 3323 for appointment.](tel:64743323)

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager