

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262

Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Estimate :

Date : 23.11.2019  
Vehicle Num : SKU 7627E  
Make/Model : MAZDA 3  
Chassis/Engine no :  
Accident Date : 21.11.2019  
Claim No :  
Reference :  
Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot lid / BT	\$ 1,352.20
1 pc	Rear boot lock / BT	\$ 465.20
1 pc	Rear boot lock catch X	\$ 70.20
2 pc	Rear boot hinges @ 168.00 X GAN	\$ 336.00
1 pc	Rear boot insulator X	\$ 365.50
1 pc	Rear boot rubber X Lwi	\$ 315.20
2 pc	Rear boot reflector lamp @ 543.00 X BR	\$ 1,086.00
1 pc	Rear boot emblem (Mazda 3)	\$ 65.00
1 pc	Rear boot emblem logo / GMBL	\$ 72.00
1 pc	Rear boot emblem (Skyactive)	\$ 65.00
2 pc	Taillamp panel @388 X repair	\$ 776.00
2 pc	Rear tail lamp @ 985.00 X PH X CRA	\$ 1,970.00
1 pc	Rear end panel X	\$ 825.00
1 pc	Rear end panel top garnish X RL	\$ 315.50
1 pc	Rear spare tyre panel X repair	\$ 1,325.00
1 pc	Rear spare tyre panel top cover board X CRA	\$ 465.20
2 pc	Rear bumper side retainer @ 35.00 X RL	\$ 70.00
1 pc	Rear bumper reinforcement X BT RL	\$ 652.20
2 pc	Rear bumper reflector @ 50.00 X PH X NN	\$ 100.00
2 pc	Rear number plate lamp @ 85.00 X NN	\$ 170.00
1 pc	Rear exhaust silencer X repair	\$ 1,800.00
2 pc	Rear exhaust chrome pipe 125.00 X NN	\$ 250.00
2 pc	Rear fender @1250.00 X repair	\$ 2,500.00
2 pc	Rear fender inner garnish @ 598.40 X NN	\$ 1,196.80
2 pc	Rear bumper tow cover@75.20 IPC / M's	\$ 150.40
4 pc	Reversing sensor @ 274.00 / DM	\$ 1,096.00
4 pc	Reversing sensor holder @ 22.00 X / NBC	\$ 88.00
1 pc	Rear bumper / RL	\$ 1,210.00
List Item Total :		\$ 19,152.40
Discount 20 % :		\$ 3,830.48
		\$ 15,321.92

**FASTECH AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate :

Date : 23.11.2019  
 Vehicle Num : SKU 7627E  
 Make/Model : MAZDA 3  
 Chassis/Engine no :  
 Accident Date : 21.11.2019  
 Claim No :  
 Reference :  
 Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
1 set	Rear boot board clip X <i>NN</i>	\$ 50.00
1 set	Rear end panel garnish clip <i>✓</i>	\$ 40.00
1 pc	Rear number plate <i>✓ SUR</i>	\$ 45.00
	Special Nett Total	\$ 135.00

<u>Labour Charge :</u>		
	To check wiring	\$ 150.00 <i>30</i>
	Apply anti rust chemical	\$ 200.00 <i>80</i>
	Remove and refix petrol tank	\$ 120.00 <i>X NN</i>
	Remove and refix rear cushion seat, trimming etc	\$ 150.00 <i>60</i>
	Remove and refix reversing sensor	\$ 150.00 <i>60</i>
	Remove and refix exhaust pipe	\$ 150.00 <i>X NN</i>
	Labour charge for knock dents, cut & welding parts on front & rear damage portion	\$ 1,800.00 <i>750</i>
	To spray painting and etc	\$ 1,600.00 <i>1000</i>
	Labour Charge Total :	\$ 4,320.00

E & O . E Total Amount : \$ 19,776.92

*Guo Qiang - 82880282*  
*Insurance repair.*  
*After repair photos.*

KIM CHWEE AUTO PTE LTD

*21/11/19.*

*6 Days.*