Veron Chen (LKKAuto)

Veron Chen (LKKAuto) From: Sent: Thursday, 7 January 2021 2:13 PM To: Toh Boon Wah **SUR** Cc: **Subject:** FW: Resurvey photo - Honda FBN4809K-DOA: 28/10/2019 **Attachments:** 2624_001.pdf; 2625_001.pdf Dear Mr Toh WITHOUT PREJUDICE Confirmed \$3374.30 @ 3 working days. Best Regards, Veron Chen | Case Handler LKK Auto Consultants Pte Ltd Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) ----Original Message----From: Toh Boon Wah <bwtoh@boonsiewhonda.com.sg> Sent: Monday, 19 October 2020 11:58 AM To: Guo Qiang (LKKAuto) < Guo Qiang@lkkauto.com> Subject: RE: Resurvey photo - Honda FBN4809K Hi Guo Qiang, Finally the supplementary has arrived and the parts had restored. Attachment 1 - Supplementary item. Attachment 2 - Finalisation of the full repair cost. Kindly revert your acceptance. Thank you. Regards,

Toh BW Service Department

Boon Siew Singapore Pte Ltd 370 Ubi Road 3 S'pore 408651

t: (+65) 6513 9333 f: (+65) 6844 1862 m: (+65) 9112 1132 ----Original Message-----From: Toh Boon Wah

Sent: Friday, 15 May 2020 5:08 PM

To: LKK, GUO QIANG (guoqiang@lkkauto.com) <guoqiang@lkkauto.com>

Subject: Resurvey photo - Honda FBN4809K

Hi Guo Qiang,

Attached photo as per your request.

Please note we will be putting up Supplementary for 3 more items. (Parts diagram attached) we will require to indent the parts form oversea and due to the covid-19 Some delay will expected, we shall finalise will you once the full repair is completed.

Regards, Toh BW Boon Siew S'pore Pte Ltd 370 Ubi Road 3 S'pore 408651

DID: 6513 9333 HP: 9112 1132