



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19020923/Qqf3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 30-10-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8317S	Veh. Inspected	SMJ 872T
Policy No.		Coverage (\$)	0.00
Claim No.	D19007467MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	26/11/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FREED HYBRID 1.5G	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GB71087050	Colour	GREY
Odometer	70479	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	DAYTON	6 mm
L/H Front Tyre	195/60 R15	DAYTON	6 mm
R/H Rear Tyre	195/60 R15	DAYTON	6 mm
L/H Rear Tyre	195/60 R15	DAYTON	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/11/2019	Inspection Date	25/03/2020
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------