211

27/11/19 @ 14:36 pm mandate approved by Lim Kok Change via minum.

27/11/19 @ 15:04 pm informed C/A to Gafa Via enai).

Adrien Confirmed PG \$12,166.48 @ 5 days With Boss. (\$6,415.52 Red - 404 36%)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd. To:

AIG Building

78 Shenton Way #08-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Date:

27 Nov 2019

### Preliminary Advice

Vehicle No

: SMF2645R

Accident Date

: 21/11/2019

Make

: AUDI A4

Policy No.

: 1800130211

Assignment Date

: 26/11/2019

Excess

: \$\$0.00

Date of Inspection

: 26/11/2019

Est. Duration of Repair

: 5 days

Inspection At

: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 18,882.00 |
|-----------------------------|------|-----------|
| Revised Amount              | :S\$ | 13,787.00 |
| Check Items (Estimated)     | :S\$ | 812.00    |
| Total                       | :S\$ | 14,599.00 |

Lump Sum Repair

:S\$

### **Total Loss Consideration**

| New for Old Value | :5\$ |
|-------------------|------|

135,000.00 :S\$ Pre-Accident Value 57,044.00 :S\$ COE / PARF Rebate :S\$

Salvage Value

:S\$ 77,956.00 Margin for Repair

### Remarks

| ( | X | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage<br>Kindly let us have your authorisation. |
|---|---|---|---|
|   |   |   | Tallery lot do navo you   |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto)

Sent:

Monday, 24 February 2020 10:47 am

To:

jiayee.yap@premiumauto.com.sg

Cc:

'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'; Adrian Ling (LKKAuto); SUR; Admin

A; CS A Team

Subject:

RE: FINAL REVISION - SMF2645R - OD AIG - SURVEYED 26 NOV 19

Dear Jia Yee,

Confirmed final fig \$ 12,166.48 @ 5 days of repairs before excess \$ 550/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiayee.yap@premiumauto.com.sg < jiayee.yap@premiumauto.com.sg >

Sent: Friday, 14 February 2020 2:09 pm

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A

Team <cs-a@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing'

<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SMF2645R - OD AIG - SURVEYED 26 NOV 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$12,166.48 @ 5 days of repair.

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto)

Sent:

Wednesday, 27 November 2019 3:04 pm

To:

Claims

Cc:

SUR

Subject:

RE: OD CLAIM FOR SMF 2645 R ON 22/11/2019

Dear Syafiq,

As instructed by our client, please proceed to repair the insured vehicle SMF 2645R (Excess \$ 550/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Friday, 22 November 2019 6:15 pm

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIM FOR SMF 2645 R ON 22/11/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Kindly arrang survey on 26/11/2019, 10am.

Best Regards,

Svafig

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W) 55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



#### **Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

## View Received Message

This mail is associated with:

### \*SMF2645R (7836898076SG)

OD Nov 21 2019 9:00PM [CHOOH CHUEN SIN (SHI JUNXING)] Premium Automobiles Pte Ltd

| Reply | Reply All Mark as Unread Print Message Delete Message Forward               |  |
|-------|---|--|
| From  | AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 27/11/2019 14:36 PM. |  |

Alert - Adj Mandate Approved (S\$14599.00) - SMF2645R - Claim Handler: Rparthiban, Theerthan Subject

Approved:14599.00:To resurvey and take photos for checked items if require and upload in Merimen.

#### **DOCUMENTS SUMMARY**

There are no documents.

### > Back to OneMotoring

COE Expiry Date:

COE Rebate Amount:

COE Category: COE Period(Years):

QP Paid:

| uire PARF/COE Rebate for Registered \ /ehicle Owner Particulars  | Singapore NRIC                   |
|--|----------------------------------|
| Owner ID Type:   |                                  |
| Owner ID:  | 604D                             |
| /ehicle Details<br>/ehicle No.:  | SMF2645R                         |
| /ehicle to be Exported:  | No                               |
| ntended Deregistration Date:   | 27 Nov 2019                      |
| A MANAGEMENT OF THE PROPERTY O | AUDI                             |
| /ehicle Make:  | A4 SEDAN 2.0 TFSI 5 TRONIC (NAV) |
| /ehicle Model:   | Silver                           |
| Primary Colour:  | 2018                             |
| Manufacturing Year:<br>Engine No.:   | CVK068771                        |
| Chassis No.:   | WAUZZZF41JA231770                |
| Maximum Power Output:  | 140.0 kW (187 bhp)               |
| Open Market Value:   | \$33,436.00                      |
| Original Registration Date:  | 31 Oct 2018                      |
| First Registration Date:   | 31 Oct 2018                      |
| Transfer Count:  | 0                                |
| Actual ARF Paid:   | \$38,811.00                      |
| Intended PARF Rebate Details   | 30° 100                          |
| PARF Eligibility:  | Yes                              |
| PARF Eligibility Expiry Date:  | 30 Oct 2028                      |
| PARF Rebate Amount:<br>Intended COE Rebate Details   | \$29,108.00                      |
| Illeringed - Aprilant -  | 30 Oct 2028                      |

Total Rebate Amount: The information contained herein is correct as at 27 Nov 2019 30 Oct 2028

\$32,900.00

\$27,936.00

\$57,044.00

E - Open - all except motorcycle



# CERTIFICATE OF INSURANCE

### AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: CHOOH CHUEN SIN (SHI JUNXING)

Period of Insurance

: 31 Oct 2019 To 30 Oct 2020

Engine No.

: CVK 068771

Chassis No.

: WAUZZZF41JA231770

Vehicle No.

: SMF2645R

Policy No.

: 1800130211-01

Endorsement No.

**Issued Date** 

: 11 Oct 2019

#### ABOUT THE COVER

Make/Model

: AUDI A4 Sedan 2.0 TFSI S tronic

Engine Capacity/Tonnage: 1,984.00 CC

Sum Insured : Market Value

First Year of Registration : 2018

Insuring with COE/PARF : Yes

Driver Restriction

: NA

Off Peak Car : No

Person or Classes of Persons Entitled to Drive\*:

a) The Policyholder

y other person who is driving on the Policyholder's order or with his/her permission

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use\*

This Policy does not cover use for him or reward, driving fuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### **EXCESS**

Section 1

Fire - \$0 Own Damage - \$1100 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

CHOOH CHUEN SIN (SHI JUNXING) - \$1100 (Own Damage)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRES (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other. Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### **IMPORTANT NOTES**

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rutes, 1959 (Malaysia).

0504125200

PREMILIM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Morile

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #07-16 AIG Building S079120 | T:+65 6419 3000 | www.aig.sg

### IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

### What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

### What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

#### If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s)
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

## If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable,
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the acci
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident

### LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

### Steps to activate Loss of Use Car Replacement Benefit and Important Information

- 1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
- Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
- At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
- 4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
- Rental cars are strictly for use in Singapore only.
- Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day
- Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

"The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

### IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.



AIG Asia Pacific Insurance Pte. Ltd AIG Building 78 Shenton Way #07-16

## MOTOR ACCIDENT INTERVIEW FORM

| NAME  | 1                         | CHOST CHINEN 2110   |
|---|---------------------------|---|
| VEHICLE NUMBER  | 18                        | SMF 2645 R  |
| DATE/ TIME OF ACCIDENT  |                           | 21/11/2019 Q.30 PM  |
| PLACE OF ACCIDENT   |                           | cretord Road rear Lucky Place   |
| THIRD PARTY VEHICLE (IF ANY)  | :                         |   |
| WHERE DID YOU START YOUR JOURNE                                     |                           | The WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?   |
| DID YOU DRINK ANY ALCOHOLIC DRIN<br>POLICE CONDUCT ANY BREATHE-ANAL | NKS BEFORE<br>YSER TEST O | YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC<br>N YOU? IF YES, WHAT WAS THE RESULTS? |
|   |                           | IVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?  |
| Front right to 1  | ic Ha                     | role root type.   |
|   |                           |   |
| WERE YOU OR YOUR PASSENGER/S IN<br>FOR INVESTIGATION?               | DURED? IF I               | NJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE  |
|   |                           |   |
| NAME: CHOOP CHUSE   | -<br>-<br>-<br>-<br>-     |   |

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

# UNDERTAKING

| 1, CHUOH CH   | NRIC No. 57240604 Phereby  |
|---|--|
| confirm that the Singapore  | Accident Statement lodged by me on 22/11/19  |
| at 16-10 pm hours pe  | ertaining to the accident involving motor car Reg. No:   |
| knowledge, information and  | belief.  |
|   |  |
| a breach of policy terms an   | d conditions.  |
| In the event that an unrela   | ted/unreported third party property or injury claim arises or  |
| there is evidence emerges   | s that there is a breach of policy terms and conditions, I   |
| irrevocably undertake to a  | absolve my insurer from all liability under the contract of  |
| Annual Consideration  | to re-pay any sums paid by my insurers pursuant to the   |
| insurance and i undertake   | 막지가 살아 주어가면 되어 보다면 그리겠어요? 그렇게 있지 그래요 그렇게 그렇게 그렇게 그렇게 그렇게 그렇게 그렇게 그렇게 되었다면 그렇게 |
|   |  |
|   |  |
|   |  |
|   |  |
| contract of insurance upon  |  |
| contract of insurance upon Signature  | : CHOSH CHUEN SIN  |
| confirm that the Singapore Accident Statement lodged by me on                   |  |
| contract of insurance upon  Signature  Name of Insured / Driver                 | : CHOSH CHUEN SIN  |
| Contract of insurance upon  Signature  Name of Insured / Driver  Nric No.  Date | : CHOSH CHUEN SIN  |
| Contract of insurance upon  Signature  Name of Insured / Driver  Nric No.       | : CHOSH CHUEN SIN  |
| Contract of insurance upon  Signature  Name of Insured / Driver  Nric No.  Date | : CHOSH CHUEN SIN  |
| Signature Name of Insured / Driver Nric No. Date Signature                      | : CHOSH CHUEN SIN  |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 20360

### Telefax

**Estimate** 

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323

Fax No Reference 6841 1183 PA/OD/1396/2019/NS

Date

25-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr Chooh Chuen Sin (Shi Junxing)

34B Punggol Field

Address

#10-34

Singapore 828809

Telephone

HP +65 98151011

Type of Claim

Own Damage Claims

Policy No.

1800130211-01

Vehicle No

**SMF 2645 R** 

Model Code

Audi A4 SEDAN 2.0 TFSI 8W

31/10/2018

Model / Year

**Engine No** 

CVK 068771

Chassis No

WAUZZZF41JA231770

Mileage

:

Date In

Estimated By

Johnny Boo / Allan Wu

**Accident Date** 

21-Nov-19

Place of Accident

Orcahrd Road

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Estimated Labour Charges for Accident Vehicle. SMF 2645 R

| S/n | Nature of Jobs   |     | Estimated<br>Charges | Surveyor's<br>Recommendations |
|-----|--|-----|----------------------|-------------------------------|
| 1   | To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. | S/N | \$<br>480.00         |                               |
| 2   | To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.  | S/N | \$<br>300.00 V       |                               |
| 3   | To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.     |     | \$<br>-              | 1253                          |
| 4   | To respray front bumper, rhs front fender and RHF door   |     | \$<br>2,500.00       | 1650.                         |
| 5   | To renew rhs front rim. Carry out wheel alignment.   | S/N | \$<br>280.00         | +                             |
| 6   | To carry out diagnostic check.   | S/N | \$<br>192.00         |                               |
|     | TOTAL LABOUR CHARGES   | :   | \$<br>6,202.00       |                               |

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Material List for Accident Vehicle Regn No. SMF 2645 R

|    |  | Damaged Parts & Price S/Nett Ren |                       |  |
|----|--|----------------------------------|-----------------------|--|
| /N | Parts Description                            |                                  | S/Nett Remarks        |  |
| 1  | FRONT BUMPER Deformed                        | \$                               | 1,999.00 - 1599.20    |  |
| 2  | FRONT BUMPER FIXING PARTS                    | \$                               | 258.00                |  |
| 3  | FRONT BUMPER SECURING STRIP 1                | \$                               | 64.00                 |  |
| 4  | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE  | \$                               | 191.00                |  |
| 5  | FRONT BUMPER AIR GUIDE - RH PAPE NEW         | \$                               | 56.00 X               |  |
| 6  | FRONT BUMPER AIR GUIDE GRILLE - RH           | \$                               | 123.00                |  |
| 7  | FRONT BUMPER GUIDE SECTION - RH Dang d       | \$                               | 34.00 / 24.12         |  |
| 8  | FRONT PARKING AID SENSOR - INNER / OUTER HEM | \$                               | 231.00                |  |
| 9  | FRONT FENDER - RH Dewled                     | \$                               | 700.00 559.60         |  |
| 10 | FRONT FENDER ATTACHMENT PARTS HE NEC         | \$                               | 183.00 ? 🔀            |  |
| 11 | FRONT FENDER CLOSING ELEMENT - RH 364        | \$                               | 45.00 ? 2 3 6         |  |
| 12 | FRONT FENDER BRACKET - RH NEVEL              | \$                               | 32.00 ? X             |  |
| 13 | DEFORMATION ELEMENT BRACKET - RH 74 NCC      | \$                               | 45.00 ? 🗸             |  |
| 14 | FRONT FENDER BRACE - RH Bent.                | \$                               | 107.00 ? 185-60       |  |
| 15 | FRONT WHEEL HOUSING LINER - RH tom           | \$                               | 220.00 1 7 1 75.6     |  |
| 16 | WHEEL HOUSING LINER ATTACHMENT PARTS NEW     | \$                               | 82.00 <sup>&lt;</sup> |  |
| 17 | WHEEL SPOILER Craled                         | \$                               | 66.00 X V 52.32       |  |
| 18 | WHEEL SPOILER TRIM - RH New New              | \$                               | 33.00 -               |  |
| 19 | STONE CHIP GUARD - RH 2                      | \$                               | 46.00 3664            |  |
| 20 | FENDER LEDGE TOP COVER - RH                  | \$                               | 21.00 / 16.16         |  |
| 21 | FENDER LEDGE COVER - RH                      | \$                               | 28.00 22-24           |  |
| 22 | LED HEADLIGHT - RH Cut                       | \$                               | 7,087.00 - 5669.6     |  |
| 23 | FRONT ALUMINIUM RIM - RH Not New             | \$                               | 629.00                |  |
| 24 |  | \$                               | 400.00 1 14.46        |  |
|    | TOTAL SPARE PARTS                            | \$                               | 12,680.00<br>6,202.00 |  |
|    | TOTAL LABOUR CHARGES GRAND TOTAL             | \$                               | 18,882.00             |  |

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

Name

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability

Remarks

: Adrian Ling : 26/11/19.

LICK Auto Consultants hence notify the Receiver of the following: Some I very perform after spray painting

To disputy damaged part(s) during resurvey

Pans prices are a object to confirmation

\* The principles in the violence a "Without Prejudice" basis

+ No megal monolication(s) is allowed

· Supple - ntary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

: Not Anthorsed, 05 Days

Tel:6768 9828 for appointment.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

|     | Parts Description gloy wisher 30   | 111 -            | Damaged Parts & Prices S/Nett Remarks |
|-----|--|------------------|---------------------------------------|
| /N  | Parts Description  |                  | Jillet Remarks                        |
| 1   | FRONT BUMPER Deformed  | \$               | 1,999.00 -                            |
| 2   | FRONT BUMPER FIXING PARTS  | \$               | 258.00                                |
| 3   | FRONT BUMPER SECURING STRIP  | 2 \$             | 64.00                                 |
|     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE  | NH S             | 191.00 F                              |
| 4   | FRONT BUMPER AIR GUIDE - RH PAR NEW  | S                | 56.00 X                               |
| 5   | FRONT BUMPER AIR GUIDE GRILLE - RH   | S                | 123.00 ×                              |
| 6   | FRONT BUMPER GUIDE SECTION - RH Dange  | \$               | 34.00                                 |
| J   | FRONT PARKING AID SENSOR - INNER / OUTER 74  | m s              | 231.00 /                              |
| 8   |  | \$               | 700.00                                |
| 19/ | FRONT FENDER - RH DEWEC ?  | \$               | 183.00 ?                              |
| 10  | FRONT FENDER CLOSING ELEMENT - RH 7 H  | s                | 45.00 ?                               |
| 11) | The state of the s | 5                | 32.00 ?                               |
| 12  | FRONT FENDER BRACKET - RH  | \$               | 45.00 ?                               |
| 13  | DEFORMATON ELEMENT BRACKET - RH  | s                | 107.00 ?                              |
| 14/ | THOM:  |                  | 220.00*                               |
| 15) | FRONT WHEEL HOUSING LINER - RH de 2 H  | \$               | 82.00 <sup>*</sup>                    |
| 16  | WHEEL HOUSING LINER ATTACHMENT PARTS   | \$               | 66.00 X                               |
| 17) | WHEEL SPOILER de The Me  | \$               |                                       |
| 18  | WHEEL SPOILER TRIM - RH  | \$               | 33.00 £                               |
| 118 | STONE CHIP GUARD - RH  | ۶<br>۱۸۰۰        | 46.00                                 |
| 20  | FENDER LEDGE TOP COVER - RH HAN ME   | 5                | 21.00                                 |
| 27  | FENDER LEDGE COVER - RH  | 12. 5            | 28.00                                 |
| 22  | LED HEADLIGHT - RH Cut   | \$               | 7,087.00                              |
| 23  | FRONT ALUMINIUM RIM - RH NEW NEW   | \$               | 629.00                                |
| 24  | SUNDRIES ?   | \$               | 400.00 🧳                              |
|     | TOTAL SPARE PARTS TOTAL LABOUR CHARGES GRAND TOTAL   | : \$<br>\$<br>\$ | 12,680.00<br>6,202.00<br>18,882.00    |
|     | All charges are not inclusive of GST.  Legend: Remarks (OK) = Approved, Remarks (X  Spare parts are Special Nett.  | ) = Not app      | roved                                 |

# **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 20360

### Telefax

Estimate

**Accident Repairs** Ubi Road 1

Workshop Contact No Fax No

6366 2323 6841 1183

Reference

PA/OD/1396/2019/NS

Date

25-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Hi-Adrian,

5 days - ok - Jy - 14 Feb 2020

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr Chooh Chuen Sin (Shi Junxing)

34B Punggol Field

Address

#10-34

Singapore 828809

Telephone Type of Claim HP +65 98151011 Own Damage Claims 1800130211-01

Policy No. Vehicle No

SMF 2645 R

Model Code

Audi A4 SEDAN 2.0 TFSI 8W

Model / Year

31/10/2018

**Engine No** 

CVK 068771

Chassis No

WAUZZZF41JA231770

Mileage

Date In

Estimated By

Johnny Boo / Allan Wu

**Accident Date** Place of Accident 21-Nov-19 Orcahrd Road

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Estimated Labour Charges for Accident Vehicle. SMF 2645 R

| S/n | Nature of Jobs   |     | Estimated<br>Charges | Surveyor's ecommendations |    |          |
|-----|--|-----|----------------------|---------------------------|----|----------|
| 1   | To remove and transfer front wire narness<br>for headlights, horns, fog lamps, outside<br>temperature sensor, headlight washer assy<br>and front parking aid | S/N | \$                   | 480.00                    | \$ | 480.00   |
| 2   | To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assv.  | S/N | \$                   | 300.00                    | \$ | 300.00   |
| 3   | ro dismantie and renew front bumper, rns<br>front fender and headlight. Re-organise<br>front crash management components.<br>Reinstall all parts removed     |     | S                    | 2,450.00                  | \$ | 1,250.00 |
| 4   | To respray front bumper, rhs front fender and RHF door   |     | \$                   | 2,500.00                  | \$ | 1,650.00 |
| 5   | To renew rns front rim. Carry out wheel alignment.   | S/N | \$                   | 280.00                    |    |          |
| 6   | To carry out diagnostic check.   | S/N | \$                   | 192.00                    | \$ | 192.00   |
|     | TOTAL LABOUR CHARGES   | :   | \$                   | 6,202.00                  | \$ | 3,872.00 |

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

# Material List for Accident Vehicle Regn No. SMF 2645 R

| S S S S S S S S S S S S S S S S S S S |   |           | Damaged Part          |    |                       |
|---------------------------------------|---|-----------|-----------------------|----|-----------------------|
| S/N                                   | Parts Description                           |           | S/Nett                |    | Remarks               |
| 1                                     | FRONT BUMPER                                | S         | 1,999.00              | \$ | 1,599.20              |
| 2                                     | FRONT BUMPER FIXING PARTS                   | s         | 258.00                |    |                       |
| 3                                     | FRONT BUMPER SECURING STRIP                 | 2 \$      | 64.00                 |    |                       |
| 4                                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | s         | 191.00                |    |                       |
| 5                                     | FRONT BUMPER AIR GUIDE - RH                 | \$        | 56.00                 |    |                       |
| 6                                     | FRONT BUMPER AIR GUIDE GRILLE - RH          | \$        | 123.00                |    |                       |
| 7                                     | FRONT BUMPER GUIDE SECTION - RH             | s         | 34.00                 | \$ | 27.12                 |
| 8                                     | FRONT PARKING AID SENSOR - INNER / OUTER    | s         | 231.00                |    |                       |
| 9                                     | FRONT FENDER - RH                           | \$        | 700.00                | \$ | 559.60                |
| 10                                    | FRONT FENDER ATTACHMENT PARTS               | \$        | 183.00                |    |                       |
| 11                                    | FRONT FENDER CLOSING ELEMENT - RH           | \$        | 45.00                 | \$ | 36.00                 |
| 12                                    | FRONT FENDER BRACKET - RH                   | \$        | 32.00                 |    |                       |
| 13                                    | DEFORMATON ELEMENT BRACKET - RH             | \$        | 45.00                 |    |                       |
| 14                                    | FRONT FENDER BRACE - RH                     | s         | 107.00                | \$ | 85.60                 |
| 15                                    | FRONT WHEEL HOUSING LINER - RH              | s         | 220.00                | \$ | 175.60                |
| 16                                    | WHEEL HOUSING LINER ATTACHMENT PARTS        | s         | 82.00                 |    |                       |
| 17                                    | WHEEL SPOILER                               | s         | 66.00                 | \$ | 52.32                 |
| 18                                    | WHEEL SPOILER TRIM - RH                     | \$        | 33.00                 |    |                       |
| 19                                    | STONE CHIP GUARD - RH                       | s         | 46.00                 | \$ | 36.64                 |
| 20                                    | FENDER LEDGE TOP COVER - RH                 | \$        | 21.00                 | \$ | 16.16                 |
| 21                                    | FENDER LEDGE COVER - RH                     | s         | 28.00                 | \$ | 22.24                 |
| 22                                    | LED HEADLIGHT - RH                          | \$        | 7,087.00              | 5  | 5,669.60              |
|                                       | FRONT ALUMINIUM RIM - RH                    | 5         | 629.00                |    |                       |
| 23                                    |   | \$        | 400.00                | \$ | 14.40                 |
| 24                                    | SUNDRIES                                    | (2.30)    |                       | _  |                       |
|                                       | TOTAL SPARE PARTS                           | : \$      | 12,680.00             | \$ | 8,294.48              |
|                                       | TOTAL LABOUR CHARGES GRAND TOTAL            | <u>\$</u> | 6,202.00<br>18,882.00 | \$ | 3,872.00<br>12,166.48 |

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles Pte Ltd

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SMF 2645 R

Norah Khai From

6768 9911 Telephone +65 -

+65 -

6841 1183 Telefax

Nora.khai@premiumauto.com.sg Mobile +65 -Body & Paint Dept Our Dept

PA/OD/1396/2019/NH Email

11-Mar-2020 Date

Showroom

1 Total Pages

Dear Sir,

RE: INSURANCE CLAIM FOR SMF 2645 R - Audi A4 SEDAN 2.0 TFSI

With reference to the above-mentioned vehicle, no. SMF 2645 R, claimant, Mr. Chooh Chuen Sin, please find the related document per attached.

9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Premium Automobiles Pte Ltd.

- A copy of the Original invoice no. 85014976 S\$ 12,429.63
- A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG - SMF 2645 R

# Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6388 2223 Main Telefax 6475 1023

**Ubi Service Centre** 55 Ubi Road Singapore 408699 Main Telephone 6388 2323 Main Telefax 6841 1163 **Customer Service** 6366 2323 Service Appointment 9828 1233 24-hour Breakdown Service customer care@premiumauto.com.sg Email

### INS TAX INVOICE

Page 1 12:08

Company Reg. No. 199902271W GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY #07-16

SINGAPORE 079120 079120

Invoice No: 85014976

Account: A0006

0) AIG ASIA PACIFIC INSURANCE PTE LTD

Date : 10/03/2020

Order: SMF2645R

MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY

#07-16

SINGAPORE 079120

Term : 30

Regn No: SMF2645R (V

39472)

Regn Date: 31/10/2018

Mileage: 16715

WIP No.: 20360

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF41JA231770

Engine: CVK 068771

Dept: U

You have been assisted by :- UB-Tony Foong

(33)

|                                       |  | Details  | Qty  | Unit Price | Amount   |
|---------------------------------------|--|--|--|------------|--|
| 3                                     | TUG  | M: 8888  | -550.00  | 1.00       | -550.00  |
| 2                                     | EXC  | Insurance Excess/Liability   | 480.00   | 1.00       | 480.00   |
| S                                     | BODYWORK   | M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.  | 400.00   |            |  |
| 5.                                    | BODYWORK   | TO DISMANTLE RHS FRONT DOOR PANEL TRIM. O REMOVE AND REINSTALL RHS WING MIRROR   | 300.00   | 1.00       | 300.00   |
|                                       | BODYWORK   | ASSY  M:  TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS   | 1250.00  | 1.00       | 1,250.00   |
| 3                                     | BODYWORK   | REMOVED  M: TO RESPRAY FRONT BUMPER, RHS FRONT FENDER  | 1650.00  | 1.00       | 1,650.00   |
| S                                     | BODYWORK   | AND RHS FRONT DOOR M:  | 192.00   | 1.00       | 192.00   |
| X X X X X X X X X X X X X X X X X X X | A8W0807065D GRU<br>A8W0807284<br>A8W0821106A<br>A8W0821092<br>AN 0161857<br>A8W0821136C<br>A8W0821172A<br>A8W0853888L<br>A8W0853824B 9B9<br>A8W0823746<br>A8W0820582C<br>A8W0941774A | TO CARRY OUT DIAGNOSTIC CHECK  (SK)COVER GUIDE FENDER PLATE AP POP-RIVET SUPPORT AP WHEEL HOUS AP SPOILER AP STONEGUARD COVER COVER (SK)HEADLIGHT  Less 020% | 1.00<br>1.00<br>1.00<br>1.00<br>6.00<br>1.00<br>1.00<br>1.00 |            | 1,599.20<br>27.12<br>559.60<br>36.00<br>14.40<br>85.60<br>175.60<br>52.32<br>36.64<br>16.16<br>22.24<br>5,669.60 |
|                                       | Parts 8,294.48   |  |  | Sub-Total  | 11,616.4   |
|                                       | Labour 0.00<br>Sublet 3,872.00   | EN 201/201/EN  |  | 7% GST     | 813.1  |

0.00 Menus Lubricant

12,429.63 **Grand Total** 

Received by

For & on behalf of Premium Automobiles Pte Ltd

# **Premium Automobiles**

:

### Telefax

to AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Motor Claims Dept Yr Ref: SMK 26 45 R Norah Khai 6768 9828 6841 1183

from

Telephone +65-+65-Telefax +65-Mobile

Body Repair

Our department Your Claim Ref

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111

Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

PA/OD/1396/2019/KS

Our Ref Date

Showroom

9 Leng Kee Road

Singapore 159090

55 Ubi Road 1

Singapore 408699

20 Dec 2019

total pages

CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER RE:

Make & Model

Audi A4 SEDAN 2.0 TFSI

Vehicle Chassis No.

WAUZZZF41JA231770

Vehicle Regn No.

SMF 2645 R

Vehicle Mileage

16715 KM

Vehicle Owner

Mr. Chooh Chuen Sin

Certificate No

1800130211-01

Own Damage Excess :

\$ 588.50 (Inclusive GST)

Accident Date

21/11/2019

Place

Orchard Road

Repair Cost

12429.63

WIP No.

20360

Repairer's Name

Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature

Time Date

21/2/10

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

|   | FOLDER TRA              |  | Take Australia                           | Adi Rot                       | Adj Subr                    | nitted In                  | s Auth'ed  | Status   |                   |
|---|-------------------------|--|--|-------------------------------|-----------------------------|----------------------------|--|--|-------------------|
| Case<br>Main                                | Notified<br>25 Nov 2019 | Est Submitted  | 26 Nov 2019<br>17:14<br>Edit Adj Rpt     | S\$12,166.48<br>Edit Estimate | 5\$12,16                    | 6.48                       |  | Pending for Survey R Cancel Case               |                   |
|   | Main                    | Re   | eference                                 | CI                            | aim Details                 |                            | Documents  | SI   | now All           |
| CI ATM S                                    | JBFOLDER DI             | TAILS  | SCHOOL STATE                             |                               | Section 1                   |                            | y insurer]   |  |                   |
| Insured:                                    | сноон с                 | HUEN SIN (SHI  | JUNXING), ID                             | : S7240604D,                  | Tel: +65981                 | 51011, Ema                 | ail: NOEMAIL   |  |                   |
| Vehicle Re                                  |                         | account of   |  |                               | Date of Loss:               | [12 Months                 | The state of the s | om LTA Reg Date (N                             | tan Yr)]          |
| Claim Typ                                   | e: <b>OD</b> / 78       | 36898076SG   |  |                               | Policy/Cover<br>Note No.:   | 1800130211 (Comprehensive) |  |  |                   |
|   |                         |  |  |                               | Excess:                     | S\$550.00                  |  |  |                   |
| Repairer:                                   | Premium                 | Automobiles Pt   | e Ltd (UBI) 55                           | Ubi Road 1, 40                | 8699 Ubi - Tel              | : 67689828/S               | 982//9911<br>arthiban Theet  | than]  |                   |
| Handling                                    | AIG Asia                | Pacific Insuran  | ce Pte. Ltd. (SG                         | i) - Tel: 65-64               | 9-3000 [Ha                  | naled by KP                | arthiban, Theer  |  |                   |
|   | Theerthan               | n.Parthiban@aig.c  | om                                       |                               |                             |                            | (C) [Final R   | nt due 05/12/20                                | 191               |
|   | Theerthan               | .Parthiban@aig.c   | om<br>e Ltd (HQ) - Tel                   | l: 6256-3561                  | . [Handled by               | ADRIAN LIN                 | (G) [Final R   | pt due 05/12/2                                 | 19]               |
| Insurer:                                    | Theerthan               | n.Parthiban@aig.co<br>Consultants Pt<br>HUEN SIN (SHI JU | om<br>e Ltd (HQ) - Tel                   | l: 6256-3561                  | . [Handled by               | ADRIAN LIN                 | (G) [Final R<br>51011 Email: NC  | pt due 05/12/20                                |                   |
| Insurer:<br>Adjuster:<br>Driver/Cu<br>dian: | Theerthan               | n.Parthiban@alg.co<br>Consultants Pt<br>HUEN SIN (SHI JU | om<br>e Ltd (HQ) - Te<br>UNXING) (47 / M | l: 6256-3561<br>ale) , NRIC:  | . [Handled by<br>57240604D, | ADRIAN LIN                 | (G) [Final R<br>51011 Email: NO  | Ept due 05/12/20<br>DEMAIL<br>View All Compose | O19]<br>Case Mail |

### **Claim Documents**

# \*SMF2645R (7836898076SG) OD Nov 21 2019 9:00PM [CHOOH CHUEN SIN (SHI JUNXING)] Premium Automobiles Pte Ltd

|         | The second second              | ad Photos   Compose New Letter   Upload Video   Upload Audio | 1 per |           | <b>Ø</b>   |
|---------|--------------------------------|--|-------|-----------|------------|
| /ide    |                                | Premium Automobiles Pte Ltd (UBI)                            |       | Thumbnail | Print      |
| lo      | Finalized On<br>22/11/19 16:47 | Video - Accident [Linked Accident Report Documents]          | 0     | Load MP4  |            |
|         | essment Reports                |  | 1 per |           | •          |
|         |                                | LKK Auto Consultants Pte Ltd (HQ)                            |       | Thumbnail | Print      |
| Vo<br>1 | Finalized On<br>27/11/19 09:02 | Adjuster Immediate Advice                                    | 0     | Load HTM  |            |
|         | 27/11/15 05:02                 |  | 3 per | page v    | •          |
| Pho     | tos/Images                     |  | 3 per | Thumbnail | -          |
| No      | Relabel/Reorder                | LKK Auto Consultants Pte Ltd (HQ)                            | 0     | Load JPG  | •          |
| 1       | 27/11/19 09:06                 | General View   | 0     | Load JPG  | •          |
| 2       | 27/11/19 09:06                 | General View   | 0     | Load JPG  |            |
| 3       | 27/11/19 09:06                 | General View   | 0     | Load JPG  | •          |
| 4       | 27/11/19 09:06                 | General View   |       | Load JPG  | (e)        |
| 5       | 27/11/19 09:06                 | General View   | 0     |           | -          |
| 6       | 27/11/19 09:06                 | General View   | 0     | Load JPG  | (e)        |
| 7       | 27/11/19 09:06                 | General View   | 0     | Load JPG  | <b>(2)</b> |
| 8       | 27/11/19 09:06                 | General View   | 0     | Load JPG  | (4)        |
| 9       | 27/11/19 09:06                 | General View   | 0     | Load JPG  | •          |
| 10      | 27/11/19 09:06                 | General View   | 0     | Load JPG  | €          |
| 11      | 27/11/19 09:06                 | General View   | 0     | Load JPG  | •          |
| 12      | 27/11/19 09:06                 | General View   | 0     | Load JPG  | 2          |
|         |                                | General View   | 0     | Load JPG  |            |
| 13      | 27/11/19 09:06                 | General View   | 0     | Load JPG  | •          |
| 14      | 27/11/19 09:06                 | General View   | 0     | Load JPG  | 2          |
| 15      | 27/11/19 09:06                 | General View   | 0     | Load JPG  | •          |
| 16      | 27/11/19 09:06                 |  | 0     | Load JPG  | •          |
| 17      | 27/11/19 09:06                 | General View   | 0     | Load JPG  | 2          |
| 18      | 27/11/19 09:06                 | General View   | 0     |           |            |
| 19      | 27/11/19 09:06                 | General View   | 0     |           |            |
| 20      | 21/02/20 15:32                 | Reinspection Photo   | 0     |           |            |
| 21      | 21/02/20 15:32                 | Reinspection Photo   | 0     |           | -          |
| 22      | 21/02/20 15:32                 | Reinspection Photo   | ō     |           | -          |
| 23      | 21/02/20 15:32                 | Reinspection Photo   | 0     |           |            |
| 24      | 21/02/20 15:32                 | Reinspection Photo   | 0     | _         | -          |
| 25      | 21/02/20 15:32                 | Reinspection Photo   | 0     |           | - 1        |
| 26      | 21/02/20 15:32                 | Reinspection Photo   |       |           | -          |
| 27      | 21/02/20 15:32                 | Reinspection Photo   | 0     |           |            |
| 28      | 21/02/20 15:32                 | Reinspection Photo   | 0     | _         |            |
| 29      | 21/02/20 15:32                 | Reinspection Photo   | 0     |           |            |
| 30      |                                | Reinspection Photo   | 0     |           | -          |
| 31      |                                | Reinspection Photo   | •     |           | - 10       |
| 32      |                                | Reinspection Photo   | 0     | -         | -          |
| 33      |                                | Reinspection Photo   | •     | _         | _          |
| 34      |                                | Reinspection Photo   | •     | Load JPG  | 9          |
| -       | 21/02/20 15:32                 | Reinspection Photo   | •     | Load JPG  | 6          |

| 2020 |                 |  | 1 per  | page ▼    | •     |
|------|-----------------|--|--|-----------|-------|
| Vide | 80              |  |  | Thumbnail | Print |
| No   | Finalized On    | Premium Automobiles Pte Ltd (UBI)          | 0  | Load JPG  | •     |
| 36   | 21/02/20 15:32  | Reinspection Photo                         | 0  | 2000 31 0 | 965   |
|      |                 |  | 1 per  | page 🔻    | ~     |
| Doc  | umentation      |  |  | Thumbnail | Print |
| No   | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)  | 0  | Load JPG  | •     |
| 1    | 27/11/19 14:52  | Driving Licence Validity                   |  | Thumbnail | Print |
| No   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | 0  | Load PDF  | 1     |
| 1    | 27/11/19 09:03  | SMF 2645R GIA.pdf                          | ŏ  | Load PDF  |       |
| 2    | 27/11/19 09:03  | DRIVING & CI.pdf                           | 0  | Load PDF  |       |
| 3    | 27/11/19 09:03  | INTERVIEW & UNDERTAKING FORM.pdf 124.70 KB | and the same of th | Load PDF  | -     |
| 4    | 27/11/19 09:03  | ESTIMATE.pdf                               | 0  | Load PDF  | -     |
| 5    | 24/02/20 10:43  | ESTIMATE MARKED.pdf                        | 0  |           |       |
| 6    | 13/03/20 13:51  | WORKSHOP INVOICE                           | 0  | Load PDF  | -     |
| 7    | 13/03/20 13:52  | DISCHARGE VOUCHER                          | 0  | Load PDF  | -     |

# **Linked Accident Report Documents**

|      | View in Browser ' |  | er ▼  |              |          |
|------|-------------------|--|-------|--------------|----------|
|      |                   |  | 1 per | page ▼       | •        |
| /ide |                   | Table 1 to makilog Pho Ltd (LIRI)  |       | Thumbnail    | Print    |
| lo   | Finalized On      | Premium Automobiles Pte Ltd (UBI)  Video - Accident  | 0     | Load MP4     |          |
|      | 22/11/19 16:47    | Video - Accident   |       |              | 1000     |
| 1556 | essment Reports   |  | 1 per |              | •        |
| Vo   | Finalized On      | Premium Automobiles Pte Ltd (UBI)  |       | Thumbnail    |          |
| 1    | 22/11/19 18:12    | Addendum Sheet   | 0     | Load JPG     | •        |
|      | 06/12/19 19:25    | Accident Statement   | 0     | Load HTM     |          |
| 2    | 06/12/19 19:26    | Accident Statement   | 0     | Load HTM     |          |
| 4    | 06/12/19 19:26    | Accident Statement   | 0     | Load HTM     |          |
| 5    | 06/12/19 19:29    | Accident Statement   | 0     | Load HTM     |          |
| 6    | 06/12/19 19:29    | Accident Statement   | 0     | Load HTM     |          |
| 7.   | 06/12/19 19:29    | Accident Statement   | ŏ     | Load HTM     |          |
| 8    | 06/12/19 19:30    | Accident Statement   | 0     | Load HTM     |          |
| 9    | 06/12/19 19:32    | Accident Statement   |       | - Louis IIII | 7        |
|      |                   |  | 3 per | page ▼       | •        |
|      | tos/Images        | AIG Asia Pacific Insurance Pte. Ltd. (SG)  |       | Thumbnail    | Print    |
| No   | Finalized On      | Accident Photo   | 0     | Load JPG     | •        |
| 1    | 22/11/19 11:55    | TO STATE OF THE ST | 0     | Load JPG     | •        |
| 2    | 22/11/19 11:55    | Accident Photo   | 0     | Load JPG     | •        |
| 3    | 22/11/19 11:55    | Accident Photo   |       | Thumbnail    | Print    |
| No   | Finalized On      | Premium Automobiles Pte Ltd (UBI)  | 0     | Load JPG     | •        |
| 1    | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | •        |
| 2    | 22/11/19 17:20    | Accident Photo   | ŏ     | Load JPG     | •        |
| 3    | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | •        |
| 4    | 22/11/19 17:20    | Accident Photo   |       |              | •        |
| 5    | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | -        |
| 6    | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | •        |
| 7    | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | ×        |
|      | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | •        |
| 8    |                   | Accident Photo   | 0     | Load JPG     | 2        |
| 9    | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | •        |
| 10   | 22/11/19 17:20    |  | 0     | Load JPG     | •        |
| 11   | 22/11/19 17:20    | Accident Photo   | 0     |              | •        |
| 12   | 22/11/19 17:20    | Accident Photo   | 0     |              | •        |
| 13   | 22/11/19 17:20    | Accident Photo   | 0     |              | •        |
| 14   | 22/11/19 17:20    | Accident Photo   |       |              | <b>2</b> |
| 15   | 22/11/19 17:20    | Accident Photo   | 0     | Load JPG     | •        |
|      |                   |  | 1 0   | er page 🔻    |          |
| Do   | cumentation       |  | 1-7   | Thumbna      | -        |
| No   | Finalized On      | Premium Automobiles Pte Ltd (UBI)  | 6     |              | - 670    |
| 1    | 22/11/19 16:57    | Sketch Plan  |       |              | -        |

| 2020 | 2020           |                                   | 1 per page ▼ |       |
|------|----------------|-----------------------------------|--------------|-------|
| Vide |                |                                   | Thumbna      | Print |
| No   | Finalized On   | Premium Automobiles Pte Ltd (UBI) | ♠ Load JPG   | •     |
| 2    | 22/11/19 16:57 | Sketch Plan #2                    |              |       |

# **Documents Checklist**

|   | Reset   Save   Print |
|---|----------------------|
| DOCUMENTS CHECKLIST   |                      |
| There are no document checklists configured.  |                      |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)   |                      |
|   |                      |
| Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties. |                      |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #08-16

Our File No: Date:

Singapore 079120

REFERENCE

CHOOH CHUEN SIN (SHI JUNXING) Insured/Claimant:

21/11/2019 Date of Loss:

1800130211 Policy No:

Nature of Claim: OD

13/03/2020

7836898076SG Claim No:

WAUZZZF41JA231770

CVK068771

15959 km

CC3/AIG19020927/ASF3N2

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg. Date:

SMF2645R

Make & Model:

AUDI A4, 2.0 TFSI QU S-TRONIC (A)

31/10/2018 (Man. Year: 2018)

Colour: Engine Capacity: Silver 1984 cc

Market Value/New Car Price:

\$\$135,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable): Yes

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

Engine Modification: Yes

No Pre-accident Condition:

CONDITION OF TYRES

225/50R17

Rear Tyre Size: Rear Left Side:

225/50R17 Michelin 6 mm

Front Left Side: Front Right Side:

Front Tyre Size:

Michelin 6 mm Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

|   | Repairer's | Adjuster's | Difference | Diff % |
|---|------------|------------|------------|--------|
| COST OF CLAIMS                              | 12,680.00  | 8,294,48   | 4,385.52   | 34.59  |
| Parts                                       | 0.00       | 0.00       | 0.00       | -      |
| Miscellaneous Items                         | 6,202.00   | 3,872.00   | 2,330.00   | 37.57  |
| Labour                                      | 0.00       | 0.00       | 0.00       |        |
| Paintwork Labour                            | 0.00       | 0.00       | 0.00       |        |
| Towing                                      | 18,882.00  | 12,166.48  | 6,715.52   | 35.57  |
| Calculated Gross Total (S\$) - Excess (S\$) | 550.00     | 550.00     | 0.00       | 0.00   |
| (S\$)                                       | 18,332.00  | 11,616.48  | 6,715.52   | 36.63  |
| + GST 7.00/7.00% (S\$)                      | 1,283.24   | 813.15     | 470.09     | 36.63  |
| Nett Amount (S\$)                           | 19,615.24  | 12,429.63  | 7,185.61   | 36.63  |

INSPECTION

Date of Assignment:

26/11/2019

Date Inspected:

26/11/2019

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

5.0 days

ADRIAN LING Adjuster:

Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

|      |                  | nded Parts<br>lo. Particulars              | Condition         | Repairer's  | Amount       |
|------|------------------|--|-------------------|-------------|--------------|
|      |                  |  | Deformed          | 1,999.00 FS | *1,599.20 FS |
| 1    | 1                | *FRONT BUMPER                              | Not Necessary     | 258.00 FS   | *-FS         |
| 2    | 1                | *FRONT BUMPER FIXING PARTS                 | Not Necessary     | 64.00 FS    | *-FS         |
| 3    | 2                | *FRONT BUMPER SECURING STRIP               | Not Necessary     | 191.00 FS   | *-FS         |
| 4    | 1                | *FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE | Not Necessary     | 56.00 FS    | *-FS         |
| 5    | 1                | *FRONT BUMPER AIR GUIDE-RH                 | Not Necessary     | 123.00 FS   | *-FS         |
| 6    | 1                | *FRONT BUMPER AIR GUIDE GRILLE-RH          | Damaged           | 34.00 FS    | *27.12 FS    |
| 7    | 1                | *FRONT BUMPER GUIDE SECTION-RH             | Not Necessary     | 231.00 FS   | *-FS         |
| 8    | 1                | *FRONT PARKING AID SENSOR-INNER/OUTER      | Dented            | 700.00 FS   | *559.60 FS   |
| 9    | 1                | *FRONT FENDER-RH                           | Not Necessary     | 183.00 FS   | *-FS         |
| 10   | 1                | *FRONT FENDER ATTACHMENT PARTS             | Bent              | 45.00 FS    | *36.00 FS    |
| 11   | 1                | *FRONT FENDER CLOSING ELEMENT-RH           |                   | 32.00 FS    | *-FS         |
| 12   | 1                | *FRONT FENDER BRACKET-RH                   | Not Necessary     | 45.00 FS    | *-FS         |
| 13   | 1                | *DEFORMATION ELEMENT BRACKET-RH            | Not Necessary     | 107.00 FS   | *85.60 FS    |
| 14   | 1                | *FRONT FENDER BRACE-RH                     | Bent              | 220.00 FS   | *175.60 FS   |
| 15   | 1                | *FRONT WHEEL HOUSING LINER-RH              | Torn              | 82.00 FS    | *- FS        |
| 16   | 1                | *WHEEL HOUSING LINER ATTACHMENT PARTS      | Not Necessary     | 66.00 FS    |              |
| 17   | 1                | *WHEEL SPOILER                             | Cracked           | 33.00 FS    |              |
| 18   | 1                | *WHEEL SPOILER TRIM-RH                     | Not Necessary     | 46.00 FS    |              |
| 19   | 1                | *STONE CHIP GUARD-RH                       | Necessary         | 21.00 FS    |              |
| 20   | 1                | *FENDER LEDGE TOP COVER-RH                 | Necessary         |             |              |
| 21   | 1                | *FENDER LEDGE COVER-RH                     | Necessary         | 28.00 FS    | 경            |
| 22   | 1                | *LED HEADLIGHT-RH                          | Cut               | 7,087.00 FS |              |
| 23   | 1                | *FRONT ALUMINIUM RIM-RH                    | Not Necessary     | 629.00 FS   |              |
| 24   | 1                | *SUNDRIES                                  | Necessary         | 400.00 FS   | *14.40 FS    |
| 0.77 | ranchise part. S |  |                   |             |              |
| 100  | ranomico parti e | 957-334337                                 | Total Parts (S\$) | 12,680.00   | 8,294.48     |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

| Re<br>∾ | commended Labour Particulars  | Lab.Type      | Repairer's | Amount   |
|---------|---|---------------|------------|----------|
| Lab     | our Items   | New           | 480.00     | 480.00   |
| 1       | TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE |               |            |          |
|         | SENSOR.HEADLIGHT WASHER ASSY AND FRONT PARKING AID  | New           | 300.00     | 300.00   |
| 2       | TO DISMANTLE RHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL RHS WING MIRROR ASSY             | INCW          | X-3-333-3  |          |
| 3       | TO DISMANTI E AND RENEW FRONT BUMPER, RHS FRONT FENDER  | New           | 2,450.00   | 1,250.00 |
| 78      | AND HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT<br>COMPONENTS.REINSTALL ALL PARTS REMOVED      |               |            |          |
|         | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHF   | New           | 2,500.00   | 1,650.00 |
| 4       | DOOR  |               |            |          |
| -       | TO RENEW RHS FRONT RIM.CARRY OUT WHEEL ALIGNMENT  | New           | 280.00     | 0.00     |
| 5       | TO CARRY OUT DIAGNOSTIC CHECK   | New           | 192.00     | 192.00   |
| 6       | TO CARRY OUT DIAGNOSTIC STILLON   | -             |            |          |
|         | Gross Labou   | ır Cost (S\$) | 6,202.00   | 3,872.00 |
| _       | Report was unsubmitted during this  | print-out.    |            |          |

< END OF ESTIMATES >