

# WORTDELGRO ENGINEERING PTE LTD

DATE: AIR ESTIMATE\*

VEHICLE NO : SHD3037J  
 MAKE : HYUNDAI  
 MODEL : i40

DATE: 26. Nov. 2019

DOA: 22. Nov. 2019

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover x(R)			\$1,052.20
1	Front Bumper Side Bracket - RH xun			\$24.60
1	Front Bumper Top Bracket - RH xun			\$22.40
10	Front Bumper Clips xun		\$2.20	\$22.00
1	Front Bumper Grille - RH xun			\$41.60
1	Headlamp - RH cra			\$1,388.00
1	Headlamp Support Panel xun			\$907.40
1	Front Fender - RH x(R)			\$566.30
SUB TOTAL				\$4,024.50
LESS 20%				\$804.90
DISCOUNTED TOTAL				\$3,219.60
1 Advertisement - RHF Fender				\$100.00
Labour Charge				
1	Panel Beating		\$480	\$500.00
1	Spray Painting Charge		\$400	\$500.00
1	Tuff Kote		xun	\$50.00
1	Wiring Charge		xun	\$50.00
TOTAL LABOUR				\$1,100.00
ESTIMATE TOTAL				\$4,419.60

\$1110.4

Nett

\$100.00

Ram (LKR)  
 26/11/19 1330V5Xm  
 Ram@LKR.com  
 88622720  
 aft repair  
 photo

2090

45

3 repair days

45: \$1650/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.