

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Date : #####

M/SAIG INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SJX6972K (MERCEDES-BENZ C180)

TO SUPPLY :

List Items

- | | | | | |
|---|-------|----------------------------|-------|---------|
| 1 | 1 PC | FRONT BUMPER | DD/OE | 1322.23 |
| 2 | 2 PCS | FRONT BUMPER SIDE RETAINER | 11 | |
| 3 | 2 PCS | FRONT HEADLAMP | one | |
| 4 | 1 PC | REAR BUMPER | DD/OE | 135.12 |
| 5 | 2 PC | REAR BUMPER SIDE RETIANER | 11 | |
| 6 | 1 PC | REAR BUMPER REINFORCEMENT | DD | |
| 7 | 1 PC | Rear end panel | 1 | |

NETT ITEM

\$	1,506.00	✓
\$	48.00	X
\$	3,160.00	✓
\$	1,758.00	✓
\$	80.00	X
\$	665.00	✓
\$	1,225.00	X
\$	8,442.00	

LESS 10% \$ (610.60)

\$	7,831.40	
\$	300.00	X
\$	180.00	X
\$	40.00	✓
\$	50.00	X

- | | | | |
|----|------|-----------------------------|-----|
| 8 | 1 PC | Rear reverse sensor (1 set) | 822 |
| 9 | | Rear bumper clip (2 set) | 11 |
| 10 | | Front number plate | 2nd |
| 11 | | REAR PANEL SEALANT | 11 |

Labour Costs

- | | | | | |
|----|---|----|-----------|-----|
| 12 | To remove& refix rear damage parts | \$ | 980.00 | 600 |
| 13 | To remove and refit wiring | \$ | 30.00 | 15 |
| 14 | To remove and refit inner garnishes | \$ | 50.00 | 4 |
| 15 | To remove and refit rear reverse sensor | \$ | 80.00 | 40 |
| 16 | To spray painting | \$ | 880.00 | 500 |
| 17 | To apply undercoating | \$ | 120.00 | 40 |
| 18 | TO SPRAY PAINTING FRONT | \$ | 880.00 | 400 |
| 19 | CHECK HARNESS | \$ | 11 150.00 | X |
| 20 | TO REMOVE AND REFIX AIRCON PARTS | \$ | 11 160.00 | X |
| 21 | LABOUR CHARGES RENEW FRONT PARTS REPAIR SUPPORT | \$ | 780.00 | 500 |
| | | \$ | 12,511.40 | |

Jin Auto Consultants hence notify

owner of the following:

1. To remove and refit spray painting

2. To remove and refit inner garnishes

3. To remove and refit rear reverse sensor

4. To remove and refit rear reverse sensor

5. To remove and refit rear reverse sensor

6. To remove and refit rear reverse sensor

7. To remove and refit rear reverse sensor

8. To remove and refit rear reverse sensor

9. To remove and refit rear reverse sensor

10. To remove and refit rear reverse sensor

11. To remove and refit rear reverse sensor

12. To remove and refit rear reverse sensor

13. To remove and refit rear reverse sensor

14. To remove and refit rear reverse sensor

15. To remove and refit rear reverse sensor

16. To remove and refit rear reverse sensor

Acknowledged by Repairer

Signature: Page 1 of 1