

27/03/2002

ASS. REC. BY:

REF: CS/CT1 1902097C/E 94337

Special Instruction:

Surveyor:

Steve

ASSIGNMENT (Office)

Date/Time: 27.11.19 9.07a.m

From (Person): Chong Boon Sen

of CT1

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SNJ 6508X

To Inspect Vehicle No:

SMF 5196A

Tel: 97704368

at Workshop m/s

Wearness

of 45 Long Kee Road

Policy No:

DMP/CSN/5062819044

Claim No:

SNM19D205609C02

Excess:

Sum Insured:

D.O.A. 25.11.2019

Make of Veh:

(Client's Record)

Impi

CA / REV / REP. / REV 24 HRS

Patricia

H.O.D. Endorsement:

Date/Time: 27.11.19 11.42a.m

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMF 5196A - NBA 1CT1 1902097C/E 94337
	SNJ 6508X - X

D.O.A. - 19/11/2019

ASS. REC. BY:

Steve

REF:

CTI

ASSIGNMENT

From:

Date:

28/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMF 5196A

at Workshop m/s

Weavnes

of

45 Leng Kee Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

10:30am (waiting)

(Policy Condition)

Patricia

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SMF 5196A

Yr Regn: 15/11/18

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Land Rover Discovery Spd

C.C. 1997

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

7398

T/Radio: Insured / Std / NI / NA

Eng/No:

SALCA2AX8JH 761176

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19

R:

C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/11/19

D.O.I.

28/11/19

Survey held at

Weavnes

Des. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/12/19

N/V - 185K

Finalke \$14,162.66 - 5 days (Patricia) Ched \$8934.73, 39%

RECEIVED 08 JAN 2020

Date/Time, File Pass to?

1) 08/11/19

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S+RS \$

Folio:

Other:

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

MER-TP

Lump Sum / L.E.J. (\$)

14162.66

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 27 November 2019 9:07 AM
To: Patricia Kueh Anak Slin
Cc: Paul Ong Qing Yong; assignments
Subject: RE: OUR REF: SNM19D205609/SNJ6508X/CBS & YOUR REF: SMF5196A -TO CONDUCT PRS -TP Claim for SMF5196A

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Patricia Kueh Anak Slin [mailto:patricia.kueh@wearnes.com]
Sent: Tuesday, November 26, 2019 5:51 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: RE: OUR REF: SNM19D205609/SNJ6508X/CBS & YOUR REF: SMF5196A -TO CONDUCT PRS -TP Claim for SMF5196A

Dear Boon Sen,

Please assign LKK to survey.

Thank you.

Patricia Kueh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 | D (65) 6378 9336
www.wearnesauto.com | patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 26 November, 2019 5:44 PM
To: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: RE: OUR REF: SNM19D205609/SNJ6508X/CBS & YOUR REF: SMF5196A -TO CONDUCT PRS -TP Claim for SMF5196A

Without prejudice
Dear Sir,
LKK
STA
LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Patricia Kueh Anak Slin [<mailto:patricia.kueh@wearnes.com>]
Sent: Tuesday, November 26, 2019 3:51 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: RE: OUR REF: SNM19D205609/SNJ6508X/CBS & YOUR REF: SMF5196A -TO CONDUCT PRS -TP Claim for SMF5196A

Dear Boon Sen,

Please refer attachments and advise if we can settle direct for this case.

Kindly please arrange for pre-repair survey on 27.11.19 at 2pm. Location at 45 Leng Kee Road. Owner will be waiting.

Please advice for confirmation survey date and time.

Thank you.

Patricia Kueh
Service Consultant
Bodywork & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 | D (65) 6378 9336
www.wearnesauto.com | patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Tuesday, 26 November, 2019 3:48 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Subject: OUR REF: SNM19D205609/SNJ6508X/CBS & YOUR REF: SMF5196A -TO CONDUCT PRS -TP Claim for SMF5196A

Dear Boon Sen,

Please conduct PRS-SMF5196A soonest possible.(Our Insured has not filed SAS Report)

Officer In Charge –Chong Boon Sen -6389 6171.

Dear Patricia,

**** kindly quote our reference number when replying ****

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Patricia Kueh Anak Slin [<mailto:patricia.kueh@wearnes.com>]
Sent: Tuesday, 26 November, 2019 11:07 AM
To: Claims Dept of CTI
Cc: Paul Ong Qing Yong
Subject: TP Claim for SMF5196A

Hi,

Please refer attachments and advise if we can settle direct for this case.

Kindly please arrange for pre-repair survey on 27.11.19 at 2pm. Location at 45 Leng Kee Road. Owner will be waiting.

Please advice for confirmation survey date and time.

Thank you.

Patricia Kueh
Service Consultant
Bodyshop & Paint



WEARNES

Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2019 16:32
Date Of Accident	25/11/2019 12:30
Exact Location Of Accident	COMMONWEALTH AVE WEST TOWARDS CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF5196A
Insured/Policyholder	
Name Of Registered Owner	YUAN MEIQI
NRIC No	S8481692B
Email Address	NOEMAIL@CONTRACT.COM
Mobile Phone No	(LOCAL) +65-83333313
Alternative Phone No	OTHERS-83333313
Vehicle Particulars	
Manufacturer	LAND ROVER
Model	DISCOVERY SPORT-2.0 SE SI4 (L550) (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI19V11907/VPC/R01
Cover Note Number	

Driver

Name of Driver	YUAN MEIQI
NRIC No	S8481692B
Date Of Birth	13/07/1984
Occupation	INDOOR
Date Of Driving Pass	14/07/2016
Driving Experience	3 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83333313
Fax Number	
Contact Number	OTHERS-83333313
Email Address	NOEMAIL@CONTRACT.COM

Address	BLK 201 CLEMENTI AVENUE 6 #10-37
Postcode	120201
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : YUAN ZHENGDA GENDER: : MALE
Passenger 2	NAME: : PA PA WIN GENDER: : FEMALE
Passenger 3	NAME: : WAI WAI THAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer attachments.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN6508X
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;

(collectively the "Purposes").

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

Around 12. P.M, at the cross junction between
Commonwealth West & Cleverly Ave 6, while stopping
behind the traffic light, a Honda vehicle number
SJN 6508X hit from behind.


IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence
or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	692B
Vehicle Details	
Vehicle No.:	SMF5196A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Nov 2019
Vehicle Make:	LAND ROVER
Vehicle Model:	DISCOVERY SPORT 2.0P 7 SEATER S/R
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	180220Y0094PT204
Chassis No.:	SALCA2AX8JH761176
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$43,951.00
Original Registration Date:	15 Nov 2018
First Registration Date:	15 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$53,532.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Nov 2028
PARF Rebate Amount:	\$40,149.00
Intended COE Rebate Details	
COE Expiry Date:	14 Nov 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,900.00
COE Rebate Amount:	\$28,057.00
Total Rebate Amount:	\$68,206.00

The information contained herein is correct as at 28 Nov 2019

OK

Steve (LKK)

28/11/19, 19:30 an

5 days

P/P

Ry P/L SM

SERVICE ESTIMATE

99092 - C00001

SL: SERVICE SALES - PC

Ms Yuan Meiqi

BLK 201 Clementi Avenue 6

#10-37

Singapore 120201

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 26/11/2019

WIP No. : 49925

Veh.In/Out:

*Tel.No. : Mobile: 83333313

Reg.No. : SMF5196A

Reg.date : 15/11/2018

Mileage : 0

Chassis No: SALCA2AX8JH761176

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Ms Yuan Meiqi

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE TAILGATE, REAR BUMPER, REAR TOW COVER, PARKING SENSORS, REAR BUMPER BEAM, REAR BUMPER FOAM, REAR PANEL, REAR BUMPER REFLECTOR RH, REAR BUMPER REFLECTOR LH, ETC	0	4800.00	0		4,800.00 S	2400/-
800	TO PUTTY SPRAYPAINT AND BLENDING OF PAINT ON REAR BUMPER, TAILGATE, REAR PANEL, ETC	0	4000.00	0		4,000.00 S	2000/-
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	510.00	0		510.00 S	//
802	TO TRANSFER TAILGATE PARTS	0	500.00	0		500.00 S	//
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00 S	600/-
0080	TO INSTALL REAR WINDSCREEN	0	280.00	0		280.00 S	//
419	WHEEL ALIGNMENT	0	280.00	0		280.00 S	X
	LLR106865/BUMPER - R	1.0 EA	1616.40	1506.15		1,616.40 S	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

99092 - C00001 SL: SERVICE SALES - PC

Ms Yuan Meiqi
BLK 201 Clementi Avenue 6
#10-37

Singapore 120201

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 26/11/2019

WIP No. : 49925

Veh.In/Out:

*Tel.No. : Mobile: 83333313

Reg.No. : SMF5196A

Reg.date : 15/11/2018

Mileage : 0

Chassis No: SALCA2AX8JH761176

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Ms Yuan Meiqi

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	TOW EYE COVER REAR D		1.0 EA	530.90	487.35		530.90	S
	REINFORCEMENT - BUMP		1.0 EA	595.40			595.40	S
	BRACKET - BUMPER MOU		1.0 EA	115.20			115.20	S
	BRACKET - BUMPER MOU		1.0 EA	115.20			115.20	S
	SENSOR - PARKING AID		2.0 EA	366.80	673.39		1,467.20	S
	LAMP - FOG - REAR RH		1.0 EA	337.00			337.00	S
	LAMP - FOG - REAR LH		1.0 EA	337.00			337.00	S
	GLASS - BACK WINDOW		1.0 EA	1038.70	953.55		1,038.70	S
	ADHESIVE AND SEALER		2.0 EA	147.50	290.90		295.00	S
	BADGE REAR "DISCO" D		1.0 EA	159.00	145.98		159.00	S
	BADGE REAR "VERY" DS		1.0 EA	142.60	130.95		142.60	S
	BADGE OVAL REAR RR3		1.0 EA	84.70	77.76		84.70	S
	NAME PLATE - PLASTIC		1.0 EA	128.40			128.40	S
	ADHESIVE SEALER FL2		1.0 EA	669.10	614.35		669.10	S
	BODY PANEL SEALANT X		1.0 EA	883.20			883.20	S

Gross Total. 20,085.00

Labour Total 11,570.00
Parts Total 8,515.00
Package Total 0.00

Net..... 20,085.00

GST @ 7.0% 1,405.95

Total..... 21,490.95

Paid..... 0.00

Please Pay.. 21,490.95

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

23/11/19

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 26/12/2019
 SINGAPORE 079909 WIP No. . : 49925
 Veh.In/Out: 16/12/2019 26/12/2019
 *Tel.No. . : 63896111
 Reg.No. . : SMF5196A
 Closed by : Patricia Kueh Anak S Reg.date .: 15/11/2018
 Svc Consultant : ACC Mileage .. : 7,798
 Remarks : Ms Yuan Meiqi Chassis No: SALCA2AX8JH761176

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE TAILGATE, REAR BUMPER,REAR TOW COVER, PARKING SENSORS,ETC	0	2400.00	0		2,400.00	S/
800	TO PUTTY SPRAYPAINT AND BLENDING OF PAINT ON REAR BUMPER,TAILGATE,ETC	0	2000.00	0		2,000.00	S/
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	510.00	0		510.00	S/
802	TO TRANSFER TAILGATE PARTS	0	500.00	0		500.00	S/
802	TO REPLACE REAR WINDSCREEN	0	600.00	0		600.00	S/
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S/
	TOW EYE COVER REAR D	1.0 EA	541.50	10		487.35	S/
	SENSOR - PARKING AID	2.0 EA	374.10	10		673.38	S/
	GLASS - BACK WINDOW	1.0 EA	1059.50	10		953.55	S/
	ADHESIVE AND SEALER	2.0 EA	150.50	10		270.90	S/
	BADGE REAR "DISCO" D	1.0 EA	162.20	10		145.98	S/
	BADGE REAR "VERY" DS	1.0 EA	145.50	10		130.95	S/

SERVICE ESTIMATE

0 - C00010 - 3L: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 2
 #16-00, SPRINGLEAF TOWER Inv.date. : 26/12/2019
 SINGAPORE 079909 WIP No. : 49925
 Veh.In/Out: 16/12/2019 26/12/2019

Closed by : Patricia Kueh Anak S
 Svc Consultant : ACC
 Remarks : Ms Yuan Meiqi

*Tel.No. : 63896111
 Reg.No. : SMF5196A
 Reg.date. : 15/11/2018
 Mileage : 7,798
 Chassis No: SALCA2AX8JH761176

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BADGE OVAL REAR RR3	1.0 EA	86.40	10		77.76	S/
	TAILGATE PANEL DSPOR	1.0 EA	3347.10	10		3,012.39	S/
	ADHESIVE SEALER FL2	1.0 EA	682.50	10		614.25	S/
	BUMPER - REAR	1.0 EA	1673.50	10		1,506.15	S/

Labour Total 6,290.00
 Parts Total 7,872.66
 Package Total 0.00

Gross Total. 14,162.66 ✓
 Net..... 14,162.66
 GST @ 7.0% 991.39
 Total..... 15,154.05
 Paid..... 0.00
 Please Pay.. 15,154.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE - Supplementary

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No: M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date : 26/12/2019
 SINGAPORE 079909 WIP No. : 49925
 Veh.In/Out: 16/12/2019 26/12/2019

Closed by : Patricia Kueh Anak S
 Svc Consultant : ACC
 Remarks : Ms Yuan Heiqi

*Tel.No. : 63896111
 Reg.No. : 3MF5196A
 Reg.date : 15/11/2018
 Mileage : 7,798
 Chassis No: SALCA2AX8JH761176

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	TAILGATE PANEL DSPOR / 00	1.0 EA	3347.10	10		3,012.39	3 - Supp
--	---------------------------	--------	---------	----	--	----------	----------

			Gross Total.	3,012.39
Labour Total	0.00		Net.....	3,012.39
Parts Total	3,012.39		GST @ 7.0%	210.87
Package Total	0.00		Total.....	3,223.26
			Paid.....	0.00
			Please Pay..	3,223.26

GSI: S=StdRated; O=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2020		08 Jan 2020 11:51 Edit Adj Rpt	S\$14,162.66 Edit Estimates	S\$14,162.66 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: YUAN MEIQI , ID: S8481692B									
Vehicle Reg. No.:	SMF5196A	Date of Loss:	25/11/2019 12:00 - :59 [12 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205609C02	Policy/Cover Note No.:	DMPCSN15062819044						
Vehicle Reg. No. (Insured):	SJN6508X	Policy No. (Claimant):	SI19V11907/VPC/R01						
		Excess:	S\$0.00						
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMF5196A (SNM19D205609C02)**
[SJN6508X]

TP
YUAN MEIQI
Nov 25 2019 12:00PM
[-]

Wearnes Automotive Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Video			1 per page ▼	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	25/11/19 16:54	Video - Accident [Linked Accident Report Documents]	Load MP4	☒
Assessment Reports			1 per page ▼	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	06/12/19 19:41	Accident Statement	Load HTM	☒
2	09/12/19 15:06	Addendum Sheet	Load TIF	☒
3	09/12/19 15:06	Accident Statement	Load HTM	☒
4	12/12/19 12:11	Addendum Sheet	Load TIF	☒
5	12/12/19 12:11	Accident Statement	Load HTM	☒
Photos/Images			3 per page ▼	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	25/11/19 17:00	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/20 15:05	General View	Load JPG	☒
2	08/01/20 15:05	General View	Load JPG	☒
3	08/01/20 15:05	General View	Load JPG	☒
4	08/01/20 15:05	General View	Load JPG	☒
5	08/01/20 15:05	General View	Load JPG	☒
6	08/01/20 15:05	General View	Load JPG	☒
7	08/01/20 15:05	General View	Load JPG	☒
8	08/01/20 15:05	General View	Load JPG	☒
9	08/01/20 15:05	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
10	08/01/20 15:05	General View	Load JPG	☒
11	08/01/20 15:05	General View	Load JPG	☒
12	08/01/20 15:05	General View	Load JPG	☒
13	08/01/20 15:05	General View	Load JPG	☒
14	08/01/20 15:05	General View	Load JPG	☒
15	08/01/20 15:05	General View	Load JPG	☒
16	08/01/20 15:05	General View	Load JPG	☒
17	08/01/20 15:05	General View	Load JPG	☒
18	08/01/20 15:05	General View	Load JPG	☒
19	08/01/20 15:05	General View	Load JPG	☒
20	08/01/20 15:05	General View	Load JPG	☒
21	08/01/20 15:05	General View	Load JPG	☒
22	08/01/20 15:05	General View	Load JPG	☒
23	08/01/20 15:05	General View	Load JPG	☒
24	08/01/20 15:05	General View	Load JPG	☒
25	08/01/20 15:05	General View	Load JPG	☒
26	08/01/20 15:05	Odometer Reading	Load JPG	☒
27	08/01/20 15:05	Chassis Number	Load JPG	☒
28	08/01/20 15:05	General View	Load JPG	☒
29	08/01/20 15:05	General View	Load JPG	☒
30	08/01/20 15:05	General View	Load JPG	☒
31	08/01/20 15:05	General View	Load JPG	☒
32	08/01/20 15:05	General View	Load JPG	☒
33	08/01/20 15:05	General View	Load JPG	☒
34	08/01/20 15:05	General View	Load JPG	☒
35	08/01/20 15:05	General View	Load JPG	☒
36	08/01/20 15:06	BEFORE PAINT PHOTOS	Load JPG	☒
37	08/01/20 15:06	BEFORE PAINT PHOTOS	Load JPG	☒
38	08/01/20 15:06	BEFORE PAINT PHOTOS	Load JPG	☒
39	08/01/20 15:06	BEFORE PAINT PHOTOS	Load JPG	☒
40	08/01/20 15:10	Photo After Spray	Load JPG	☒
41	08/01/20 15:10	Photo After Spray	Load JPG	☒
42	08/01/20 15:10	Photo After Spray	Load JPG	☒
43	08/01/20 15:10	Photo After Spray	Load JPG	☒
44	08/01/20 15:15	General View	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	25/11/19 19:06	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	25/11/19 19:06	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	25/11/19 19:06	Sketch Plan #3 [Linked Accident Report Documents]	Load TIF	
4	25/11/19 19:06	Sketch Plan #4 [Linked Accident Report Documents]	Load TIF	
5	25/11/19 19:06	Sketch Plan #5 [Linked Accident Report Documents]	Load TIF	
6	25/11/19 19:06	Sketch Plan #6 [Linked Accident Report Documents]	Load TIF	
7	25/11/19 19:06	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 16:54	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

			View	View in Browser ▼
Video			1 per page ▼	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	25/11/19 16:54	Video - Accident	Load MP4	
Assessment Reports			1 per page ▼	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	06/12/19 19:37	Accident Statement	Load HTM	
2	06/12/19 19:40	Accident Statement	Load HTM	
3	06/12/19 19:41	Accident Statement	Load HTM	
4	06/12/19 19:41	Accident Statement	Load HTM	
5	09/12/19 15:06	Addendum Sheet	Load TIF	
6	09/12/19 15:06	Accident Statement	Load HTM	
7	12/12/19 12:11	Addendum Sheet	Load TIF	
8	12/12/19 12:11	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	25/11/19 17:00	Accident Photo	Load JPG	☒
2	25/11/19 17:00	Accident Photo	Load JPG	☒
3	25/11/19 17:00	Accident Photo	Load JPG	☒
4	25/11/19 17:00	Accident Photo	Load JPG	☒
5	25/11/19 17:00	Accident Photo	Load JPG	☒
6	25/11/19 17:00	Accident Photo	Load JPG	☒
7	25/11/19 17:00	Accident Photo	Load JPG	☒
8	25/11/19 17:00	Accident Photo	Load JPG	☒
9	25/11/19 17:00	Accident Photo	Load JPG	☒
10	25/11/19 17:00	Accident Photo	Load JPG	☒
11	25/11/19 17:00	Accident Photo	Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	25/11/19 19:06	Sketch Plan	Load TIF	
2	25/11/19 19:06	Sketch Plan #2	Load TIF	
3	25/11/19 19:06	Sketch Plan #3	Load TIF	
4	25/11/19 19:06	Sketch Plan #4	Load TIF	
5	25/11/19 19:06	Sketch Plan #5	Load TIF	
6	25/11/19 19:06	Sketch Plan #6	Load TIF	
7	25/11/19 19:06	Accident Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19020976/EQF3S2
Date: 17/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN15062819044

Claimant Vehicle No: SMF5196A Insured Vehicle No: SJN6508X

Date of Loss: 25/11/2019 Nature of Claim: TP Claim No: SNM19D205609C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF5196A

Make & Model: LAND ROVER DISCOVERY SPORT, 2.0 P 5 SEATER Engine No: 180220Y0094PT204

Reg. Date: 15/11/2018 (Man. Year: 2018) Chassis No: SALCA2AX8JH761176

Colour: White Odometer: 7398 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,527.39	7,872.66	3,654.73	31.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,570.00	6,290.00	5,280.00	45.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,097.39	14,162.66	8,934.73	38.68
+ GST 7.00/7.00% (S\$)	1,616.82	991.39	625.43	38.68
Nett Amount (S\$)	24,714.21	15,154.05	9,560.16	38.68

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 28/11/2019 Inspected At: Wearnes Automotive Pte Ltd
45 LENG KEE ROAD
SINGAPORE 159103

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=904460&extid=328051&CFID=65797258&C... 1/4

1/17/2020

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jan 2020)
Parts:	N/A LAND ROVER DISCOVERY SPORT 2.0 P 5 SEATER S/R (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF5196A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REINFORCEMENT - BUMP	Not Necessary	595.40 FS	*- FS
2	1		*BRACKET - BUMPER MOU	Not Necessary	115.20 FS	*- FS
3	1		*BRACKET - BUMPER MOU	Not Necessary	115.20 FS	*- FS
4	1		*SENSOR - PARKING AID 4pcs	Shorted 2pcs Only	1,467.20 FS	*673.38 FS
5	1		*LAMP - FOG - REAR RH	Not Necessary	337.00 FS	*- FS
6	1		*LAMP - FOG - REAR LH	Not Necessary	337.00 FS	*- FS
7	1		*GLASS - BACK WINDOW	Necessary	1,038.70 FS	*953.55 FS
8	2		*ADHESIVE AND SEALER	Necessary	295.00 FS	*270.90 FS
9	1		*BADGE REAR DISCO D	Necessary	159.00 FS	*145.98 FS
10	1		*TOW EYE COVER REAR D	Broken	530.90 FS	*487.35 FS
11	1		*BADGE REAR VERY DS	Necessary	142.60 FS	*130.95 FS
12	1		*BADGE OVAL REAR RR3	Necessary	84.70 FS	*77.76 FS
13	1		*NAME PLATE - PLASTIC	Not Necessary	128.40 FS	*- FS
14	1		*ADHESIVE SEALER FL2	Necessary	669.10 FS	*614.25 FS
15	1		*BODY PANEL SEALANT X	Not Necessary	883.20 FS	*- FS
16	1		*LLR106865/BUMPER - R	Dented	1,616.40 FS	*1,506.15 FS
17	1		*TAILGATE PANEL DSPOR	Dented	3,012.39 FS	*3,012.39 FS
Total Parts (\$\$)					11,527.39	7,872.66

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE TAILGATE, REAR BUMPER, REAR TOW COVER, PARKING SENSOR, REAR BUMPER BEAM, REAR BUMPER FOAM, REAR PANEL, REAR BUMPER REFLECTOR RH, REAR BUMPER REFLECTOR LH, ETC.	New	4,800.00	2,400.00
2	TO PUTTY SPRAYPAINT AND BLENDING OF PAINT ON REAR BUMPER, TAILGATE, REAR PANEL, ETC.	New	4,000.00	2,000.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.	New	510.00	510.00
4	TO TRANSFER TAILGATE PARTS.	New	500.00	500.00
5	TO REPLACE REAR WINDSCREEN.	New	1,200.00	600.00
6	TO INSTALL REAR WINDSCREEN FIL.	New	280.00	280.00
7	WHEEL ALIGNMENT.	New	280.00	0.00
Gross Labour Cost (\$\$)			11,570.00	6,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >