

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1911-143
DATE : 26-Nov-2019
POLICY NO. : MT/00582872
VEHICLE REG. NO. : SKZ2568Z
VEHICLE MAKE : HONDA VEZEL-1.5 X (A)

P = 2088
L = 430
2,518
- 20%

2,014.4

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

[Empty box for Surveyor Signature]

L/S
\$2,000
2 days

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper / D7	1	\$ 800.00	\$ 800.00
2	Front Bumper Clips / Nec	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH X SVC	1	\$ 20.00	\$ 20.00
4	Front Bumper Retainer LH ? X SVC	1	\$ 20.00	\$ 20.00
5	Front Reinforcement ? X SVC	1	\$ 320.00	\$ 320.00
6	Head Lamp LH / SCR	1	\$ 1,780.00	\$ 1,780.00
7	Head Lamp Upper Bracket LH ? X SVC	1	\$ 30.00	\$ 30.00
8	Head Lamp Lower Bracket LH ? X SVC	1	\$ 30.00	\$ 30.00
9	Front Fog LH X SVC	1	\$ 280.00	\$ 280.00
10	Front Fog Garnish LH X SVC	1	\$ 40.00	\$ 40.00
Total Spare Parts				\$ 3,370.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
11	Spray Painting Front Bumper	1	\$ 400.00	\$ 400.00
12	Remove, Replace and Refit Accident Affected Areas	1	\$ 400.00	\$ 400.00
13	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 830.00
Amount Before Excess				\$ 4,200.00
Add GST @ 7%				294.00
Total Amount Payable				\$ 4,494.00

Estimate prepared by: Raymond Tan
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour \$ 830.00
Amount Before Excess \$ 4,200.00
Add GST @ 7% 294.00
Total Amount Payable \$ 4,494.00

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Repair day - 2 days.

L/S.

After point photo

Sun Pin (Lkk)

21/04/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: