

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 Nov 2019

Preliminary Advice

Vehicle No	: SKE435Y	Accident Date	: 26/11/2019
Make	: AUDI Q3	Policy No.	: 1800096948-01
Assignment Date	: 29/11/2019	Excess	: S\$0.00
Date of Inspection	: 29/11/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,911.00
Revised Amount	:S\$	4,091.00
Check Items (Estimated)	:S\$	774.00
Total	:S\$	4,865.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	136,000.00
COE / PARF Rebate	:S\$	62,561.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,439.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :