

ASSIGNMENT

Surveyor:

MARCUS

DOI: 29.11.2019

Date / Time: 29.11.2019

Registered in Merimen: 29.11.2019

Pre-assign / CCU / FTE



Insured Vehicle No.: SKL 8804B

Claim No.: 0842170265SG

Name of Insured: LIM SWEE HONG

Policy No.: 2100359757

Insured Tel No.: HP: +65-96750651

Make / Model: MERCEDES-BENZ A45 AMG-2.0 (A)

Excess Sec II :S\$ D.O.A: 28/11/2019 18:30

Place of Accident: SIMS AVE. BEFORE JUNCTION OF LOR 1 GEYLANG HEADING

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.: (V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SJQ 8181A

INSRS:
WSP: FASTECH
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	SJQ 8181A - X	SKL 8804B - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI: AFTER 18:12:19	
			After call ltr to OI:	
			Documentation Check List: Handler Typist	
			Notification ltr (if non-pickup)	
			After call ltr to OI:	
			Authorisation To Act:	
			Release Voucher:	
			Final Repair Bill:	
			Car Rental Invoice:	
			Towing Invoice:	
			LTA / GIA:	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction:	
			LOD	
			Payment Breakdown Form:	
			Post-Repair Photos:	
			Others:	
PRELIMINARY ADVICE Date/Time:	Sent By:			
FINALIZATION Date/Time:	Confirm with:		Confirm by:	
Repair Cost: L9	S\$ 7,299.50 (5 days) Reduction: 70 %	Email ☐ Call ☐		
FINAL SETTLEMENT Date/Time: 10/02/20	Confirm with: SHON		Email ☒ Call ☐	
Final Liability: % 100 (Assessed) BOLA S/N No.: 31	If NO or B 28, Ass. Lia:			
Repair Cost: (w/loss) S\$ 7,757.60	O. REAR ENDED TP			
Loss of Rental (LOR): S\$ 540.00 (3 days) x 180				
Loss of Use (LOU): S\$ - (5 x days)				
Loss of Income (LOI): S\$ - (5 x days)				
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]				
GIA/LTA Search S\$ 2.00				
Medical: S\$ -				
Disbursement: S\$ - (e.g. Tow/ Independent)				
Legal Cost S\$ -				
Total: S\$ 8,299.50	Global Sum S\$: -			
FINAL PAYMENT Date/Time:	Confirm with:		Email ☐ Call ☐	
Payee 1: S\$ 8,299.50	Name 1: FASTECH AUTO PTE LTD			
Payee 2: (Strike if N.A.) S\$ -	Name 2: -			
Payee 3: (Strike if N.A.) S\$ -	Name 3: -			

COPY SENT
10/2/20201) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$320.00

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJQ 8181A
 at Workshop m/s R.
 of SJL 8804B
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 115k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7556

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJQ 8181A Yr Regn: 6 118
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Toyota harrier c.c. 1998
 Colour: Black / purple A/C: Insured / Std / NI / NA
 Sp. Reading: 40749 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTEKB36H00J00240
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/35 R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 28/11/18 D.O.I. 29/11/18
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/1/20 4/5 @ 7250 Confirmed with Alu.

CRIP: 417, 100-32 (70%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date: Person Contacted:

N/S	O/S

115k

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

7556

Vehicle: IN / OUT

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

STQ 8181A Yr Regn: 6 118

CA/

Zyoto harrie c.c 1998

Black/purple

40749

JTEKB36H00J002U0

F: 235/35 R18

R:

28/11/18

Date / Time Action / Instruction

2YA 64025

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS - \$

Photos

Others

TOTAL

Not Authorized
28/11/19
2/5 7250/
507.

nu	\$297.54	✓
nu	\$68.10	✓
Body DO	\$1,712.35	✓
nu	\$91.60	✓
nu	\$60.00	✓
17	\$783.20	α
twi	\$341.66	✓
shub	\$459.10	✓
del/tern	\$460.32	✓
17	\$1,160.20	α
D.S	\$455.00	✓
D.S	\$955.10	✓
tern	\$145.00	✓
17	\$136.20	α
nu	\$50.00	✓
Beul	\$1,195.00	✓
sun	\$330.00	X
17	\$151.00	X
DO	\$831.60	✓
twi	\$360.89	✓
crA	\$1,082.20	✓
17	\$820.10	X
R	\$1,166.50	X
R	\$2,042.20	α
17	\$1,290.40	X
17	\$1,185.00	X
shub	\$1,444.40	2pc
17	\$199.20	α
n/s/cr	\$250.00	pc
	\$19,226.32	

(252
9,75.92
6,881.94

11	\$180.00	X
me	\$50.00	40
me	\$50.00	✓
17	\$50.00	X

	\$80.00	30
	\$80.00	50
	\$150.00	120
17	\$100.00	X
	\$150.00	80
	\$120.00	60
17	\$380.00	X
	\$120.00	80
	\$2,200.00	680

TO PUTTY & SPRAY PAINTING

\$1,800.00

1000

TOTAL

\$24,736.32

8071.94

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 6 Months Road Tax! Single Owner, Low Mileage!



Good Fuel Consumption Power With Hybrid Synergy, Beautiful Elegant White!

StarAd



Think One Automobile



Browse by Category		Sort by Date Posted		20 results/page															
9 vehicles		Harrier		Advanced Search Submit															
Search Selection		Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status									
		Harrier		Any	Any	2018	Any	Any	Any	Available									
	Toyota Harrier 2.0A M-Grade Turbo																		
	1 Owner! Agent Unit With 5 Years Borneo Warranty! Free 2 Years Servicing Package From Borneo. Excellent Condition. Accident Free. B...																		
Posted: 28-Nov-2018		Tags: 2018 Toyota Harrier, 2018 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota																	
	Toyota Harrier 2.0A M-Grade Turbo																		
	1 Owner! Extremely Well Maintained By Previous Owner. Tip Top Condition. Fully Agent Maintained. View To Believe. Different Loan Sch...																		
Posted: 26-Nov-2018		Tags: 2018 Toyota Harrier, 2018 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota																	
	Toyota Harrier 2.0A G-Grade Turbo																		
	High Spec Luxury Edition With Toyota Safety Sense, 5 Years Warranty And 3 Years Free Servicing By Borneo Motors, Pristine Condition...																		
Posted: 22-Nov-2018		Tags: 2018 Toyota Harrier, 2018 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota																	
	Toyota Harrier 2.0A G-Grade Turbo																		
	1 Owner! Car Maintained In Pristine Condition! Pearl White Exterior Paintwork Matched With Black Leather Interior! Still Under 5 Years...																		
Posted: 21-Nov-2018		Tags: 2018 Toyota Harrier, 2018 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota																	
	Why Toyota Harrier is the best SUV choice																		
	SUVs are the common choice for practicality. If you are looking for one, you don't need to look further than the Harrier. Here's five reasons why we say so.																		
Read this article																			
	Toyota Harrier 2.0A M-Grade Turbo																		
	1 Owner! Rarely Driven! Agent Unit With 5 Years Borneo Warranty! Pearl White, Excellent Condition. Instant In House Loan Approval, L...																		
Posted: 19-Nov-2018		Tags: 2018 Toyota Harrier, 2018 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota																	
	Toyota Harrier 2.0A G's																		
	Rare High Specs Toyota Harrier Model. In Perfect And Well-maintained Condition. View And Test Drive The Car Today!																		
Posted: 18-Nov-2018		Tags: 2018 Toyota Harrier, 2018 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota																	
Compare																			

https://www.sgcarmart.com/used_cars/listing.php?MOD=Harrier&PRC=0&DEP=0&RGD=2018&VEH... 29-Nov-19

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 755G

Vehicle Details

Vehicle No.: SJQ8181A

Vehicle to be Exported: No

Intended Deregistration Date: 29 Nov 2019

Vehicle Make: TOYOTA

Vehicle Model: HARRIER G GRADE

Primary Colour: Black

Manufacturing Year: 2018

Engine No.: 8ARZ124233

Chassis No.: JTEKB3GH00J002210

Maximum Power Output: 170.0 kW (227 bhp)

Open Market Value: \$35,785.00

Original Registration Date: 19 Jun 2018

First Registration Date: 19 Jun 2018

Transfer Count: 0

Actual ARF Paid: \$42,099.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Jun 2028

PARF Rebate Amount: \$31,574.00

Intended COE Rebate Details

COE Expiry Date: 18 Jun 2028

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$37,989.00

COE Rebate Amount: \$32,501.00

Total Rebate Amount: \$64,075.00

The information contained herein is correct as at 29 Nov 2019

OK

Print Received Message

This mail is associated with :

***SJQ8181A (0842170265SG)**
[SKL8804B]
TP
NG PHEAN HAI, NICHOLAS
Nov 28 2019 12:00AM
[Lim Swee Hong]
Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 04/02/2020 11:24 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8299.50) - SJQ8181A - Claim Handler: Loh, Chee-Heng

Approved:8299.50.

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	755G

Vehicle Details

Vehicle No.:	SJQ8181A
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER G GRADE
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	8ARZ124233
Chassis No.:	JTEKB3GH00J002210
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$35,785.00
Original Registration Date:	19 Jun 2018
First Registration Date:	19 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$42,099.00
Intended ARF Paid:	

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2028
PARF Rebate Amount:	\$31,574.00

Intended COE Rebate Details

COE Expiry Date:	18 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,989.00
COE Rebate Amount:	\$32,501.00
Total Rebate Amount:	\$64,075.00

The information contained herein is correct as at 29 Nov 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Nov 2019 Edit Reg		29 Nov 2019 00:00 Edit Adj Rpt	\$57,250.00 Edit Estimates	\$57,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Lim Swee Hong, ID: -		
Main Claimant:	NG PHEAN HAI, NICHOLAS, ID: S8123755G		
Vehicle Reg. No.:	SJQ8181A	Date of Loss:	28/11/2019 00:00 - :59 [17 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0842170265SG	Policy/Cover Note No.:	2100359757 (Comprehensive) Coverage: 02/01/2019 - 01/01/2020
Vehicle Reg. No. (Insured):	SKL88048	Policy No. (Claimant):	MA004564
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	Etika Insurance Pte Ltd (HQ) - Tel: 63360477		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/12/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (04/02/2020): Alert - Adj Mandate Approved (\$58299.50) - SJQ8181A - Claim Handler: Loh, Chee-H...
- AIG_SG (02/12/2019): TP GIA report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJQ8181A (0842170265SG)
[SKL8804B]

TP

NG PHEAN HAI, NICHOLAS

Nov 28 2019 12:00AM

[Lim Swee Hong]

Fastech Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	---	--

Letters/Correspondences				1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/19 10:16	Chassis Number		Load JPG	☒
2	30/11/19 10:16	Odometer Reading		Load JPG	☒
3	30/11/19 10:17	General View		Load JPG	☒
4	30/11/19 10:17	General View		Load JPG	☒
5	30/11/19 10:17	General View		Load JPG	☒
6	30/11/19 10:17	General View		Load JPG	☒
7	30/11/19 10:17	General View		Load JPG	☒
8	30/11/19 10:17	General View		Load JPG	☒
9	30/11/19 10:17	General View		Load JPG	☒
10	30/11/19 10:17	General View		Load JPG	☒
11	30/11/19 10:17	General View		Load JPG	☒
12	30/11/19 10:17	General View		Load JPG	☒
13	30/11/19 10:17	General View		Load JPG	☒
14	30/11/19 10:17	General View		Load JPG	☒
15	30/11/19 10:17	General View		Load JPG	☒
16	30/11/19 10:17	General View		Load JPG	☒
17	30/11/19 10:17	General View		Load JPG	☒
18	30/11/19 10:17	General View		Load JPG	☒
19	30/11/19 10:17	General View		Load JPG	☒
20	30/11/19 10:17	General View		Load JPG	☒
21	30/11/19 10:17	General View		Load JPG	☒
22	30/11/19 10:17	General View		Load JPG	☒
23	30/11/19 10:17	General View		Load JPG	☒
24	30/11/19 10:17	General View		Load JPG	☒
25	30/11/19 10:17	General View		Load JPG	☒
26	30/11/19 10:17	General View		Load JPG	☒
27	30/11/19 10:17	General View		Load JPG	☒
28	30/11/19 10:17	General View		Load JPG	☒
29	30/11/19 10:17	General View		Load JPG	☒
30	30/11/19 10:17	General View		Load JPG	☒
31	30/11/19 10:17	General View		Load JPG	☒
32	30/11/19 10:17	General View		Load JPG	☒
33	30/11/19 10:17	General View		Load JPG	☒
34	30/11/19 10:17	General View		Load JPG	☒
35	30/11/19 10:17	General View		Load JPG	☒
36	30/11/19 10:17	General View		Load JPG	☒
37	30/11/19 10:17	General View		Load JPG	☒
38	30/11/19 10:17	General View		Load JPG	☒
39	30/11/19 10:20	Reinspection Photo		Load JPG	☒
40	30/11/19 10:20	Reinspection Photo		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	30/11/19 10:20	Reinspection Photo		☒
42	30/11/19 10:20	Reinspection Photo		☒
43	30/11/19 10:20	Reinspection Photo		☒
44	30/11/19 10:20	Reinspection Photo		☒
45	30/11/19 10:20	Reinspection Photo		☒
46	30/11/19 10:20	Reinspection Photo		☒
47	30/11/19 10:20	Reinspection Photo		☒
48	30/11/19 10:20	Reinspection Photo		☒
49	30/11/19 10:20	Reinspection Photo		☒
50	30/11/19 10:20	Reinspection Photo		☒
51	30/11/19 10:20	Reinspection Photo		☒
52	30/11/19 10:20	Reinspection Photo		☒
53	30/11/19 10:20	Reinspection Photo		☒
54	30/11/19 10:20	Reinspection Photo		☒
55	30/11/19 10:20	Reinspection Photo		☒
56	30/11/19 10:20	Reinspection Photo		☒
57	30/11/19 10:20	Reinspection Photo		☒
58	30/11/19 10:20	Reinspection Photo		☒
59	30/11/19 10:20	Reinspection Photo		☒
60	30/11/19 10:20	Reinspection Photo		☒
61	30/11/19 10:20	Reinspection Photo		☒
62	30/11/19 10:20	Reinspection Photo		☒
63	30/11/19 10:20	Reinspection Photo		☒
64	30/11/19 10:20	Reinspection Photo		☒
65	30/11/19 10:20	Reinspection Photo		☒
66	30/11/19 10:20	Reinspection Photo		☒
67	30/11/19 10:20	Reinspection Photo		☒
68	30/11/19 10:20	Reinspection Photo		☒
69	30/11/19 10:20	Reinspection Photo		☒
70	30/11/19 10:20	Reinspection Photo		☒
71	30/11/19 10:20	Reinspection Photo		☒
72	30/11/19 10:20	Reinspection Photo		☒
73	30/11/19 10:20	Reinspection Photo		☒
74	30/11/19 10:20	Reinspection Photo		☒
75	30/11/19 10:20	Reinspection Photo		☒
76	30/11/19 10:20	Reinspection Photo		☒
77	30/11/19 10:20	Reinspection Photo		☒
78	30/11/19 10:20	Reinspection Photo		☒
79	30/11/19 10:20	Reinspection Photo		☒
80	30/11/19 10:20	Reinspection Photo		☒
81	30/11/19 10:20	Reinspection Photo		☒
82	30/11/19 10:20	Reinspection Photo		☒
83	30/11/19 10:20	Reinspection Photo		☒
84	30/11/19 10:20	Reinspection Photo		☒
85	30/11/19 10:20	Reinspection Photo		☒
86	30/11/19 10:20	Reinspection Photo		☒
87	30/11/19 10:20	Reinspection Photo		☒
88	30/11/19 10:21	Reinspection Photo		☒
89	30/11/19 10:21	Reinspection Photo		☒
90	30/11/19 10:21	Reinspection Photo		☒
91	30/11/19 10:21	Reinspection Photo		☒
92	30/11/19 10:21	Reinspection Photo		☒
93	30/11/19 10:21	Reinspection Photo		☒
94	30/11/19 10:21	Reinspection Photo		☒
95	30/11/19 10:21	Reinspection Photo		☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	30/11/19 10:21	Reinspection Photo		Load JPG	☒
97	30/11/19 10:21	Reinspection Photo		Load JPG	☒
98	30/11/19 10:21	Reinspection Photo		Load JPG	☒
99	30/11/19 10:21	Reinspection Photo		Load JPG	☒
100	30/11/19 10:21	Reinspection Photo		Load JPG	☒
101	30/11/19 10:21	Reinspection Photo		Load JPG	☒
102	30/11/19 10:21	Reinspection Photo		Load JPG	☒
103	30/11/19 10:21	Reinspection Photo		Load JPG	☒
104	30/11/19 10:21	Reinspection Photo		Load JPG	☒
105	30/11/19 10:21	Reinspection Photo		Load JPG	☒
106	30/11/19 10:21	Reinspection Photo		Load JPG	☒
107	30/11/19 10:21	Reinspection Photo		Load JPG	☒
108	30/11/19 10:21	Reinspection Photo		Load JPG	☒
109	30/11/19 10:21	Reinspection Photo		Load JPG	☒
110	30/11/19 10:24	Reinspection Photo		Load JPG	☒
111	30/11/19 10:24	Reinspection Photo		Load JPG	☒
112	30/11/19 10:24	Reinspection Photo		Load JPG	☒
113	30/11/19 10:24	Reinspection Photo		Load JPG	☒
114	30/11/19 10:24	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/19 12:02	TP GIA REPORT		Load PDF	
2	14/12/19 12:14	LETTER TO OI		Load PDF	
3	16/01/20 10:40	TP ESTIMATE-MARKED		Load PDF	
4	30/01/20 16:59	RENTAL RECEIPT		Load PDF	
5	30/01/20 16:59	GIA SEARCH		Load PDF	
6	30/01/20 16:59	LOD		Load PDF	
7	10/02/20 14:41	EMAIL TO TP		Load PDF	
8	11/02/20 14:53	WORKSHOP INVOICE		Load PDF	
9	11/02/20 14:53	AUTHORISATION TO ACT FORM		Load PDF	
10	11/02/20 14:53	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/12/19 16:20	OI GIA REPORT		Load PDF	
2	27/12/19 16:12	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKL8804B (Insd veh)	Model:	TOYOTA HARRIER 2.0 G
	SJQ8181A (TP veh)		GRADE (A)
Date of Accident:	28/11/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	26,786.23
Final Repair Cost	:	\$	7,757.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	540.00 3 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,299.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable; Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 8,299.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

11 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021125/UHA3Q2

Date: 11/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100359757
 Claimant: SJK8181A Insured Vehicle No: SKL8804B
 Vehicle No: SJK8181A Date of Loss: 28/11/2019 Nature of Claim: TP Claim No: 0842170265SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK8181A
 Make & Model: TOYOTA HARRIER, 2.0 G GRADE (A) Engine No: 8ARZ124233
 Reg. Date: 19/06/2018 (Man. Year: 2018) Chassis No: JTEKB3GH00J002210
 Colour: Black Odometer: 40749 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R18 Rear Tyre Size: 235/35 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,853.86	6,971.94	12,881.92	64.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	2,100.00	3,080.00	59.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,033.86	9,071.94	15,961.92	63.76
Approved Total (Overridden) (S\$)		7,250.00		
(S\$)	25,033.86	7,250.00	17,783.86	71.04
+ GST 7.00/7.00% (S\$)	1,752.37	507.50	1,244.87	71.04
Nett Amount (S\$)	26,786.23	7,757.50	19,028.73	71.04
+ Car Rental (3.0 x S\$180.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,299.50		

INSPECTION

Date of Assignment: 29/11/2019
 Date Inspected: 29/11/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Necessary	297.54 F	*113.10 FL
2	1	*TAILGATE REAR LOGO	Necessary	68.10 F	*68.10 FL
3	1	*TAILGATE	Badly Dented	1,712.35 F	*1,712.05 FL
4	1	*TAILGATE HARRIER EMBLEM	Necessary	91.60 F	*68.10 FL
5	1	*TAILGATE TURBO EMBLEM	Necessary	60.00 F	*60.00 FL
6	2	*TAILGATE REFLECTORS	Not Necessary	783.20 F	*- FL
7	1	*TAILGATE WEATHERSTRIP	Twisted	341.66 F	*341.66 FL
8	1	*TAILGATE INNER LOCK	Shorted	459.10 F	*459.10 FL
9	1	*TAILGATE INNER TRIM BOARD	Deformed / Torn	460.32 F	*460.32 FL
10	2	*TAILGATE DAMPERS	Not Necessary	1,160.20 F	*- FL
11	1	*REAR BUMPER DIFUSSER	Distorted	455.00 F	*455.00 FL
12	1	*REAR BUMPER	Distorted	955.10 F	*955.10 FL
13	1	*REAR BUMPER SPONGE	Torn	145.00 F	*145.00 FL
14	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	136.20 F	*- FL
15	1	*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
16	1	*REAR BUMPER SUPPORT BAR	Bent	1,195.00 F	*1,195.00 FL
17	2	*REAR BUMPER SUPPORT BAR BRACKETS	Serviceable	330.00 F	*- FL
18	2	*REAR BUMPER SIDE HOLDERS	Not Necessary	151.00 F	*- FL
19	1	*REAR END PANEL	Dented	831.60 F	*803.10 FL
20	1	*REAR END PANEL TOP GARNISH	Twisted	360.89 F	*360.89 FL
21	2	*TAILLAMPS	Cracked	1,082.20 F	*1,082.20 FL
22	1	*REAR FLOOR PANEL TOP BOARD	Not Necessary	820.10 F	*- FL
23	1	*REAR FLOOR PANEL	Repair	1,166.50 F	*- FL
24	2	*REAR FENDERS	Repair	2,042.20 F	*- FL
25	2	*REAR FENDER INNER TRIM BOARDS	Not Necessary	1,290.40 F	*- FL
26	1	*REAR EXHAUST	Not Necessary	1,185.00 F	*- FL
27	4	*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	1,444.40 F	*722.20 FL
28	1	*REAR SMART KEYLESS ANTENNA	Not Necessary	199.20 F	*- FL
29	1	*REAR BUMPER REFLECTORS	N/S Cracked	250.00 F	*125.00 FL
30	1	*SET REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS
31	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
33	1	*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 19,853.86 9,265.92
 - List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 2,293.98

Total Parts (\$\$) 19,853.86 6,971.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	120.00	60.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
8	TO TRANSFER TAILGATE MECHANISM	New	120.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,200.00	680.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (S\$)			5,180.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >