,		LKK Auto C provide the Repairer of the Tollow  To result on the policy spra	ving: y painting	Not Authorises
*		To dispers described part(s) during resurvey     Personal enablect to confirmation		29/11/19
FASTECH AL	UTO PTE LTD	* FALL IT BY II mudification(s) is al	thout Prejudice" basis	1/25 7 150
BLK1 KAKI BUKIT AVE 6		<ul> <li>S mulamentary item(s) must l</li> </ul>	S mulamentary item(s) must be resurveyed and	
#01-46,48,50		to subject to final approval from	m Insurance Company	1 San.
			1.00	
SINGAPORE 417883		Acknowledged by Repairer Signature:		
VEHICLE NO: SJQ 8181A		Date:		
QTY	PARTICULAR			
1 PCS	REAR WINDSCREEN	MOULDING 1/3-10		M \$297.54
1 PCS	TAILGATE REAR LO			nu \$68.10
1 PCS	TAILGATE	1712.05		BohpO \$1,712.35
1 PCS	TAILGATE 'HARRIEF			29 591.60
PCS	TAILGATE 'TURBO' I			per \$60.00
2 PCS	TAILGATE REFLECT			1 1 \$783.20 X
PCS	TAILGATE WEATHERSTRIP			1w/ \$341.66 -
PCS	TAILGATE INNER LOCK			Shell \$459.10
PCS	TAILGATE INNER TRIM BOARD			Delton \$460.32
2 PCS	TAILGATE DAMPERS @\$580.10			11 \$1,160.20 X
PCS	REAR BUMPER DIFU			7.5 \$455.00
PCS	REAR BUMPER			71 \$955.10
PCS	REAR BUMPER SPO	NGE		1000 \$145.00
PCS		E RETAINERS @\$68.10		11 \$136.20 ℃
SET	REAR BUMPER CLIF			\$50.00
PCS	REAR BUMPER SUP			Sul \$1,195.00
PCS		PORT BAR BRACKETS @\$165.0	0	8cm \$330.00 X
PCS		HOLDERS @\$75.50		17 \$151.00 X
PCS	REAR END PANEL	803.10		\$831.60
PCS	REAR END PANEL T			Tul \$360.89
PCS	TAILLAMPS @\$541.1	10		CA \$1,082.20
PCS	REAR FLOOR PANE			4 1 \$820.10 X
PCS	REAR FLOOR PANE	L		↑ \$1,166.50 €
PCS	REAR FENDERS @\$	1021.10		\$2,042.20
PCS	REAR FENDER INNE	R TRIM BOARDS @\$645.20		17 \$1,290.40
PCS	REAR EXHAUST		1000	1 4 04 405 00 1
PCS	REAR BUMPER PDC	SENSORS @\$361.10	(250	Should \$1,444.40 200
PCS	REAR SMART KEYLE	ESS ANTENNE		√/3 \$199.20 × √/3 \$250.00 ₽C
PCS	REAR BUMPER REF	LECTORS @\$125.00		N/SC12 \$250.00 PC
			9,76.9	\$19,226.32
	S.NETT		9,75.9	3./.
SET	REAR FLOOR PANEL	INSULATOR	6881.	74 11 \$180.00 X
PCS	REAR WINDSCREEN	SEALANT		Nu \$50.00 40
PCS	REAR END PANEL S	EALANT		050.00
1 PCS	REAR LICENCE PLA	TE W/HOLDER		\$50.00 X
	LABOUR CHARGES			2
	TO CHECK WIRING			\$80.00 33
	TO DISMANTLE & REPLACING PDC SENSOR			\$80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN			\$150.00 / 26
		FIX REAR EXHAUST		17 \$100.00 X
	TO DISMANTLE & RE	FIX CUSHION UPHOLSTREY		\$150.00 & C
	TO SPRAY RUST PROOFING			\$120.00 60
	TO MOUNT VEHICLE ON CAR O-LINER			1 1 \$380.00 ×
	TO TRANSFER TAILGATE MECHANISM			\$120.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS		5	\$2,200.00 680

TO PUTTY & SPRAY PAINTING		\$1,800.00 /000
	TOTAL	\$24,736.32

9071.94