

1814-24 PIP (LKK)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 28.11.2019
Time: 17:17:59
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305357820
REGN NO : SHA4645M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 22.12.2016
DATE/TIME IN : 28.11.2019 15:10
ACCIDENT DATE : 27.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	553.00	20.00	442.40	20.00 110.60 cr
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	20.00 2.00 cr
0003	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	scr
0004	04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00	50.00	2.00 48.00 cr
0005	04-01-0103-0739-G	I40VC ABSORBER-RR BUMPER	1	103.50	20.00	82.80	?

SUB-TOTAL : 775.20

JOB NATURE

0000	PB	PANEL BEATING		300.00		\$240	
0001	SP	SPRAYPAINT CHARGE		200.00		\$	
0002	17-01	CHECK ALL LIGHTING		50.00		\$20	
0003	20-05	RENEW ADVERTISEMENT BUMPER STICKER				50.00	rec
0004	20-05	RENEW ADVERTISEMENT FENDER STICKER-				200.00	rec
0005	L	REMOVE/REFIX REVERSE SENSOR				80.00	\$30

Ram (LKK)
29/11/19
2 repair days
8/p
Ref paint photo
Parasuram@lkkauto.com
6862277814

