

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Authorized
HKK
2/12/19
4/5 65501
SDH

List Item:

1 PCS	REAR WINDSCREEN MOULDING	
1 PCS	TAILGATE	953
1 PCS	TAILGATE OUTER HANDLE GARNISH	
1 PCS	TAILGATE 'H' LOGO	
2 PCS	TAILGATE REFLECTORS @\$280	
1 PCS	TAILGATE 'VEZEL' EMBLEM	
1 PCS	TAILGATE INNER LOCK	
1 PCS	TAILGATE LOCK STRIKER	
1 PCS	TAILGATE INNER TRIM BOARD	
1 SET	TAILGATE INNER TRIM BOARD CLIPS	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE KEYLESS SENSOR	
1 PCS	REAR BUMPER CENTRE	
2 PCS	REAR BUMPER SIDES @\$235.10	
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20	
2 PCS	REAR BUMPER SCREW SPACERS @\$12	
2 PCS	REAR BUMPER REFLECTORS @\$151.20	
2 PCS	TAILLAMPS @\$460.60	
2 PCS	TAILLAMP HOUSING PANELS @\$195	
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR BUMPER LOWER DIFFUSER	
1 SET	REAR BUMPER LOWER DIFFUSER CLIPS	
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS @\$45	
1 PCS	REAR EXHAUST HEAT SHIELD	
2 PCS	REAR FENDER INNER TRIMS @\$295.30	
1 SET	REAR FENDER INNER TRIM CLIPS	
2 PCS	REAR FENDER OUTER GARNISH @\$195.80	
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL TOOLS SPONGE	
2 PCS	REAR FENDERS @\$1100	

List Item Total:

rec	\$	121.30	—
bad 500	\$	1,100.90	—
117	\$	285.30	X
117	\$	35.80	X
o/s scr	\$	560.00	12C
rec	\$	56.20	—
twi/shwls	\$	198.50	—
117	\$	25.50	X
de/cne	\$	321.70	—
rec	\$	50.00	—
twi	\$	135.70	—
cne	\$	180.00	—
de	\$	762.70	—
scr	\$	470.20	X
117	\$	70.40	X
117	\$	24.00	X
117	\$	302.40	X
scr/cne	\$	921.20	—
rec	\$	390.00	X
body 20	\$	514.00	—
twi	\$	125.00	—
de/twi	\$	348.20	—
rec	\$	50.00	—
m	\$	899.20	X
117	\$	90.00	X
117	\$	98.30	X
de/twi	\$	590.60	—
117	\$	50.00	X
twi	\$	391.60	—
rec	\$	912.30	X
twi	\$	685.00	—
R	\$	2,200.00	X
	\$	12,966.00	

20%

6684.7
5347.76

Special Nett Item:

1 SET	REAR BUMPER REVERSER SENSOR	
1 PCS	REAR REVERSE CAMERA	
1 PCS	REAR WINDSCREEN SEALANT	
1 PCS	REAR END PANEL SEALANT	
1 PCS	REAR FLOOR PANEL INSULATOPR	

Special Nett Total:

shwld	\$	280.00	200
shwld	\$	500.00	380
rec	\$	50.00	40
rec	\$	50.00	—
117	\$	180.00	X
	\$	1,060.00	

Labour Charge:

TO CHECK WIRING

\$ 80.00 30

TO DISMANTLE & REPLACE REVERSE SENSOR	\$	80.00	50
TO TRANSFER TAILGATE MECHANISM	\$	100.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	\$	150.00	120
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$	150.00	80
TO DISMANTLE & REPLACE REAR EXHAUST	11 \$	100.00	X
TO SPRAY RUST PROOFING	\$	150.00	60
TO MOUNT VEHICLE ON CAR O-LINER	11 \$	380.00	X
TO DISMANTLE & REFIX PETROL TANK	11 \$	100.00	X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	\$	2,000.00	800
TO PUTTY & SPRAY PAINTING	\$	2,000.00	1000
Labour Charge Total:	\$	5,290.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 19,316.00

8217.76
6574

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: