

AIG INSURNACE

Vehicle number	SJT7667G
Make / Model	MITSUBISHI LANCER
Chassis number	JMYSRCY2AAU000358
Accident date	29/11/19
Reference	1911-40

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	702.60 <i>de</i>
1	REAR BUMPER BEAM	114.00 <i>bb</i>
1	REAR BUMPER TOW COVER	85.00 <i>ms</i>
2	REAR BUMPER SIDE RETAINER	232.80 <i>LH-X, RH-de</i>
2	REAR BUMPER REFLECTOR	207.00 <i>LH-X, RH-?</i>
1	REAR BUMPER REINFORCEMENT	270.00 <i>bb</i>
1	REAR END PANEL	769.60 <i>?</i>
1	REAR END PANEL TOP GARNISH	316.80 <i>?</i>
2	BOOTLID LAMP	680.00 <i>X</i>
2	BOOTLID HINGE	187.20 <i>Rp</i>
1	BOOTLID WEATHERSTRIP	186.00 <i>?</i>
1	BOOTLID LOCK	78.00 <i>bb</i>
1	BOOTLID LOCK STRIKER	30.00 <i>Rp</i>
1	BOOTLID INNER TRIM	201.60 <i>X</i>
1	REAR RH FENDER	939.60 <i>Rp</i>
1	SPARE TYRE TOP BOARD	512.60 <i>X</i>
2	TAILLAMP	1164.00 <i>LH-X, RH-?</i>
	<i>Bootlid X R.</i>	
		6676.80
	Less 10 %	667.68
	Subtotal	6009.12
	Balance C/F	6009.12
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR NUMBER PLATE BASE	80.00 <i>45 cm</i>
1	REAR NUMBER PLATE	80.00 <i>?</i>
1 SET	REAR BUMPER CLIP	40.00 <i>30 cm</i>
1 SET	REAR REVERSE SENSOR	600.00 <i>200, 140</i>
2	REAR BUMPER LIP	500.00 <i>LH-X, RH-?</i>
1	BOOTLID (CARBON FIBRE)	2000.00 <i>X nn</i>
1	JOINT SEALANT	150.00 <i>?</i>
	Subtotal	3290.00
	Balance C/F	9299.12

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	9299.12
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	120.00 50
3	REMOVE AND RENEW REAR REVERSE SENSOR	120.00 30
4	REMOVE AND STRAIGHTEN REAR EXHAUST	120.00 60-put?
5	PANEL BEATING ON AFFECTED AREAS	1200.00 70
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00 70
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	2770.00
	Grand total	12069.12

Tanpin 9749544
 'WP'
 Ampsun 02/12/19 @ 3pm
 Resurvey after repair
 Tanpin @ Ampsun
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: