

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **Axa Insurance Singapore Pte Ltd**
8 Shenton Way, #24-01
AXA Tower, 068811

Attn : Motor Claims Department
Tel : 68804888
Fax : 68804740

Estimate billl : TT 80 / 19 / TP / WT

Registration No : GBJ1255Z

Make model : Toyota Dyna Lorry

Mileage :

Date : 29 / 11 / 2019

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YK8083D AND GBJ1255Z ALONG
12 FISHERY PORT ROAD ON 28 NOVEMBER 2019 AT ABOUT 1434 HRS.**

2pcs	Windshield spray nozzler	(Each \$48.00)	\$	DD	96.00	7
2pcs	Front wiper arm	(Each \$165.00)	\$	MSD	330.00	24
1pc	Front wiper arm garnish		\$	B	360.00	✓
1pc	Front LH side mirror stand with built in both glass		\$	nd	450.00	✓
1pc	Front LH side mirror stand motor		\$	JM	750.00	7
	Sub A total :		\$		1,986.00	
	Less 20% discount :		\$		397.20	
	A total :		\$		1,588.80	

Remove and refit windshield spray nozzler, front wiper arm, front wiper arm garnish,
front LH side mirror stand with built in both glass, front LH side mirror stand motor.

\$ 2001 500.00

Heat /weld / beating / pull / straighten / align front chassis frame by Chassis Aligment
jack.

\$ 301 150.00

Tuff kote front damaged portion.

\$ 2001 250.00

Putty / primer application, spray painting on front wiper arm garnish

\$ 2,488.80

Grand final amount :

Not Withheld
Resurvey Blgains
2 days

Tropical Tech Automobile Services



(Authorised Signature)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: