

ASSIGNMENT

Surveyor:

ADRIAN

DOI: 29.11.2019

Date / Time: 29.11.2019

Registered in Merimen: 02.12.2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SGU 8379L

Claim No. : 1448956286SG

Name of Insured : TEO PENG BOON

Policy No. : 1900095643

Insured Tel No. : HP: +65-90067213

Make / Model : TOYOTA VIOS

Excess Sec II :SS D.O.A : 27.11.2019

Place of Accident : ECP (AIRPORT TOWARDS CITY)
BEFORE LAMP POST 568

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLR 1046A

INSRS:
WSP: SUCCESS
Tel : UNITED
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SLR 1046A - X	SGU 8379L - X	STAGE	DATE / PIC
8/1/2020 Khondra	sent e-mail to AIG - request to reject TP claim		Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
27/2/2020 Khondra	File passed to close + reject claim + survey done		Documentation Check List: Handler Typist	
			Notification ltr (if non-pickup)	
			After call ltr to OI:	
			Authorisation To Act:	
			Release Voucher:	
			Final Repair Bill:	
			Car Rental Invoice:	
			Towing Invoice:	
			LTA / GIA :	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction:	☒
			LOD	
			Payment Breakdown Form:	
			Post-Repair Photos:	
			Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	45	SS 3,600	(5 days) Reduction: 47 %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOIA S/N No.:	NIL
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS	(\$ x days)	
Loss of Income (LOI):	SS	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search:	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost:	SS		
Total:	SS	Global Sum \$S:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
28/1/2020

ASSIGNMENT

SLR1046A. 2017 July.

UO / TP / WS / TP RES / OO RES / EVA / MV / MV

To insured Vehicle No

Vehicle No

at

Insured

Policy No

Claim No

Sum Insured

Excess

(Client's Record)

Make of Vehicle

(Policy Condition)

Remark: The vsh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs 5 days Res Yes or No

Lith Sub: 20 % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Power Mower /

Truck / Trailer

Make: Mit Lancer 1590

Color: Grey A/C Insured / Std / Nil / NA

Sp Reading 39694. T/Plate Insured / Std / Nil / NA

Eng No

C/Nr: JmYSRCY1AG4007215

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt

Brake: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt

Mod: Nil / ☒ S/Rim / ☐ STD AirRim

Tyre Size F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO /

Front

Rear

R/Bal 06 mm R/Bal 06 mm

L/Bal 06 mm L/Bal 06 mm

D.O.A. D.O.I. 29/11/19.

Survey held at: Sucan United

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP ALG.

CLIS \$3,600 (Red \$3,148.50 / 47%)

MV:

PV:

Nett:

Case/Date: The First of

☐ : Prel. Report

Days Of Repair:

II

☐ : Final Report

Resurvey No. of Trip:

Case/Date: The First of

Advt Fee: ☐ See Inv 15

☐ Interim 5

☐ Final 10

☐ Other 10

Survey Fee:

Transportation

- P/L

Survey Fee

Transportation

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-161

Date : 28/11/2019

Vehicle Num. : SLR1046A

Make/Model : Mitsubishi Lancer-2017

Chassis/Eng# : JMYSRCY1AGU007215/4A92CP9648

Accident Date : 27/11/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

NETT ITEMS				
1.	1 pc	Bonnet <i>Painted</i> ✓	809	809 ✓
2.	1 pc	Bonnet Mechanism Lock <i>Painted</i> ✓	98	98 ✓
3.	2 pcs	Frt Headlamp Assy L/R <i>RH Painted, LH New</i>	698	1396 ✓
4.	2 pcs	Frt Headlamp Retainer L/R <i>DM</i>	26	52 ✓
5.	1 pc	Frt Bumper Assy <i>Painted</i> ✓	737	737 ✓
6.	2 pcs	Frt Bumper Side Holder L/R <i>Painted</i> ✓	44	88 ✓
7.	1 pc	Frt Lower Air Grille <i>Painted</i> ✓	141	141 ✓
8.	1 pc	Frt Bumper Reinforcement <i>Painted</i> ✓	326	326 ✓
9.	1 pc	Frt Grille Assy <i>Painted</i> ✓	247	247 ✓
10.	1 pc	Frt Grille Chrome Trim <i>Painted</i> ✓	169	169 ✓
11.	1 pc	Frt Tow Hook Cover <i>Painted</i> ✓	24	24 ✓
12.	1 pc	Frt Grille Mitsubishi Logo <i>New</i> ✓	30	30 ✓
13.	1 pc	Frt No. Plate Garnish <i>Painted</i> ✓	75	75 ✓
14.	1 pc	Aircon Condenser <i>New</i>	1023	1023 X
Nett Total S\$:			3484	3484
10.00% Discount S\$:			348.40	348.40

SPECIAL NETT ITEMS :				
1.	1 set	Frt No. Plate w/frame <i>Painted</i>	45	45.00 ✓
Special Nett Total S\$:				45.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				60.00 30
To remove, instal aircon parts, vacuum, refill gas.				150.00 120
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				900.00 600

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-161

Date : 28/11/2019

Vehicle Num. : SLR1046A

Make/Model : Mitsubishi Lancer-2017

Chassis/Eng# : JMYSRCY1AGU007215/4A92CP9648

Accident Date : 27/11/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

To putty and respray painting on affected area.

Labour Total S\$:

1350

600

900.00

2,010.00

(P+L+S+N) : Total 6,748.50



Adrian L

2/s 29/11/19.

050000.

total: 453860

4/s 36K

Total S\$: 2,055.00

SUCCESS UNITED PTE LTD

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

176H

Vehicle Details

Vehicle No.:

SLR1046A

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Nov 2019

Vehicle Make:

MITSUBISHI

Vehicle Model:

LANCER EX 1.6 AT LED TAIL LAMP

Primary Colour:

Grey

Manufacturing Year:

2017

Engine No.:

4A92CP9648

Chassis No.:

JMYSRCY1AGU007215

Maximum Power Output:

86.0 kW (115 bhp)

Open Market Value:

\$10,826.00

Original Registration Date:

31 Jul 2017

First Registration Date:

31 Jul 2017

Transfer Count:

1

Actual ARF Paid:

\$10,826.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

30 Jul 2027

PARF Rebate Amount:

\$8,119.00

Intended COE Rebate Details

COE Expiry Date:

30 Jul 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,789.00

COE Rebate Amount:

\$38,965.00

Total Rebate Amount:

\$47,084.00

The information contained herein is correct as at 28 Nov 2019

OK

Khanchna (LKK Auto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Wednesday, 8 January 2020 11:28 AM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: Seeking instructions to reject - AIG REF: TP / 1448956286SG-003 [Accident between SLR 1046A & SGU 8379L [AIG] on 27/11/2019]

Hi Khanchna

Per your email below, please proceed to reject TP claim.

Thanks.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: Wednesday, January 08, 2020 9:20 AM
To: Tan, Bennie-WZ
Cc: Admin A
Subject: [EXTERNAL] Seeking instructions to reject - AIG REF: TP / 1448956286SG [Accident between SLR 1046A & SGU 8379L [AIG] on 27/11/2019]


This message is from an external sender; be cautious with links and attachments.

Dear Mr. Bennie,

We refer to the above matter.

Based on all documents at hand and damage profile, we noted that the third party vehicle had head to rear end our Insured vehicle.

We append below our Insured's vehicle photo and statement for your easy reference:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was travelling along ECP (Airport toward City) direction with my wife and son. When I notice that front vehicle stopped so I follow and come to a complete stop. Suddenly, the vehicle (B) unable to stop in time and collided into my vehicle (A).



As such, we are of the view that liability is down against third party.

We seek your instructions to reject Third party's claim based on the reasons above.

Your approval please.

Thank you.

"Wishing you a happy and a prosperous New Year!"

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
 DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 15 January 2020 4:04 PM
To: sirina@successunited.com.sg
Cc: Admin A
Subject: Reject TP claim - Accident between SLR 1046A & SGU 8379L [AIG] on 27/11/2019

WITHOUT PREJUDICE


Dear Sir/Madam,

We refer to the above matter.

Based on all documents at hand and damage profile, we noted that the third party vehicle had head to rear end our Insured vehicle.

We append below our Insured's statement for your easy reference:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was travelling along ECP (Airport toward City) direction with my wife and son. When I notice that front vehicle stopped so I follow and come to a complete stop. Suddenly, the vehicle (B) unable to stop in time and collided into my vehicle (A).

As such, we opine that liability is down against your client and we have our principal's instruction to reject the claim and we are unable to look into your client's claim.

We will close file accordingly.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Wishing you a Happy and Prosperous Lunar New Year"



Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2019 Edit Reg		29 Nov 2019 00:00 Edit Adj Rpt	S\$3,600.00 Edit Estimates	S\$3,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TEO PENG BOON , ID: -									
Main Claimant: CHOO SOON HIN ETHAN , ID: S8115176H									
Vehicle Reg. No.: SLR1046A		Date of Loss: 27/11/2019 23:00 - :59 [27 Months and 27 Days From LTA Reg. Date (Man Yr)]							
Claim Type: TP / 1448956286SG		Policy/Cover Note No.: 1900095643 (Comprehensive)							
Vehicle Reg. No. (Insured): SGU8379L		Policy No. (Claimant): 10837751							
		Excess:							
Repairer: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel: 6746 1515									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Claimant's Insurer: Aviva Ltd (HQ) - Tel: (65) 6827 9966									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (03/12/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR1046A (1448956286SG)
[SGU8379L]
TP
CHOO SOON HIN ETHAN
Nov 27 2019 11:25PM
[TEO PENG BOON]
Success United Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	08/01/20 09:05	General View													Load JPG	☒		
2	08/01/20 09:05	General View													Load JPG	☒		
3	08/01/20 09:05	General View													Load JPG	☒		
4	08/01/20 09:05	General View													Load JPG	☒		
5	08/01/20 09:05	General View													Load JPG	☒		
6	08/01/20 09:05	General View													Load JPG	☒		
7	08/01/20 09:05	General View													Load JPG	☒		
8	08/01/20 09:05	General View													Load JPG	☒		
9	08/01/20 09:05	General View													Load JPG	☒		
10	08/01/20 09:05	General View													Load JPG	☒		
11	08/01/20 09:05	General View													Load JPG	☒		
12	08/01/20 09:05	General View													Load JPG	☒		
13	08/01/20 09:05	General View													Load JPG	☒		
14	08/01/20 09:05	General View													Load JPG	☒		
15	08/01/20 09:05	General View													Load JPG	☒		
16	08/01/20 09:05	General View													Load JPG	☒		
17	08/01/20 09:05	General View													Load JPG	☒		
18	08/01/20 09:05	General View													Load JPG	☒		
19	08/01/20 09:05	General View													Load JPG	☒		
20	08/01/20 09:05	General View													Load JPG	☒		
21	08/01/20 09:05	General View													Load JPG	☒		
22	08/01/20 09:05	General View													Load JPG	☒		
23	08/01/20 09:05	General View													Load JPG	☒		
24	08/01/20 09:05	General View													Load JPG	☒		
25	08/01/20 09:05	General View													Load JPG	☒		
26	08/01/20 09:05	General View													Load JPG	☒		
27	08/01/20 09:05	General View													Load JPG	☒		
28	08/01/20 09:05	General View													Load JPG	☒		
29	08/01/20 09:05	General View													Load JPG	☒		
30	08/01/20 09:05	General View													Load JPG	☒		
31	08/01/20 09:05	General View													Load JPG	☒		
32	08/01/20 09:05	General View													Load JPG	☒		
Documentation															1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	05/12/19 11:37	TP GIA REPORT													Load PDF	☒		
2	15/01/20 16:05	EMAIL FROM AIG TO REJECT TP CLAIM													Load PDF	☒		
3	15/01/20 16:05	EMAIL TO TP WORKSHOP -REJECT TP CLAIM													Load PDF	☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print		
1	03/12/19 15:32	OI GIA REPORT													Load PDF	☒		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	--------------------------------------	-------------------------------------	--------------------------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021235/AKA3Q2

Date: 03/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900095643
Claimant SLR1046A **Insured Vehicle No :** SGU8379L
Vehicle No : SLR1046A **Nature of Claim:** TP **Claim No:** 1448956286SG
Date of Loss: 27/11/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR1046A**
 Make & Model: MITSUBISHI LANCER, 1.6 1.6AT LED (M) Engine No: 4A92CP9648
 Reg. Date: 31/07/2017 (Man. Year: 2017) Chassis No: JMYSRCY1AGU007215
 Colour: Grey Odometer: 39694 km
 Engine Capacity: 1590 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,738.50	3,189.60	1,548.90	32.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,350.00	660.00	32.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,748.50	4,539.60	2,208.90	32.73
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	6,748.50	3,600.00	3,148.50	46.65
+ GST 7.00/7.00% (S\$)	472.40	252.00	220.40	46.66
Nett Amount (S\$)	7,220.90	3,852.00	3,368.90	46.65
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 29/11/2019
 Date Inspected: 29/11/2019 Inspected At: Success United Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
 AutoHub
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Deformed	809.00 FN	*809.00 FN
2	1		*BONNET MECHANISM LOCK	Damaged	98.00 FN	*98.00 FN
3	1		*FRT HEADLAMP ASSY L/R	O/S Cracked / N/SNot Necessary	1,396.00 FN	*698.00 FN
4	2		*FRT HEADLAMP RETAINER L/R	Damaged	52.00 FN	*52.00 FN
5	1		*FRT BUMPER ASSY	Distorted	737.00 FN	*737.00 FN
6	2		*FRT BUMPER SIDE HOLDER L/R	Necessary	88.00 FN	*88.00 FN
7	1		*FRT LOWER AIR GUIDE	Cracked	141.00 FN	*141.00 FN
8	1		*FRT BUMPER REINFORCEMENT	Bent	326.00 FN	*326.00 FN
9	1		*FRT GRILLE ASSY	Cracked	247.00 FN	*247.00 FN
10	1		*FRT GRILLE CHROME TRIM	Cracked	169.00 FN	*169.00 FN
11	1		*FRT TOW HOOK COVER	Deformed	24.00 FN	*24.00 FN
12	1		*FRT GRILLE MITSUBISHI LOGO	Necessary	30.00 FN	*30.00 FN
13	1		*FRT NO .PLATE GARNISH	Distorted	75.00 FN	*75.00 FN
14	1		*AIRCON CONDENSER	Not Necessary	1,023.00 FN	*- FN
15	1		*SET FRT NO.PLATE W/FRAME	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	5,260.00	3,539.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	521.50	349.40
Total Parts (S\$)	4,738.50	3,189.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	60.00	30.00
2	TO REMOVE,REINSTAL AIRCON PARTS ,VACUM ,REFILL GAS	New	150.00	120.00
3	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	900.00	600.00
4	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	900.00	600.00
Gross Labour Cost (S\$)			2,010.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >