

REF: AIG (C3) AIG 19121258/A13

ASS. REC. BY:

mmmm

ASSIGNMENT

From: _____ Date: 2/12/2019
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMT 8120C
 at Workshop m/s: Premium
 of: 55 Ubi Road 1
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 7BA \$600
 (Client's Record)
 Make of Veh: 3:00pm

Veh No: SMT 8120C Yr Regn: 2019 March
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A3 SB c.c. 999
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 7584 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZ8VSKA044586
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/40R18
 R: 225/40R18

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 115K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 wks days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 02/12/19
 Survey held at Premium
 Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD A/G</u>
	<u>SMT 8120C - x</u>
<u>3/12 @ 11:12am</u>	<u>Revert via merimen.</u>
<u>5/12 @ 11:39</u>	<u>Approval by Lim Kok Chong</u>
<u>5/12 @ 1:50pm</u>	<u>Inform premium authorize repair</u>
	<u>Finalize PIP \$4398.08 @ 3days (Red: 1045492; 70%)</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 8/5 Typast
 Date/Time, File Return to? _____
 2) _____
 Report Format: OD
 Lump Sum / 4398.08

Days Of Repair: 3
 Resurvey No. of Trip: _____

Add Fee: Site Insp (\$) _____
 Interview (\$) _____
 Tech. Invs (\$) _____
 Weekend (\$) _____

Survey Fee:	
Transportation:	
3 + PS, SI	
Photos	
Others	
TOTAL	

Dr/Final Bill uploaded

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, 29 November 2019 11:52 AM
To: 'Admin A'; 'Admin-D (LKKAuto)'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SMJ 8120 C ON 28/11/2019
Attachments: SMJ 8120 C - 28112019.PDF

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Kindly arrange survey on 2/12/2019, 3.30pm.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 5 December 2019 1:56 PM
To: Claims; Admin A; Admin-D (LKKAuto); SUR
Subject: RE: OD CLAIM FOR SMJ 8120 C ON 28/11/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SMJ 8120C (Excess \$TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 5 December 2019 9:25 AM
To: Claims <claims@premiumauto.com.sg>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SMJ 8120 C ON 28/11/2019

Dear Sir,

Driving license and NIRC

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Saturday, 30 November 2019 1:11 PM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

View Received Message

This mail is associated with :

***SMJ8120C (8633822092SG)**

OD

Nov 28 2019 1:00PM

[LEONG POK YIM]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **05/12/2019 11:39 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11482.00) - SMJ8120C - Claim Handler: Lim, Sheng Yang

Approved:11482.00:Please resurvey checked / hidden, supplementary items if require and upload in Merimen.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	775A
Vehicle Details	
Vehicle No.:	SMJ8120C
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Dec 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CHZC26507
Chassis No.:	WAUZZZ8V5KA044586
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$21,568.00
Original Registration Date:	21 Mar 2019
First Registration Date:	21 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$22,196.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2029
PARF Rebate Amount:	\$16,647.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,659.00
COE Rebate Amount:	\$24,781.00
Total Rebate Amount:	\$41,428.00

The information contained herein is correct as at 03 Dec 2019

OK

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 03 Dec 2019

Preliminary Advice

Vehicle No	: SMJ8120C	Accident Date	: 28/11/2019
Make	: AUDI A3	Policy No.	:
Assignment Date	: 03/12/2019	Excess	: S\$0.00
Date of Inspection	: 02/12/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,853.00
Revised Amount	:S\$	4,611.00
Check Items (Estimated)	:S\$	6,871.00
Total	:S\$	11,482.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	41,428.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,572.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21128

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1416/2019/NS
Date : 30-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Leong Pok Yim
Address : 250 Tembeling Road
#02-08
Singapore 423728
Telephone : (HP) +65 90900319
Type of Claim : Own Damage Claims
Policy No. : 1900072664
Vehicle No : **SMJ 8120 C**
Model Code : Audi A3 SB 1.0 TFSI S Tronic
Model / Year : 21/3/2019
Engine No : CHZ C26507
Chassis No : WAUZZZ8V5KA044586
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Nov-19
Place of Accident : 80 Playfair Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMJ 812

S/n	Nature of Jobs	S/N	\$	Es	C
				0.0	3.0
				0.0	1.0
				0.0	7.0
					3.0
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	1,358.4+	10.0
				216.0+	=
				1,040.8+	59.0
				5.12+	
				9.76+	0.0
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$	126.0+	352.0
				40.0+	359.0
				=	=
				2,796.08*	611.0
3	To respray front bumper, rhs front fender and bonnet.		\$	0.0	0.0
4	To carry out diagnostic check.	S/N	\$	1,552.0-	0.0
				50.0+	0.0
				550.0+	=
				=	170.0
				1,602.0*	35.0
				0.0	146.0
				0.0	270.0
				0.0	270.0
				1,602.0+	174.0
				1,860.08+	158.0
				=	52.0
				3,462.08*	5,029.0
				0.0	128.0
				0.0	239.0
				0.0	200.0
				1,602.0+	=
				2,796.08+	6,871.0
				=	
				4,393.08*	0.0
					0.0

14
t

U.C

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMJ 8120 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Reccomendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 500 ✓	✓
3	To respray front bumper, rhs front fender and bonnet. ✓	\$ 2,800.00 500 ✓	✓ 550
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 8120 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Delud</i>	\$ 1,698.00	✓ 1358.40
2	FRONT BUMPER FIXING PARTS <i>Not nec</i>	\$ 170.00	? X
3	FRONT BUMPER GUIDE SECTION - RH <i>Not nec</i>	\$ 35.00	? X
4	FRONT BUMPER GRILLE - CENTRE <i>Not nec</i>	\$ 146.00	? X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not nec</i>	\$ 270.00	? X
6	FRONT BUMPER CLOSING ELEMENT - RH <i>Not nec</i>	\$ 270.00	? 216
7	RADIATOR GRILLE <i>cut</i>	\$ 1,301.00	✓ 1040.80
8	RADIATOR GRILLE CLOSING ELEMENT <i>Not nec</i>	\$ 174.00	? X
9	AIRCON STICKER <i>2</i>	NEC \$ 7.00	✓ 5.12
10	CAUTION SIGN STICKER <i>7</i>	NEC \$ 13.00	✓ 9.76
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not nec</i>	\$ 171.00	+
12	FRONT WHEEL HOUSING LINER - RH <i>Not nec</i>	\$ 158.00	? 126
13	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not nec</i>	\$ 52.00	? X
14	LED HEADLIGHT - RH <i>Not nec</i>	\$ 5,029.00	? X
15	LEIFT CYLINDER - RH <i>Not nec</i>	\$ 128.00	? X
16	NOISE INSULATION <i>Not nec</i>	\$ 239.00	? X
17	FRONT NO PLATE <i>Not nec</i>	S/N \$ 40.00	✓ 40
18	SUNDRIES <i>Not nec</i>	\$ 200.00	? X
TOTAL SPARE PARTS		\$ 10,101.00	
TOTAL LABOUR CHARGES		\$ 4,752.00	
GRAND TOTAL		\$ 14,853.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Li*
Surveyed Date : *02/12/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 03 Days.*

- LKK Auto Consultants hence notify the Repairer of the following.
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

A

Material List for Accident Vehicle Regn No. SMJ 8120 C

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>delud</i>	\$	1,698.00	✓
2	FRONT BUMPER FIXING PARTS ?	\$	170.00	?
3	FRONT BUMPER GUIDE SECTION - RH ?	\$	35.00	?
4	FRONT BUMPER GRILLE - CENTRE ?	\$	146.00	?
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>2/11 ✓</i>	\$	270.00	?
6	FRONT BUMPER CLOSING ELEMENT - RH ?	\$	270.00	?
7	RADIATOR GRILLE <i>cut</i>	\$	1,301.00	✓
8	RADIATOR GRILLE CLOSING ELEMENT ?	\$	174.00	?
9	AIRCON STICKER <i>2/11</i>	NEC \$	7.00	✓
10	CAUTION SIGN STICKER	NEC \$	13.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>not on</i>	\$	171.00	+
12	FRONT WHEEL HOUSING LINER - RH ? <i>2/11 ✓</i>	\$	158.00	?
13	WHEEL HOUSING LINER ATTACHMENT PARTS ? <i>12/12</i>	\$	52.00	?
14	LED HEADLIGHT - RH ?	\$	5,029.00	?
15	LEIFT CYLINDER - RH ?	\$	128.00	?
16	NOISE INSULATION ?	\$	239.00	?
17	FRONT NO PLATE <i>new</i>	S/N \$	40.00	✓
18	SUNDRIES ?	\$	200.00	?
TOTAL SPARE PARTS		:	\$ 10,101.00	
TOTAL LABOUR CHARGES			\$ 4,752.00	
GRAND TOTAL			\$ 14,853.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21128

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1416/2019/NS
Date : 30-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,

3 days - ok - Jy - 05 Feb 2020

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Leong Pok Yim
Address : 250 Tembeling Road
#02-08
Singapore 423728
Telephone : (HP) +65 90900319
Type of Claim : Own Damage Claims
Policy No. : 1900072664
Vehicle No : **SMJ 8120 C**
Model Code : Audi A3 SB 1.0 TFSI S Tronic
Model / Year : 21/03/2019
Engine No : CHZ C26507
Chassis No : WAUZZZ8V5KA044586
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Nov-19
Place of Accident : 80 Playfair Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMJ 8120 C

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's teccomendations</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash manadement components Reinstall all	\$	1,400.00	\$ 500.00
3	To respray front bumper, rhs front fender and bonnet.	\$	2,800.00	\$ 550.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,752.00	\$ 1,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 8120 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,698.00	\$ 1,358.40
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 35.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 270.00	\$ 216.00
6	FRONT BUMPER CLOSING ELEMENT - RH	\$ 270.00	
7	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
8	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	
9	AIRCON STICKER	NEC \$ 7.00	\$ 5.12
10	CAUTION SIGN STICKER	NEC \$ 13.00	\$ 9.76
11	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 171.00	
12	FRONT WHEEL HOUSING LINER - RH	\$ 158.00	\$ 126.00
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 52.00	
14	LED HEADLIGHT - RH	\$ 5,029.00	
15	LEIFT CYLINDER - RH	\$ 128.00	
16	NOISE INSULATION	\$ 239.00	
17	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00
18	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS		\$ 10,101.00	\$ 2,796.08
TOTAL LABOUR CHARGES		\$ 4,752.00	\$ 1,602.00
GRAND TOTAL		\$ 14,853.00	\$ 4,398.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.