

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793] . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YP2812E191030

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Date: 02-12-19

Address Motor Claims Department

Vehicle No: YP2812E

8 Shenton Way #27-01

Model/Make: Mitsubishi Fuso

AXA Tower

Singapore 068811

FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Panel <i>Body</i>	\$ 3,263.20	
2	Panel "FUSO" Mark <i>rec</i>	\$ 280.10	
3	Panel "Corporate" Sticker <i>rec</i>	\$ 400.00	
4	Grille <i>one</i>	\$ 978.10	
5	Grille "Mitsubishi" Motif <i>one</i>	\$ 272.10	
6	Grille "Fighter" Emblem <i>one</i>	\$ 155.30	
7	Wiper Washer Tank <i>de</i>	\$ 326.60	
8	Wiper Motor <i>one</i>	\$ 1,179.60	
9	Wiper Linkage Lh <i>one</i>	\$ 1,257.70	
10	Lock Catch Lh <i>one</i>	\$ 114.40	
	To check all wiring & electrical component for proper function	\$ 50.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	
	To putty & spray painting & including touch up paint on accident affected	\$ 680.00	
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 9,507.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

*not authorized**3/12/19**4/5 4100**4000*

M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*9-5475.8**252**9-4106.9**S.N-280.0**1-750.0**5136*