

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 4 December 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : JRQ 5443

Honda AFS

ACCIDENT DATE: 22 November 2019

	<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1	Handle Bar HH	1	185.00 X
front 2	Left Side Signal broken	1	75.00 ✓
3	Handle Cover HH	1	78.00 X
4	Front Side Left Fairing rep	1	185.00 X
5	Front Footrest Bar Left 1/2	1	105.00 ✓
6	Left Side Mirror broken	1	80.00 ✓
7	Front Fork HH	1 set	480.00 X
8	Front Rim cut / dustbin	1	320.00 ✓
9	Pillion Footrest Left broken	1	80.00 ✓
10	Pillion Footrest Bracket broken H/S	1 set	135.00 ✓ 67.50
11	Pillion Handle Bar cut	1	95.00 ✓
12	Left Side Fairing rep	1	80.00 X
13	Rear Mudguard cut / 1/2	1	185.00 ✓
14	Front Disc HH	1	230.00 X
15	Side Signal HH	1	150.00 X
16	Exhaust Cover HH	1	180.00 X
17	Balancer Left cut	1	75.00 ✓
18	Rear Left Signal Lamp broken	1	85.00 ✓
19	Front Head Lamp Cover cut	1	135.00 ✓
	Sub-Total		2,938.00
	Less 10%		293.80
	Sub-Total		2,644.20

VEHICLE NO : JRQ 5443

Honda AFS

Nett Items

- | | | |
|---|--|--------------|
| 1 | Rear number plate | 15.00 ✓ |
| 2 | Towing fee | 60.00 X |
| 3 | Remove & replace new parts, align & etc | 350.00 180/- |
| 4 | Remove & replace fork assy, brake disc & rim | 150.00 ✓ |
| 5 | Replace body new sticker and spray painting | 80.00 ✓ |

Sub-Total 655.00

Nett Total 3,299.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

1447.25
L/S 1150/-

S9 MOTOR TRADING PTE LTD

:LG

03/12/19 @ 1200hrs
H/A Andrew
L/S 3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

yan
LKK Auto