

WANG Peter
6880 4393

CC4/ASM19021327/Uga3

LKK:
IDAC: 149889

ASSIGNMENT

Surveyor:

MARCUS

DOI: 03/12/2019

Date/Time: 03.12.2019

Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : SGW 2911D
 Name of Insured : KUAN CHEOW FUI
 Insured Tel No. : _____ HP: +65-97695115
 Excess Sec II :SS _____ D.O.A : 29.11.2019
 Is driver the owner? (YES / NO) _____ Nature of Accident : _____

Claim No. : S9M02807
 Policy No. : GA503463
 Make / Model : BMW 520I-2.0 (A)
 Place of Accident : UBI AVENUE 1

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SJL 2392Z



INSRS:
WSP: LEE BRO
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/Time	STAGE	DATE / PIC
14/12/2019	SJL 2392Z - X	
	SGW 2911D - CS/AVI09014626/Rfg1, DOA: 27.06.09	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA :	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS 6000.00	(7 days) Reduction:	SS 4.52 % 51
FINAL SETTLEMENT Date/Time: 14/12/2019		Confirm with: Adeime	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost:	SS 6490.00		
Loss of Rental (LOR):	SS 700.00	(7 days) x	\$100
Loss of Use (LOU):	SS -	(5 x days)	
Loss of Income (LOI):	SS -	(5 x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	(Tick only one)	
GIA/LTA Search	SS 76.45		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 7196.45	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS 7196.45	Name 1:	Lee Brothers Automotive Pte Ltd
Payee 2: (Strike if N.A.)	SS -	Name 2:	
Payee 3: (Strike if N.A.)	SS -	Name 3:	

X GIA

(08/11/13) wef

ASS. REC. BY: *7/11/13*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJL 23922

Yr Regn:

11108

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda Stream

c.c

1799

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

25-5904

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRN6880PS 200.208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45-217

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

R/Bal.

mm

Rear

6

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

3/14/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10L 19-11-2012

L/S \$6000 (Red- \$6174.52 / 517.7)

MV: \$28,800

Rebate: \$10,714

NV: \$16,086.

7 repair days + 1 PRS + 1 sat + 1 sun = 10 days.

Date/Time. File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time. File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) \$ + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SGW2911D

Not Aired
nlu
2/5 #6000/?
7 day
Zhang & Huang
12/18

ESTIMATE

DATE : 02.12.2019

VEHICLE NO : SJL2392Z

MAKE/MODEL : HONDA STREAM

ACC DATE : 29.11.2019

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
NETT ITEMS			
1	1 REAR WINDSCREEN MOULDING neu ✓	102.60	102.60 ✓
2	1 REAR TAILGATE 3-300 ✓	1,373.20	1,373.20 ✓
3	2 REAR TAILGATE HINGE RH/LH 11 X	48.80	97.60 X
4	2 REAR TAILGATE DAMPER RH/LH 11 X	146.70	293.40 X
5	1 REAR TAILGATE RUBBER 121 ✓	210.40	210.40 ✓
6	1 REAR TAILGATE LOCK 10/500 ✓	285.90	285.90 ✓
7	1 REAR TAILGATE LOCK CATCH 11 X	26.70	26.70 X
8	1 REAR TAILGATE INNER HANDLE 121 ✓	43.60	43.60 ✓
9	1 REAR TAILGATE INNER TRIM De/Torn	456.30	456.30 ✓
10	1 REAR TAILGATE EMBLEM H 11 X	65.40	65.40 X
11	1 REAR TAILGATE EMBLEM STREAM neu ✓	68.50	68.50 ✓
12	1 REAR TAILGATE EMBLEM RSZ nec ✓	64.20	64.20 ✓
13	2 REAR TAILLAMP RH/LH 12/500 1pc	404.30	808.60 1pc
14	1 REAR BUMPER D.S ✓	1,105.60	1,105.60 ✓
15	1 REAR BUMPER TOW COVER 121 ✓	58.20	58.20 ✓
16	2 REAR BUMPER BRACKET RH/LH 11 X	35.20	70.40 X
17	2 REAR BUMPER SIDE RETAINER RH/LH 12/500 1pc	68.40	136.80 1pc
18	1 REAR SPARE TYRE CARRIER 811	356.10	356.10 X
19	1 REAR SPARE TYRE CARRIER BOLT 11 X	42.10	42.10 X
20	1 REAR END PANEL 3-300 ✓	387.80	387.80 ✓
21	1 REAR END PANEL INNER MEMBER 3-300 ✓	285.90	285.90 ✓
22	1 REAR END PANEL GARNISH 121 ✓	367.80	367.80 ✓
23	1 REAR FLOOR PANEL 121 ✓	1,237.50	1,237.50 ✓
24	2 REAR FLOOR PANEL CARDBOARD RH/LH 11 X	281.50	563.00 X
25	2 REAR FENDER INNER TRIM RH/LH De/Torn 404.40 2-100-100	645.90	1,291.80 ✓
			9,799.40
		LESS 20%	1,959.88
			7,839.52
SPECIAL NETT ITEMS			
1	1 REAR WINDSCREEN SPONGE TAPE neu ✓	20.00	20.00
2	1 (SET) REAR WINDSCREEN SEALANT neu 40	80.00	80.00
3	1 (SET) REAR NUMBER PLATE WITH CASING 11 X	50.00	50.00
4	1 (SET) REAR BUMPER REVERSE SENSOR 121 200	450.00	450.00
5	1 (SET) REAR BUMPER CLIPS neu 30	45.00	45.00
6	1 (SET) REAR FLOOR PANEL SOUND INSULATOR neu 100	250.00	250.00
			895.00

30130

460648

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
LABOUR CHARGES :			
1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, REAR FLOOR PANEL AND REPLACE ACCIDENT PARTS	1100	1,500.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1100	1,200.00
3	TO CHECK WIRING	20	30.00
4	TO REMOVE, REFIX REAR WINDSCREEN	✓	120.00
5	TO TRANSFER REAR TAILGATE PARTS	60	100.00
6	TO REMOVE, REFIX CUSHION AND INNER TRIM	80	120.00
7	TO REFIX REAR CAMERA, REVERSE CAMERA AND REPLACE REVERSE SENSOR	50	150.00
8	TO REMOVE, REFIX FUEL TANK	1100	120.00
9	TO TUFF KOTE	80	100.00
			3,440.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 12,174.52

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To duplicate (damaged part/s) during resurvey
- Parts price will be held to confirmation
- This estimate is given on a "Without Prejudice" basis
- No other work (additional/s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

P - 4606-4f
S.N - 380
L - 2610
7606-4f
6284-18

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	389K
Vehicle Details	
Vehicle No.:	SJL2392Z
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L SUNROOF ALLOY WHEEL AT
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	R18A13800200
Chassis No.:	JHMRN68809S200208
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,032.00
Original Registration Date:	20 Nov 2008
First Registration Date:	20 Nov 2008
Transfer Count:	4
Actual ARF Paid:	\$25,032.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$16,061.00
COE Rebate Amount:	\$12,714.00
Total Rebate Amount:	\$12,714.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Dec 2019

OK

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[Forum](#)

Bidded Car Plate Number for sale

Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.

[Home](#) » [Used Cars](#) » [Mayfair Motoring](#) » [Honda Stream 1.8A \(COE till 08/2023\)](#)

Honda Stream 1.8A (COE till 08/2023)

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**MAYFAIR**
MOTORING

Price	\$28,800		
Depreciation ⓘ	\$7,690 /yr	Reg Date	26-Nov-2008 (3yrs 8mths 28days COE left)
Mileage	172,354 km (15.6k /yr)	Manufactured ⓘ	2008
Road Tax ⓘ	\$1,076 /yr	Transmission	Auto
Dereg Value ⓘ	\$13,105 as of today (change)	OMV ⓘ	\$23,116
COE ⓘ	\$17,496	ARF ⓘ	\$23,116
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight ⓘ	1,370 kg	No. of Owners ⓘ	3
Type of Vehicle	MPV		

Features

Reliable 1.8L I-VTEC 16 Valves DOHC Engine, 5 Speed Auto Transmission. SRS Airbags, ABS. View specs of the Honda Stream (2007-2014)

Accessories

Leather Seats, Sport Rims, DVD Player, Reverse Camera, Reverse Sensors, Arm Rest, Solar Film, Remote Key Alarm System.

Description

Kah Motor Model. In Excellent Condition. Best MPV In Its Class. Must View To Appreciate. Loan From 3.18%. High Trade In Possible.

Category

COE Car,

[Compare](#)[Shortlist](#)[Compare](#)[Report Error](#)[More Acti](#)

Seller Information

Mayfair Motoring

58 vehicles for sale. 180 sold in pas

61 Ubi Avenue 2 #05-11/16

Automobile Megamart

Tel: 64792220

[Search cars nearby](#)

	Kenny Toh	9
	Alex E	8
	Winston	8
	David Tan	9

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more

Stream

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼



Home » Used Cars » Direct Owners » Honda Stream 1.8A X (COE till 08/2023)

Honda Stream 1.8A X (COE till 08/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$24,800

Depreciation ⓘ \$6,650 /yr

Reg Date 26-Aug-2008
(3yrs 8mths 22days COE left)

Mileage N.A.

Manufactured ⓘ 2008

Road Tax ⓘ \$1,076 /yr

Transmission Auto

Dereg Value ⓘ \$13,048 as of today (change)

OMV ⓘ \$16,664

COE ⓘ \$17,496

ARF ⓘ \$16,664

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight ⓘ 1,350 kg

No. of Owners ⓘ 2

Type of Vehicle MPV

Features

Stock Condition. View specs of the Honda Stream (2007-2014)

Accessories

Stock Condition.

Description

Lowest In Town \$24800. Wear And Tear Replaced With Receipts.

Category

COE Car, Direct Owner Sale

Status

Available

Resources



Compare

- Free

ket value of your existing car for free. Get started

https://www.sgcarMart.com/used_cars/info.php?ID=870540&DL=1000



Preferred Viewing Area

Shortlist

Compare

Report Error

More Actions

Seller Information

Contact Person(s) Ah Quek

Contact No. 9747737

Enquiry ⓘ Cont

ESSENTIAL TRANSACTION FORM

» Indemnity form » Sales

» Receipt » Hand-

» Ownership Transfer

GET HELP WITH
PAPERWORK

21327/143.



Service Request Details

Claim

S9M02807

Reference

None

Loss Date

November 30, 2019

Report Date

Dec 3, 2019 9:41:00 AM

Request Date

December 3, 2019

Due Date

December 10, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Direct settlement

Sur. Marcus

P. Mr Lee

T: 259p.m 3.12.19

V: 14

E: V

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJL2392Z

MODEL

HONDA STREAM

Service Address

51 Ubi Avenue 1, #01-25, , 408933

Primary Contact/Insured

KUAN CHEOW FUI @ SHANGGUAN CHEOW FUI

NO.10 WOODLEIGH CLOSE, #01-05 BLOSSOMS@WOODLEIGH, 357905, Singapore

97695115

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Lee Brothers Pls request for TP GIA. Liability clear for DS

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/1/2020

Survey Details:

Date of loss	29-Nov-19
Date of appointment	3-Dec-19
Date of survey	3-Dec-19
Location of survey	LEE BROTHERS AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJL 2392Z
Make and Model	HONDA STREAM 1.8L
Date of registration	20-Nov-08
Parf Rebate	
Market Value	\$ 28,800.00
Parf Rebate	\$ 12,714.00
Nett Loss	\$ 16,086.00

Repair details:

Initial Estimate	\$ 12,174.52
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,996.48
Check items (estimate)	\$ -
Labour	\$ 2,610.00
Total	\$ 7,606.48
Lump Sum(if applicable)	\$ 6,000.00

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 C BLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

07 RECOMMEDED REPAIR DAYS + 1 PRS + 1 SAT + 1 SUN = 10 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 6,420.00	W/GST
Loss of use	\$ -	
Loss of rental	\$ 1,800.00	10days x \$180
Loss of income	\$ -	
LTA search fees	\$ 36.45	
Others	\$ -	
Proposed Total	\$ -	
	\$ 8,256.45	

 <MANDATE IA> - S9M028O7 {ACCIDENT INVOLVING
SGW 2911D (OI) & SJL 2392Z (TP) ON 29/11/2019}

Type

 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8256.45 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 31/01/2020

[Reply](#)

LEE BROTHERS AUTOMOTIVE PTE LTD

1 Kaki Bukit Avenue 6, #02-47 Autobay, Singapore 417883

Tel : (65) 6509 5521 Fax : (65) 6509 5523

Email : sales@leebrothers.com.sg

Co. Reg. : 201101880C

GST Reg. No. : 201101880C

TAX INVOICE

9964

Messrs : **AXA INSURANCE PTE LTD**
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Claim No. : LB1219-2749

Acc. Date : 29/11/2019

Veh. No./Model : SJL 2392Z HONDA STREAM

Date : 17/12/2019

QTY	DESCRIPTIONS	AMOUNT
	Repair Cost : Inclusive of supply parts, panel beating, spray painting and labour.	6,000.00
	Sub-total	6,000.00
	Add GST 7%	420.00
	Total Amount	6,420.00

E. & O.E.

* Please make all payments to " Lee Brothers Automotive Pte Ltd "

* All service and repairing are in good order & conditions.



Customer Sign & Chop

Lee Brothers Automotive Pte Ltd

<< Pls proceed DS with below revised quantum

Type

🔗 Question

Message

COR: \$6420.00; LOR: \$700 (\$100/day for private hire, for 7 days); LTA/GIA FEE \$36.45. Total: \$7156.45

Reply

LEE BROTHERS AUTOMOTIVE PTE.LTD

NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY

SINGAPORE 417883

TEL: 6509 5521 FAX: 6509 5523 GST Reg. No. : 201101880C

ATTN:THE MOTOR CLAIMS DEPARTMENT

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

Yrs Ref. : SGW2911D

Our Ref. : LB1219-2749

Date: : 31.12.2019

Accident involving SJL2392Z and SGW2911D on 29.11.2019 at 1050hrs along Ubi Ave 1

We refer to the above matter. We are instructed that above accident was caused solely and completely by the negligence of your insured, as a result of which, our client have suffered loss and expenses.

We are instructed by our client to make a property damages claims as:-

		<u>Amount</u>
1. Cost of repair (Inc GST)	SS	6,420.00
2. Loss of Use (10Days @ SS180PerDay)	SS	1,800.00
3. Towing	SS	-
5. LTA Search fee	SS	7.45
4. E-File Search fee	SS	29.00
Claim Amount	SS	<u>8,256.45</u>

Enclosed are the following documents for your perusal.

☒ Original Final repair Bill	☒ Letter of Authority
☐ Original Survey Report & Invoice	☒ Rental Agreement /Receipt
☐ Original Photographs of [SJL2392Z]	☒ E-File Search Fee/LTA Receipt
☒ GIAS Reports of [SJL2392Z]	☒ Vehicle Registration Card
☒ Certificate of Insurance	☒ Driver's Driving License / Identity Card
☐ Report Of A Traffic Accident	

Your prompt action will be greatly appreciated.

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Yours faithfully,

Lee Brothers Automotive Pte Ltd



sales@leebrothers.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19021327/Uga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER			Date : 26-02-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 2911D	Veh. Inspected	SJL 2392Z	
Policy No.	GA503463	Coverage (\$)	0.00	
Claim No.	S9M02807	Excess (\$)	0.00	
Assign From		Assign Date	03/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMRN68809S200208	Colour	GREY	
Odometer	255904	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/45 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2019	Inspection Date	03/12/2019	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 2392Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING (N)(CONSISTENT)	NECESSARY	102.60	102.60
1	REAR TAILGATE (N)(CONSISTENT)	BADLY DENTED	1,373.20	903.20
2	REAR TAILGATE HINGE RH/LH @\$48.80 (N)(CONSISTENT)	NOT NECESSARY	97.60	-
2	REAR TAILGATE DAMPER LH/RH @\$146.70 (N)(CONSISTENT)	NOT NECESSARY	293.40	-
1	REAR TAILGATE RUBBER (N)(CONSISTENT)	TWISTED	210.40	188.20
1	REAR TAILGATE LOCK (N)(CONSISTENT)	DENTED / SHORTED	285.90	119.80
1	REAR TAILGATE LOCK CATCH (N)(CONSISTENT)	NOT NECESSARY	26.70	-
1	REAR TAILGATE INNER HANDLE (N)(CONSISTENT)	TWISTED	43.60	43.60
1	REAR TAILGATE INNER TRM (N)(CONSISTENT)	DEFORMED / TORN	456.30	456.30
1	REAR TAILGATE EMBLEM H (N)(CONSISTENT)	NOT NECESSARY	65.40	-
1	REAR TAILGATE EMBLEM SYSTEM (N)(CONSISTENT)	NECESSARY	68.50	36.50
1	REAR TAILGATE EMBLEM RSZ (N)(CONSISTENT)	NECESSARY	64.20	48.50
2	REAR TAILLAMP LH/RH @\$404.30 (N)(CONSISTENT)	N/S SCRATCHED	808.60	404.30
1	REAR BUMPER (N)(CONSISTENT)	DISTORTED	1,105.60	678.20
1	REAR BUMPER TOW COVER (N)(CONSISTENT)	TWISTED	58.20	25.00
2	REAR BUMPER BRACKET RH/LH @\$35.20 (N)(CONSISTENT)	NOT NECESSARY	70.40	-
2	REAR BUMPER SIDE RETAINER RH/LH @\$68.40 (N)(CONSISTENT)	N/S BENT	136.80	32.50
1	REAR SPARE TYRE CARRIER (N)(CONSISTENT)	SERVICEABLE	356.10	-
1	REAR SPARE TYRE CARRIER BOLT (N)(CONSISTENT)	NOT NECESSARY	42.10	-
1	REAR END PANEL (N)(CONSISTENT)	BADLY DENTED	387.80	333.10
1	REAR END PANEL INNER MEMBER (N)(CONSISTENT)	BADLY DENTED	285.90	186.40
1	REAR END PANEL GARNISH (N)(CONSISTENT)	TORN	367.80	245.80
1	REAR FLOOR PANEL (N)(CONSISTENT)	CRUMPLED / BUCKLED	1,237.50	1,145.30
2	REAR FLOOR PANEL CARDBOARD RH/LH @\$281.50 (N)(CONSISTENT)	NOT NECESSARY	563.00	-
2	REAR FENDER INNER TRIM LH/RH @\$645.90 (N)(CONSISTENT)	DEFORMED / TORN	1,291.80	808.80

Report Ref No. CC4/ASM19021327/Uga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,959.88	-1,151.62
			7,839.52	4,606.48
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SPONGE TAPE (SN)(CONSISTENT)	NECESSARY	20.00	20.00
1	SET REAR WINDSCREEN SEALANT (SN)(CONSISTENT)	NECESSARY	80.00	40.00
1	SET REAR NUMBER PLATE WITH CASING (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	450.00	200.00
1	SET REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	45.00	30.00
1	SET REAR FLOOR PANEL SOUND INSULATOR (SN) (CONSISTENT)	NECESSARY	250.00	100.00
			895.00	390.00
	LABOUR			
	TO KNOCK OUT DENT ,CUT WELD REAR PANEL ,REAR FLOOR PANEL AND REPLACE ACCIDENT PARTS.		1,500.00	1,100.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		1,200.00	1,100.00
	TO CHECK WIRING .		30.00	20.00
	TO REMOVE,REFIX REAR WINDSCREEN.		120.00	120.00
	TO TRANSFER REAR TAILGATE PARTS.		100.00	60.00
	TO REMOVE,REFIX CUSHION AND INNER TRIM .		120.00	80.00
	TO REFIX REAR CAMERA ,REVERSE CAMERA AND REPLACE REVERSE SENSOR .		150.00	50.00
	TO REMOVE,REFIX FUEL TANK .	NOT NECESSARY	120.00	-
	TO TUFF KOTE.		100.00	80.00
			3,440.00	2,610.00
GRAND TOTAL			12,174.52	7,606.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CC4/ASM19021327/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M02807	Actions	
Reference	CCA/ASM19021227/Uga3q2 	Next Step	Wait for Approve Invoice
Loss Date	30 November 2019	Add Invoice	
Report Date	3 Dec 2019 9:41:50 AM		
Request Date	28 January 2020		
Due Date			
Vendor Name	LIX AUTO CONSULTANTS PTE LTD (TP)		
Type of Loss	Third Party Vehicle Damage		
Services	Direct settlement		

Davidson, M. 1993. *How to Grow a Brain*. New York: Basic Books.

Make	Year
1990	1990
1991	1991
1992	1992
1993	1993
1994	1994
1995	1995
1996	1996
1997	1997
1998	1998
1999	1999
2000	2000
2001	2001
2002	2002
2003	2003
2004	2004
2005	2005
2006	2006
2007	2007
2008	2008
2009	2009
2010	2010
2011	2011
2012	2012
2013	2013
2014	2014
2015	2015
2016	2016
2017	2017
2018	2018
2019	2019
2020	2020
2021	2021
2022	2022
2023	2023
2024	2024
2025	2025
2026	2026
2027	2027
2028	2028
2029	2029
2030	2030
2031	2031
2032	2032
2033	2033
2034	2034
2035	2035
2036	2036
2037	2037
2038	2038
2039	2039
2040	2040
2041	2041
2042	2042
2043	2043
2044	2044
2045	2045
2046	2046
2047	2047
2048	2048
2049	2049
2050	2050
2051	2051
2052	2052
2053	2053
2054	2054
2055	2055
2056	2056
2057	2057
2058	2058
2059	2059
2060	2060
2061	2061
2062	2062
2063	2063
2064	2064
2065	2065
2066	2066
2067	2067
2068	2068
2069	2069
2070	2070
2071	2071
2072	2072
2073	2073
2074	2074
2075	2075
2076	2076
2077	2077
2078	2078
2079	2079
2080	2080
2081	2081
2082	2082
2083	2083
2084	2084
2085	2085
2086	2086
2087	2087
2088	2088
2089	2089
2090	2090
2091	2091
2092	2092
2093	2093
2094	2094
2095	2095
2096	2096
2097	2097
2098	2098
2099	2099
2100	2100
2101	2101
2102	2102
2103	2103
2104	2104
2105	2105
2106	2106
2107	2107
2108	2108
2109	2109
2110	2110
2111	2111
2112	2112
2113	2113
2114	2114
2115	2115
2116	2116
2117	2117
2118	2118
2119	2119
2120	2120
2121	2121
2122	2122
2123	2123
2124	2124
2125	2125
2126	2126
2127	2127
2128	2128
2129	2129
2130	2130
2131	2131
2132	2132
2133	2133
2134	2134
2135	2135
2136	2136
2137	2137
2138	2138
2139	2139
2140	

Model:

Service Address

51 Uhl Avenue 1: #01-25... 408931

Primary Contact/Insured

KUAN CHEOW FUI @ SHANGGUAN CHEOW FUI
NO.10 WOODLEIGH CLOSE, #01-05
BLOSSOM@WOODLEIGH, 337905, Singapore
97695115

Claim Handler

WAVES PAPER

best.western@buck.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type Document Subtype						
Upload Documents						
NAME		TYPE	SUB-TYPE	AUTHOR	DATE UPDATED	
Accident Statement		Reports & Statements		Meinmen		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
LKKAdjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
TP ADDENDUM FORM4.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020
PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020
TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020
MANDATE IA DO 3101 2020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020
LOG AND OTHER DOCUMENT'S.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 January 2020
 LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 December 2019
 GA503463-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Certificate of Insurance	KADRI Maseen	3 December 2019
 GA503463-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Certificate of Insurance	KADRI Maseen	3 December 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PH).png	Letters and Correspondence	Workshop	KADRI Maseen	3 December 2019