

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SGW2911D

ESTIMATE

DATE : 02.12.2019

VEHICLE NO : SJL2392Z

MAKE/MODEL : HONDA STREAM

ACC DATE : 29.11.2019

PARTICULAR	QTY	UNIT PRICE	AMOUNT
		SS	SS

NETT ITEMS			
1	1	REAR WINDSCREEN MOULDING	102.60
2	1	REAR TAILGATE	1,373.20
3	2	REAR TAILGATE HINGE RH/LH	48.80
4	2	REAR TAILGATE DAMPER RH/LH	146.70
5	1	REAR TAILGATE RUBBER	210.40
6	1	REAR TAILGATE LOCK	285.90
7	1	REAR TAILGATE LOCK CATCH	26.70
8	1	REAR TAILGATE INNER HANDLE	43.60
9	1	REAR TAILGATE INNER TRIM	456.30
10	1	REAR TAILGATE EMBLEM H	65.40
11	1	REAR TAILGATE EMBLEM STREAM	68.50
12	1	REAR TAILGATE EMBLEM RSZ	64.20
13	2	REAR TAILLAMP RH/LH	404.30
14	1	REAR BUMPER	1,105.60
15	1	REAR BUMPER TOW COVER	58.20
16	2	REAR BUMPER BRACKET RH/LH	35.20
17	2	REAR BUMPER SIDE RETAINER RH/LH	68.40
18	1	REAR SPARE TYRE CARRIER	356.10
19	1	REAR SPARE TYRE CARRIER BOLT	42.10
20	1	REAR END PANEL	387.80
21	1	REAR END PANEL INNER MEMBER	285.90
22	1	REAR END PANEL GARNISH	367.80
23	1	REAR FLOOR PANEL	1,237.50
24	2	REAR FLOOR PANEL CARDBOARD RH/LH	281.50
25	2	REAR FENDER INNER TRIM RH/LH	645.90
			9,799.40
		LESS 20%	1,959.88
			7,839.52

SPECIAL NETT ITEMS			
1	1	REAR WINDSCREEN SPONGE TAPE	20.00
2	1	(SET) REAR WINDSCREEN SEALANT	80.00
3	1	(SET) REAR NUMBER PLATE WITH CASING	50.00
4	1	(SET) REAR BUMPER REVERSE SENSOR	450.00
5	1	(SET) REAR BUMPER CLIPS	45.00
6	1	(SET) REAR FLOOR PANEL SOUND INSULATOR	250.00
			895.00

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
LABOUR CHARGES :			
1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, REAR FLOOR PANEL AND REPLACE ACCIDENT PARTS	1100	1,500.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1100	1,200.00
3	TO CHECK WIRING	20	30.00
4	TO REMOVE, REFIX REAR WINDSCREEN	1	120.00
5	TO TRANSFER REAR TAILGATE PARTS	60	100.00
6	TO REMOVE, REFIX CUSHION AND INNER TRIM	80	120.00
7	TO REFIX REAR CAMERA, REVERSE CAMERA AND REPLACE REVERSE SENSOR	50	150.00
8	TO REMOVE, REFIX FUEL TANK	120	120.00
9	TO TUFF KOTE	80	100.00
			3,440.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 12,174.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price to be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No third party communication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 4606-4f
S. N - 390
L - 2610
7606-4f
6284-4f