

COMFORTDELGRO ENGINEERING

Asher

Our Job Ref No : 305358424

Date : 5. Dec. 2019

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHA3694C

Date of Accident: 1. Dec. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SKX7594A

2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,442.48

(b) Labour Charges \$1,000.00

Total for Part-By-Part Repair Cost \$3,442.48

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 4 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Guo Qiang

Name : _____

Date : 02/1/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA3694C

DATE: 2. Dec. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 1. Dec. 2019

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover / <i>cut</i>			\$1,052.20
1	Front Bumper Side Bracket - LH <i>R / CFA</i>			\$24.60
1	Front Bumper Top Bracket - LH <i>R NN</i>			\$22.40
10	Front Bumper Clips / <i>MC</i>		\$2.20	\$22.00
1	Front Bumper Grille - LH <i>x NN</i>			\$41.60
1	Headlamp - LH / <i>scr</i>			\$1,388.00
1	Front Fender - LH / <i>MC</i>			\$566.30
SUB TOTAL				\$3,117.10
LESS 20%				\$623.42
DISCOUNTED TOTAL				\$2,493.68
<div> <p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				\$-
Labour Charge				
1	Panel Beating			\$600.00
1	Spray Painting Charge			\$500.00
1	Tuff Kote			\$50.00
1	Wiring Charge			\$50.00
TOTAL LABOUR				\$1,200.00
ESTIMATE TOTAL				\$3,693.68
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

3083.1
3083.1
2442.48
2442.48

560
400
20
20

3442.48

Larry Ng
P/P
new face paint photos
4 Days
03/12/19
Gm Off.