

menimen

ASSIGNMENT

Equip:

Date:

31/12/19

Veh No:

SLU3484.

Yr Regn:

2017 / Nov

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SLU 3484

Make:

Audi A6

C.C.

1798.

at Workshop m/s

premium

Colour:

Silver.

A/C:

Insured / Std / NI / NA

of

55 Ubi Road 1

Sp. Reading

49384.

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

1700076736-02

C/No:

WAU222468HN129401

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

800

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Vehicle In

Modi: Nil / ☒ S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

Tyre Size:

F:

225/55R17.

R:

225/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

1/12/19

D.O.I.

03/12/19.

Survey held at

Premium.

Des. of Damages: ☒ Frt / Rear / O/S / ☒ N/S / ☒ U/C / Rooftop orCA ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/12/19	Recd email from Andy recommend constructive T/L
10/12/19	Recd approved \$124,795 from Andy, repair cost not exceeding \$143,000/2
10/12/19	Informed Kee Siang c/A not exceeding \$143,000/2 ex \$800 by email
13/12/19	Recd email from Kay Eng to hold back repair
13/12/19	Adrian informed repairer hold back repair
16/12/19	@4:29pm Kee Siang said insured don't want to repair the vehicle
6/1/2020	Recd email from ms Sim vehicle recommend Total Loss
6/1/2020	Submit uneconomical T/L -

RECEIVED 07 JAN 2020