

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 108623

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BOOY REPAIRS

REFERENCE : INS/IC/EA/0601/19

DATE : 03-DEC-2019

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BLDG

S(079120)

TEL : 64191891

FAX : 68357416

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : GOH CHONG CHENG

ADDRESS : BLK 75B BEDOK RESERVOIR ROAD

#12-24

S(479260)

TELEPHONE NO : 67887623/96190645

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM

POLICY NO : 2100490767-03

VEHICLE NO : SLH8224J

MODEL CODE : TDWARDZE12EDAY407Z

MODEL/YEAR : NISSAN NOTE 1.2 BASE

ENGINE NO : HR12215546B

CHASSIS NO : JN1TAAE1270972578

MILEAGE : 59498 KM

DATE IN : 03/12/2019

LIABILITY : 0.00

EXCESS CLAUSE : 600.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 03/12/2019

91645 0084 elmer@fanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLH8224J

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RR BUMPER, RH RR FENDER, RENEW RH RR DOOR	980.00	735
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	850.00	600
3 ZZ/003	REMOVE AND TRANSFER RH RR DOOR MECHANISM	80.00	✓
4 ZZ/004	APPLY SEALANT TO RH RR DOOR	100.00	✓
5 ZZ/005	RENEW RH RR WHEEL RIM, TRYE AND BALANCING	15.00	✓
6 ZZ/006	PERFORM WHEEL ALIGNMENT	95.00	✓
TOTAL LABOUR CHARGES		2120.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH8224J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 RH REAR FILLET PROTECTOR <i>cut</i>	70R16-3VADA	12.10	✓	
2 RH RR DOOR FRT SASH TAPE <i>2 me</i>	82B16-3VADA	19.50	✓	
3 RH RR DOOR RR SASH TAPE	82B18-3VADA	25.50	✓	
4 RH RR DOOR <i>Deleted</i>	H210M-3VAMA	919.60	✓	
5 185/65R15 CCS CONTINENTAL TYRE RH RR <i>not me</i>	185/65/R15			120.00 ✗
6 WHEEL RIM REAR RH <i>not me</i>	40300-SH08			350.00 ✗
7 SUNDRIES <i>?</i>	NPN			50.00 20
SUB TOTAL		976.70	0.00	520.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		195.34	0.00	0.00
GRAND TOTAL		781.36	0.00	520.00
OVERALL TOTAL		1301.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLH822AL

TOTAL LABOUR CHARGES	2120.00
TOTAL SPARE PARTS CHARGES	1301.36
GRAND TOTAL	3421.36 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME :

Adrian King

SURVEYED DATE :

05/12/19.

AUTHORIZED DATE :

EXCESS CLAUSE :

600.00

LIABILITY :

0.00

REMARKS :

Not Authorized

06 Days

Excess: TBA.

total: 2426.36.

#

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.