



Not Actual 3 days.
5/12/18
why before

TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS



AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lim Jingyang ADDRESS : Blk 476c Upper Serangoon View #06-532 Singapore 533476 TEL : 98169395		WIP : 15621 EXCESS : DATE: 30-Nov-19	
VEH NO :	SLH8399M	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BM42A8G0347232	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3	DATE REG.:	21-Nov-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB	De ✓	\$ 1,128.60
2	BRACKET CENTER	1	MKD53-50-251	?	\$ 5.40
3	TOWING COVER LHS	1	MBHN1-50-EL1 BB	M.S ✓	\$ 16.50
4	TOWING COVER RHS	1	MBHN1-50-EK1 BB	?	\$ 17.10
5	REFLECTOR LHS	1	MD350-51-5L0E	1 X	\$ 53.00
6	RETAINER CENTER, SENSOR	2	MKD47-67-UC5A62	?	\$ 36.40
7	SENSOR CENTER, ULTRASONIC	2	MKD47-67-UC1 62	?	\$ 407.20
8	TAPE PROTECTOR, SENSOR	3	MG51D-50-EM1A	m ✓	\$ 25.80
9	REAR REINFORCEMENT	1	MB45A-50-260	?	\$ 564.20
10	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	m ✓	\$ 10.80
11	GROMMET, REAR BUMPER	2	M9991-00-501	m ✓	\$ 6.00
12	RIVET, REAR BUMPER	4	MBBM4-50-355	m ✓	\$ 18.00
13	CLIP, REAR BUMPER	2	MGJ21-50-049	m ✓	\$ 6.80
14	FASTENER, REAR BUMPER	4	MB45A-56-146A	m ✓	\$ 12.00
15	GASKET LHS, TAILLAMP	1	MBHN1-51-163	m ✓	\$ 22.00
16	GASKET RHS, TAILLAMP	1	MBHN1-51-153	m ✓	\$ 22.00
TOTAL PARTS					\$ 2,351.80
LESS 10%					\$ 235.18
TOTAL PARTS COST					\$ 2,116.62
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			630 \$ 1,260.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			600 \$ 1,200.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.			✓ NETT \$ 180.00

4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	120	X	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120		\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150		\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	net 20	NETT	\$ 100.00
			TOTAL LABOUR	\$ -	\$ 3,590.00
			TOTAL PARTS	\$ -	\$ 2,116.62
			TOTAL	\$ -	\$ 5,706.62
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
 CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
 WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
 PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

LKk Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Final prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- To the extent possible, no litigation(s) is allowed
- Supply of any item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: