

AAD1911-224

Not Authorized

Resurvey B4 paint

81654.03

SHD 9148H

JTDKB3FU403080643

TOYOTA

PRIUS

27.11.19

NTUC Income V

24/5/2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

03 DEC 2019

PART

- | | | |
|----|---|----------------------------------|
| 1 | 1 | REAR BUMPER |
| 2 | 1 | REAR BUMPER RE-INFORCEMENT |
| 3 | 1 | REAR BUMPER TOWING COVER |
| 4 | 1 | REAR BUMPER UNDER COVER (BLACK) |
| 5 | 1 | REAR BUMPER SIDE RETAINER LH |
| 6 | 1 | REAR BUMPER SIDE RETAINER RH |
| 7 | 1 | REAR TAILGATE |
| 8 | 1 | REAR TAILGATE OUTER GARNISH |
| 9 | 1 | COVER, REAR COMBINATION LAMP, RH |
| 10 | 1 | COVER, REAR COMBINATION LAMP, LH |
| 11 | 1 | GARNISH, BACK DOOR SIDE, LH |
| 12 | 1 | GARNISH, BACK DOOR SIDE, RH |
| 13 | 1 | BOARD ASSY, BACK DOOR TRIM |
| 14 | 1 | REAR TAILGATE WEATHERSTRIP |
| 15 | 1 | PANEL SUB-ASSY, BODY LOWER BACK |
| 16 | 1 | TAILLAMP LOWER RH |
| 17 | 1 | TAILLAMP UPPER RH |
| 18 | 1 | REAR BUMPER SIDE RH |
| 19 | 1 | REAR BUMPER SIDE LH |
| 20 | 1 | TAILLAMP LOWER LH |
| 21 | 1 | TAILLAMP UPPER LH |
| 22 | 1 | BOARD, BACK DOOR TRIM |
| 23 | 1 | COVER, DECK TRIM, REAR |
| 24 | 1 | COVER, FLOOR UNDER, NO 1 |
| 25 | 1 | COVER, FLOOR UNDER, NO 2 |
| 26 | 1 | COVER, REAR FLOOR |

LIST		
\$	mg cm	442.60 ✓
\$	R	332.70 ✓
\$	R	15.40 ✓
\$	cm	576.30 ✓
\$	R	116.50 X
\$	R	117.70 X
\$	R	1,147.80
\$	R	925.60
\$	R	64.50
\$	R	64.50
\$	R	95.60
\$	R	95.60
\$	R	259.20
\$	R	372.30
\$	R	650.30
\$	R	502.00
\$	R	451.80
\$	mg cm	123.70 ✓
\$	R	123.70 X
\$	R	502.00
\$	R	443.30
\$	R	225.20
\$	R	126.70
\$	R	175.10
\$	R	241.90
\$	R	229.90

Trans-cab Auto Services Pte Ltd

AAD1911-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9148H

TOTAL	\$	8,421.90
25%	\$	2,105.48
	\$	6,316.43

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	✓
3	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	} X
4	1	WINDSCREEN MOULDING	\$	nn	100.00	
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
6	1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	
10	1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	
11	1	REAR BUMPER PROTECTOR	\$	nn	100.00	
12	1	REAR WHEEL RIM	\$	Sn	1,570.55	}
13	1	REAR TYRE 195/65/15	\$	Sn	350.00	
14	1	REAR WHEEL RIM COVER	\$	Sn	175.80	
15	1	REAR RH BUMPER RETAINER CLIP	\$	nn	25.00	
16	1	REAR LH BUMPER RETAINER CLIP	\$	nn	25.00	

TOTAL	\$	3,605.75
--------------	-----------	-----------------

TOTAL PARTS	\$	9,922.18
--------------------	-----------	-----------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd**AAD1911-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9148H

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i>	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	<i>2201</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To Check Electrical Lighting Concerned.	\$	<i>nn</i>	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	<i>2001</i>

TOTAL \$ 11,340.00**Over All Total \$ 21,262.18****(PART-BY-PART) Repair Days***15 Days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: