

AXA INSURANCE

Vehicle number	SLV2484R
Make / Model	TOYOTA CHR
Chassis number	ZYX102037772
Accident date	29/11/19
Reference	1911-39

Qty	Particulars	Unit Price - SGD
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	550.82 de ✓
1	REAR BUMPER LOWER GARNISH	428.71 de ✓
2	REAR BUMPER SIDE AIR VENT	158.42 X nn
1	REAR BUMPER CENTRE COVER	58.91 X nn
2	REAR BUMPER REFLECTOR	\$63.27 126.54 LH-CH-RH-X nn
1	REAR BUMPER REINFORCEMENT	268.92 Bt ✓
2	REAR BUMPER RETAINER	\$45.39 90.77 LH-de, RH-X nn
2	REAR BUMPER REFLECTOR GARNISH	\$43.80 87.60 LH-de, RH-X nn
1	TAILGATE	1008.43 X
1	TAILGATE EMBLEM - LOGO	76.88 24 ✓
1	TAILGATE EMBLEM - CHR	61.73 nn ✓
1	TAILGATE EMBLEM - HYBRID TECHNOLOGY	92.16 nn ✓
1	TAILGATE LOCK	408.31 X nn
1	TAILGATE LOCK STRIKER	186.50 X nn
1	REAR END PANEL	\$625.90 708.71 Bt ✓
1	REAR END PANEL TOP GARNISH	264.55 X
1	KEYLESS ANTENA	230.64 X nn
1	REAR WINDSCREEN MOULDING	158.92 X
1	REVERSE SENSOR MODULE	899.72 X
		5867.24
	Less 25%	1466.81
		4400.43
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR BUMPER CLIP	50.00 30 ✓
1 SET	REAR WINDSCREEN SEALANT	120.00 X
1 SET	REAR END PANEL TOP GARNISH CLIP	50.00 X nn
4 PC	REVERSE SENSOR	1229.00 X
	Subtotal	1449.00
	Balance C/F	5849.43
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	5849.43
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30 ✓
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	150.00 X nn
3	TO TRANSFER TAILGATE ATTACHEMENT	200.00 X nn
4	PANEL BEATING ON AFFECTED AREAS	1400.00 600 ✓
5	SPRAY PAINTING ON AFFECTED AREAS	1000.00 500 ✓
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30 ✓
	Subtotal	1660.00
	Grand total	7509.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Tan Jiah
 97495749
 WP
 4/12/19 E 3pm
 5 days
 Sure Accounts.com



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

AXA INSURANCE

Vehicle number	SLV2484R
Make / Model	TOYOTA CHR
Chassis number	ZYX102037772
Accident date	29/11/19
Reference	1911-39

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>	
1	REAR BUMPER LOWER CHROME GARNISH (AFTER MARKET)	250.00 ¹⁵⁰
	Subtotal	250.00