



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautoteltd@gmail.com

Registration No: 201719251W Vendor No: 201719251W

I, the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices to subject to confirmation
 • Third party survey is on a without prejudice basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimate No: ES1900140
 05 Dec 2019

Veh Reg No: SMA4649T
 Make/Model: TOYOTA PRIUS C CVT
 Chassis No: JTDKD3B3901020523
 Engine No: 1NZ6400589
 Reg. Date: 25/09/2012

M/S: India International Insurance Pte Ltd
 64 Cecil Street
 #05-01 IOB Building
 Singapore 049711

ATTN: Motor Claim Department
 Your Ref No: -
 Claim Type: Third Party
 Accident Date: 28/11/2019
 TP Veh Reg No: PC5925T

Estimate Repair Cost to Vehicle No :SMA4649T

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00	60.00
Spare Parts				
2 REAR BUMPER X repair ? / RR	850.90	1 PC	850.90	539.24
3 REAR BUMPER CLIPS X - REC	60.00	1 SET	60.00	30 (SN)
4 REAR BUMPER REINFORCEMENT X repair NN	425.10	1 PC	425.10	
5 REAR BUMPER SIDE BRACKET (TOP) - LH X	85.00	1 PC	85.00	
6 REAR BUMPER SIDE BRACKET (TOP) - RH X	85.00	1 PC	85.00	
7 REAR BUMPER SIDE RETAINER - LH X	75.50	1 PC	75.50	
8 REAR BUMPER SIDE RETAINER - RH X	75.50	1 PC	75.50	
9 REAR END PANEL X repair	560.00	1 PC	560.00	
10 REAR TAILLAMP - RH X	485.50	1 PC	485.50	
11 REVERSE SENSORS X	300.00	1 SET	300.00	
			3,002.50	3,002.50
			Disc 25% = 404.43	
Labour				
12 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	200
13 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00	300
14 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	X NN
	600		1,680.00	1,680.00
			Total	S\$ 4,742.50
			Add GST @ 7%	331.98
			Total Amount Payable	S\$ 5,074.48

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVENTY FOUR AND CENTS FORTY EIGHT ONLY

2 Dims.
 After repair photos.
 Gino Giarf - 82880282
 05/12/19.

For Yee Auto Pte Ltd

AUTHORIZED SIGNATURE