

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-159

Date : 28/11/2019

Vehicle Num. : SMD8992J

Make/Model : Honda Accord-2008

Chassis/Eng# : CL73304640/K20A6055335

Accident Date : 28/11/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Rear Bumper Assy <i>Del'd</i>		1,050.00 ✓
2.	12 pcs	Rear Bumper Clips <i>pc</i>	6.50	78.00 ✓
3.	2 pcs	Rear Bumper Side Holder L/R <i>pc</i>	42.50	85.00 ✓
4.	2 pcs	Rear Bumper Bracket L/R <i>pc</i>	27.60	55.20 ✓
5.	1 pc	Rear End Panel <i>Del'd</i>		550.60 ✓
6.	2 pcs	Rear Bumper Reflector Lamp L/R <i>pc</i>	75.00	150.00 ✓
7.	1 pc	Rear End Panel Inner Top Garnish <i>Del'd</i>		158.60 ✓
8.	2 pcs	Rear Lamp L/R <i>LT cable, RT cable</i>	356.80	713.60 ✓
9.	2 pcs	Rear Boot Lid Lamp L/R <i>RT cable</i>	315.00	630.00 ✓
10.	1 pc	Rear Boot Lid Weatherstrip <i>pc</i>		151.00 ✓
11.	1 pc	Rear Boot Lid Mechanism Lock <i>pc</i>		218.00 ✓
12.	2 pcs	Rear Boot Hinge L/R <i>pc</i>	48.60	97.20 ✓
13.	1 pc	Rear Boot Lid Honda Logo <i>Free</i>		52.40 ✓
14.	1 pc	Rear Boot Lid 'Accord' Emblem <i>Free</i>		54.32 ✓
List TotalS\$:				4,043.92
20.00% Discount S\$:				808.78
				3,235.14
SPECIAL NETT ITEMS :				
1.	1 set	Reverse Sensor <i>2nd.</i>		480.00 ✓
2.	1 set	Rear No. Plate w/frame <i>pc</i>		45.00 ✓
Special Nett Total S\$:				525.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				80.00 ✓
To remove, instal upholstery, inner trim garnishes & spoiler.				400.00 ✓

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-159

Date : 28/11/2019

Vehicle Num. : SMD8992J

Make/Model : Honda Accord-2008

Chassis/Eng# : CL73304640/K20A6055335

Accident Date : 28/11/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		1,200.00 ⁶⁰⁰
		To putty and respray painting on affected area.		1,000.00 ⁶⁰⁰
		Labour Total S\$:		2,680.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 6,440.14

=====

SUCCESS UNITED PTE LTD

total: 3836.01 Adrian Lim
 h/s: 3.11C h/s 02/12/19
 O.S. pays.