



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SMP 3711 Z
JAGUAR XE

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING ✓ <i>nee</i>	1	
2	BOOTLID X ✓	1	
3	BOOTLID LOGO (JAGUAR) X	1	
4	BOOTLID EMBLEM (JAGUAR) X	1	
5	BOOTLID EMBLEM (XE) X	1	
6	BOOTLID EMBLEM (20t) X	1	
7	BOOTLID LAMP (L+R) X	2	
8	BOOTLID HANDLE SWITCH X	1	
9	BOOTLID REVERSE CAMERA X	1	
10	BOOTLID CARPLATE LAMP (L+R) X NC	2	
11	BOOTLID INSULATOR X	1	
12	BOOTLID LOCK X	1	
13	BOOTLID LOCK CATCH X	1	
14	BOOTLID HINGE (L+R) X	2	
15	BOOTLID DAMPER (L+R) X	2	
16	BOOTLID STOPPER (L+R) X	2	
17	BOOTLID WEATHER STRIP X	1	
18	TAIL LAMP (L+R) X	2	
19	TAIL LAMP PANEL (L+R) X ✓	2	
20	REAR BUMPER ✓ <i>cut</i>	1	
21	REAR BUMPER RETAINER (L+R) <i>R/H only</i> ✓ <i>nee</i> 4/4 X SVC	2	
22	REAR BUMPER REINFORCEMENT BAR X SVC	1	
23	REAR BUMPER BRACKET (L+R) X SVC	2	
24	REAR BUMPER CENTER BRACKET X SVC	1	
25	REAR BUMPER BEAM X SVC	1	
26	REAR BUMPR SPONGE X SVC	1	
27	REAR BUMPER REVERSE SENSOR SET X SVC	4	
28	REAR BUMPER REVERSE SENSOR HOLDER SET X SVC	4	
29	REAR BUMPER REVERSE SENSOR CONTROL UNIT X SVC	4	
30	REAR BUMPER LOWER X SVC	1	
31	REAR FENDER (RH) ✓ <i>BT</i>	1	
32	REAR FENDER PETROL COVER (RH) X SVC	1	
33	REAR FENDER INNER PANEL (RH) X (R)	1	
34	REAR FENDER INNER TRIM (RH) X SVC	1	
35	REAR FENDER COWLING (RH) ✓ <i>CRU</i>	1	
36	REAR ABSORBER (RH) X (SVC)	1	
37	REAR LOWER ARM (RH) X (SVC)	1	
38	REAR KNUCKLE (RH) ? <i>-photo</i>	1	
39	REAR KNUCKLE BEARING (RH) ? <i>-photo</i>	1	
40	REAR KNUCKLE BEARING HUB (RH) ? <i>-photo</i>	1	

41	REAR AXLE	X (svc)	1	
			SUBTOTAL	\$ -
			LESS 10%	\$ -
			PARTS TOTAL	\$ -
SPECIAL NETT			QTY	PRICE
1	REAR WINDSCREEN SEALANT	✓ nec	1	\$ 120.00
2	BONNET INSULATOR CLIPS	X (svc)	10	\$ 100.00
3	TAIL LAMP CLIPS	✓ nec	2	\$ 80.00
4	REAR BUMPER CLIPS	✓ nec	10	\$ 100.00
5	REAR FENDER SEALANT	3 ✓ nec	1	\$ 120.00
6	REAR FENDER INNER PANEL SEALANT		1	\$ 120.00
7	REAR FENDER INNER TRIM CLIPS	✓ nec	10	\$ 100.00
8	REAR FENDER COWLING CLIPS	✓ nec	6	\$ 100.00
9	REAR TYRE SET	X (svc)	2	\$ 3,000.00
10	REAR RIM SET	R/H only (scr)	1	\$ 8,000.00
			SPECIAL NETT TOTAL	\$ 11,840.00
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN		1	\$ 3,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		1	\$ 2,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	X	1	\$ 250.00
4	TO RNR REAR WINDSCREEN	✓	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM	X	1	\$ 400.00
6	TO RNR REAR LUGGAGE COMPARTMENT	X	1	\$ 400.00
7	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	X	1	\$ 600.00
8	TO RNR REVERSE SENSOR & CHECK FUNCTION.	✓	1	\$ 250.00
9	TO RNR UNDERCARRIAGE SYSTEM	- photo ?	1	\$ 300.00
10	TO CHECK WHEEL ALIGNMENT	Alignent Report	1	\$ 300.00
11	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	X	1	\$ 150.00
12	TO RNR TYRE AND WHEEL BALANCING	X	1	\$ 300.00
13	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	✓	1	\$ 600.00
14	TO DO WATER LEAK TEST.	✓	1	\$ 100.00
15	TO RNR FUEL TANK TO ASSIST WORK LOAD	✓	1	\$ 250.00
			TOTAL	\$ 9,700.00
			GRAND TOTAL COST	\$ 21,540.00

L/S report
 7 - 8 day
 without pay justice
 Hock ANN@lkk Auto.com
 85311883
 6/12/19
 2:30pm

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: