

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKX 4148A
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1992360/WS

Date: 09 Dec 2019

Policy No: 5109177821

Veh Reg No: SKX4148A

Make/Model: TOYOTA AQUA
HYBRID 1.5G CVT

WS Ref: TP-FC

Claim Type: Third Party

Accident Date: 03/12/2019

TP Veh Reg No: SHA6889M

Chassis No: NHP106449262

Engine No: 1NZ7672857

Reg. Date: 10/12/2015

Estimate Repair Cost to Vehicle No :SKX4148A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT LH SIDE MIRROR	1,212.10	1 PC	1,212.10	✓
2 FRONT LH SIDE MIRROR COVER	85.60	1 PC	85.60	✓
3 FRONT LH FENDER EMBLEM (HYBRID)	92.10	1 PC	92.10	✓
4 FRONT LH DOOR	1,136.07	1 PC	1,136.07	✓
5 FRONT LH DOOR GLASS CHANNEL	159.60	1 PC	159.60	✓
6 FRONT LH DOOR FRAME STICKER	49.60	1 PC	49.60	✓
7 REAR LH DOOR	1,126.10	1 PC	1,126.10	✓
8 REAR LH DOOR FRAME STICKER	48.10	1 PC	48.10	✓
			3,909.27	
		Less 25%	977.32	2,931.95
Labour				
9 REMOVE & REFIX FRT & REAR LH DOORS,TRANSFER DOOR'S ATTACHMENT,FRT LH SIDE MIRROR,KNOCK & REPAIR REAR LH FENDER,FRT LH FENDER & REALIGN THE SAME	700.00	1 LA	700.00	600
10 REMOVE & REFIX FRT & REAR LH DOOR GLASS,CHECK CENTRAL LOCKING & POWER MIRROR	120.00	1 LA	120.00	✓
11 PUTTY & RESPRAY ON FRT LH SIDE MIRROR,FRT & REAR LH DOORS,FRT & REAR LH FENDERS	900.00	1 LA	900.00	700
12 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,780.00	1,780.00
			Total	S\$ 4,711.95
			Add GST @ 7%	329.84
			Total Amount Payable	S\$ 5,041.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE