

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21780

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1438/2019/NS
Date : 5-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Choi Soon Woong
Address : 939 Bukit Timah Road
#03-41
Singapore 589657
Telephone : 96332750
Type of Claim : Own Damage Claims
Policy No. : 1800009645-1
Vehicle No. : **SLW 2825 K**
Model Code : Audi Q5 2.0 TFSI QU
Model / Year : 5/2/2018
Engine No. : DAX 019687
Chassis No. : WAUZZZF0J2053783
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Dec-19
Place of Accident : Cascadia Condo Carpark

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2825 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 750	
3	To respray front bumper, front bumper spoiler, lhs front fender and both front wheel arch trims. ✓ X	\$ 4,000.00 850	550 Bumper Arch 2x200 = 400
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 7,472.00</u>	

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2825 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER 2-pc torn	\$ 2,364.00	X ✓ 1891.20
2	FRONT BUMPER FIXING PARTS	\$ 244.00	X
3	FRONT BUMPER SECURING STRIP - LH	\$ 34.00	X
4	FRONT BUMPER CLOSING ELEMENT - LH	\$ 101.00	X
5	FRONT BUMPER SPOILER	\$ 685.00	X
6	FRONT BUMPER CLOSING ELEMENT	\$ 156.00	X
7	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 519.00	X
8	FRONT BUMPER END CAP - LH	\$ 83.00	X
9	FRONT BUMPER GUIDE SECTION - LH	\$ 34.00	X ✓ 27.12
10	FRONT FENDER - LH	\$ 1,301.00	X
11	FRONT FENDER ATTACHMENT PARTS	\$ 60.00	X
12	FRONT FENDER BRACKET - LH	\$ 16.00	X
13	FRONT FENDER BRACE - LH	\$ 206.00	X
14	FRONT FENDER CLOSURE PANEL - LH	\$ 28.00	X
15	FRONT FENDER COVER PANEL - LH	\$ 36.00	X
16	FRONT WHEEL HOUSING LINER - LH	\$ 246.00	X
17	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 35.00	X
18	FRONT WHEEL SPOILER - LH	\$ 146.00	X
19	FRONT WHEEL COVER - LH / RH	\$ 1,154.00	X ✓ 922.40
20	HEADLIGHT MOUNTING - LH	\$ 107.00	X ✓ 85.60
21	LED HEADLIGHT - LH	\$ 7,227.00	X ✓ 5781.60
22	SUNDRIES	\$ 300.00	X

TOTAL SPARE PARTS
TOTAL LABOUR CHARGES
GRAND TOTAL

: \$ 15,082.00
: \$ 7,472.00
: \$ 22,554.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

damaged
(check with Adrian
on dated 24/04/20)

X NA (checked with
Adrian on dd
27/04/20)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 06/12/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant