

Endorsement

ASS. REC. BY:

REF: CS/AG/119021580/Agf3

n2

Special Instructions:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): WY of AGI Date/Time: 06/12/19 @ 3:49 PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 7536U Insured: SJT 26314

at Workshop n/s MG SOLUTION Tel: 67431373

of No 73 Kaki Bukit Ave 4 #05 KAKI BUKIT Centre - #02-030

Policy No: Claim No: C1204820/JW

Sum Insured: Excess:

Make of Veh: D.O.A. 04/12/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 06/12/19 @ 3:50 PM Person Contacted: Yoke Heng Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJV 7536U - x
	SJT 26314 - x
	US \$1300, 4 days (Fed to 6146.56, 83%)

Adrian

ASSIGNMENT

SJV7526U.

2010 Feb.

Estimated Cost:

Type: ☒ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Heavy Motor /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Insured Vehicle / H

Make: Honda Freed

1497

at Workshop no:

Color: Silver.

A/C: Insured / Std / NI / NA

at:

Sp Reading: 216466.

T/Rails: Insured / Std / NI / NA

Insured:

Engine:

Policy No:

C/Nr: MH R6B38604J090036.

Client No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt

Make of Veh:

Mod: Nil / ☒ S/Rim / ☐ STD A/Rim

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size

F: 185/65R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Bot. or Mark of Value

Front

Rear

IDAC Accident Report: Consistent? Yes or No

R/Bal: 06 mm

R/Bal: 06 mm

GIA / PR Seen: Consistent? Yes or No

L/Bal: 06 mm

L/Bal: 06 mm

Est. Repairs: 4 days Res: Yes or No

D.O.A: D.O.A: 10/12/19.

Sum Sum: % 3 Val: Yes or No

Survey held at: MG Solution.

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / ☒ Rear / ☐ OIS / ☐ N/S / ☐ U/C / ☐ Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: Action / Instruction

TP Budget Direct.

MV: 14.7K $\frac{3}{2} \times 90K$ (Depreciation) + 15K (Min Part) = 1.7K + 13.1K = 14.5K.
PV: 13.4K
Nett: 1.31K.

RECEIVED 30 JAN 2020

Cost/Time, Fee/Task to: ☐ Prel. Report

Days Of Repair: 4

30/1 transfer ☐ Final Report

Resurvey No. of Trip:

Date/Time: File/Photo:

1st Fee: ☐ Site Visit: 15

☐ 1st Survey: 15

☐ 2nd Survey: 15

☐ 3rd Survey: 15

Survey Fee:

Insurance:

1st Fee: 15

2nd Fee: 15

3rd Fee: 15

TP

1300

250

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Friday, 6 December 2019 3:49 PM
To: Admin-D (LKKAuto)
Cc: SUR; Julie Mangubat
Subject: FW: SJV7526U-(PRE-INSPECTION) ; YOUR REF : SJJ2631U -DOA ON 04/12/2019 || C10004820/JM
Attachments: Survey Request.pdf

Hi Team,

We would like to arrange TP PRS for SJV7526U. They have chosen Mr. Adrian Ling to survey the vehicle.

Workshop information:

MG SOLUTION PTE LTD
No 23 Kaki Bukit Avenue 4
AAS Kaki Bukit Centre
#02-03B Singapore 415933
Tel: 6243 1373 | Fax: 6243 1376

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

*This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: MG Solution <mg3solution@gmail.com>

Sent: Friday, 6 December 2019 3:07 PM

To: Claims <claims@budgetdirect.com.sg>

Subject: SJV7526U-(PRE-INSPECTION) ; YOUR REF : SJJ2631U -DOA ON 04/12/2019

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

We prefer our single joint expert as below:

• **ADRIAN LING WAI PING (LKK AUTO CONSULTANTS PTE LTD)**

Thank you.

Best Regards,

Ms Hong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	007D
Vehicle Details	
Vehicle No.:	SJV7526U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED 1.5L E AT
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	L15A73840084
Chassis No.:	MHRGB3860AJ090036
Maximum Power Output:	87.0 kW (116 bhp)
Open Market Value:	\$26,050.00
Original Registration Date:	08 Feb 2010
First Registration Date:	08 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$26,050.00
Intended PARF Rebate Amount	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Feb 2020
PARF Rebate Amount:	\$13,025.00
Intended COE Rebate Amount	
COE Expiry Date:	07 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$319.00
Total Rebate Amount:	\$13,344.00

The information contained herein is correct as at 10 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/12/2019 16:10
Date Of Accident	04/12/2019 18:15
Exact Location Of Accident	JUNC OF DUEARN RD X LINDEN DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV7526U
Insured/Policyholder	
Name Of Registered Owner	SOH HEE YEOW
NRIC No	S1761007D
Email Address	SHY1501@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96161501
Alternative Phone No	OTHERS-96161501

Vehicle Particulars

Manufacturer	HONDA
Model	FREED 1.5L E AT
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105025344
Cover Note Number	

Driver

Name of Driver	SOH HEE YEOW
NRIC No	S1761007D
Date Of Birth	15/01/1966
Occupation	OUTDOOR
Date Of Driving Pass	13/01/1984
Driving Experience	35 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96161501
Fax Number	
Contact Number	OTHERS-96161501
Email Address	SHY1501@YAHOO.COM

Address	BLK 171 #21-32 GANGSA ROAD SINGAPORE 670171
Postcode	670171
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER/DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ2631U
Vehicle Make/Model/Colour	TOYOTA / CAMRY 2.4G A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please read carefully the terms of this accident report to the General Insurance Association of Singapore (GIA).
 2. This form must be completed by the policyholder and/or the authorised driver.
 3. Information provided must be as truthful and accurate as possible. Any intentional misstatements, withholding of material facts may affect insurance companies to invalidate policy liability.
 4. The issue and acceptance of this form by insurance companies is not a submission of policy liability on the part of the insured concerned.
 5. The false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for preserving and making use of the report will for a fee be made available upon application to interested parties.
 7. By the submission of this report to the insurers, the insured accepts the archiving of this report at the records centre subject to the report being made available elsewhere.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports of claims to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as to the external issuer of envelopes/postal packages); and/or
 - (v) complying with regulatory or other supervisory, procedural, handling and/or dealing with my claims and/or the Insurers' ("Regulatory").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' "suppliers" may process my Personal Information to disclose and/or transfer my Personal Information to my Insurers' suppliers for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and necessary investigations relating to the claims;
 - (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iii) administering my claims (including the mailing of correspondence, statements, invoices, reports of claims to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as to the external issuer of envelopes/postal packages); and/or
 - (iv) complying with regulatory or other supervisory, procedural, handling and/or dealing with my claims and/or the Insurers' ("Regulatory").
 - (c) My Insurers, workshop, suppliers, Insurers' suppliers and any other third parties that assist in settling, investigating, handling and/or dealing with my claims, claims, disputes, law enforcement and government agencies as necessary to fulfil for the purposes stated, or
 - (d) to comply with regulatory or other supervisory, procedural, handling and/or dealing with my claims and/or the Insurers' ("Regulatory").

Insured's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

TDAC KANG BUKIT (YAC)
25 Kang Bukit Ave 4 #02-02
Singapore 415633
Tel: 67416887 Fax: 67482305
Email: nyct@tdac.com.sg
Reporting Centre (Kangbukit) 24hrs 365
Name
NAC/PAC/...

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04/12/2019 at about 1810 hrs at Junction of Dunearn Road and Linden Drive. I was travelling on the extreme Right Lane along Dunearn Road and when coming towards the above mentioned junction, my front vehicle slow down and stop due to heavy traffic hence I follow suit. Suddenly I felt a great impact from the Rear and when I alighted, I realised that it was Vehicle (B) who hit onto my Rear Portion of my Vehicle (A) causing damages to my vehicle. I have one passenger inside my vehicle.

(A) SJV 7526 U

(B) SJJ 2631 U

Note: Please note that your insurer may have 14 days time frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check your policy for more information.

DECLARATION

I/We declare the foregoing statements to be a true and correct statement.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (YAG)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416687 Fax: 67492305
Reporting Name: Person's Sign
Name:
Signature:

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AUTO & GENERAL	DATE	: 06/12/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: TP CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJV7526U	Xiao Chen	
MODEL	: HONDA FREED 1.5G A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 4-Dec-19
		TIME	: 18:15HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,460.30	\$ 1,460.30
2	TAIL GATE LOGO <i>Ne</i>	1	\$ 72.30	\$ 72.30
3	TAIL GATE EMBLEM 'FREED' <i>Ne</i>	1	\$ 76.40	\$ 76.40
4	TAIL GATE TOP LOCK <i>Ne on</i>	1	\$ 232.10	\$ 232.10
5	TAIL GATE WEATHERSTRIP <i>Ne on</i>	1	\$ 241.70	\$ 241.70
6	TAIL GATE WINDSCREEN MOULDING <i>Ne</i>	1	\$ 194.20	\$ 194.20
7	REAR BUMPER <i>Dented</i>	1	\$ 630.00	\$ 630.00
8	REAR BUMPER SIDE RETAINER <i>Ne</i>	2	\$ 69.70	\$ 139.40
9	REAR END PANEL (OUTER) <i>Regr</i>	1	\$ 380.00	\$ 380.00
10	REAR END PANEL TOP GARNISH <i>Ne</i>	1	\$ 169.30	\$ 169.30

2227.30

1781.84

TOTAL PRICE \$ 3,595.70

LESS 20% \$ 719.14

SUB TOTAL PRICE \$ 2,876.56

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not Ne</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP(SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
3	TAIL GATE INNER GARNISH CLIP(SET) <i>Ne on</i>	1	\$ 20.00	\$ 20.00

4	TAIL GATE WINDSCREEN INNER SEAL <i>3m</i>	1	\$ 100.00	\$ 100.00	<i>30</i>
5	TAIL GATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	<i>30</i>
6	REAR END PANEL INSULATOR SEAL(OUTER) <i>2</i>	1	\$ 120.00	\$ 120.00	<i>+</i>
7	REAR END PANEL TOP GARNISH CLIPS(SET) <i>M</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
8	REAR FLOOR PANEL INSULATOR SEAL	1	\$ 150.00	\$ 150.00	<i>+</i>
9	REAR REVERSE SENSOR <i>Net Net</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
<i>80</i>			TOTAL	\$ 810.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,400.00	<i>400</i>	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,400.00	<i>400</i>	
3	TO APPLY RUST PROOFING/ UNDER COAT	\$ 250.00	<i>x</i>	
4	WIRING, BULB CHECKING	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR	\$ 250.00	<i>x</i>	
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>	
7	TO TRANSFER TAIL GATE MECHANISM	\$ 80.00	<i>✓</i>	
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>x</i>	
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>x</i>	
TOTAL		\$3,760.00	<i>1030</i>	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,686.56

TOTAL LABOUR COST : \$ 3,760.00

TOTAL REPAIR COST : \$ 7,446.56

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King - total: 28918x
L/S 10/12/19. L/S: 1-31K
048 days. (Net Value)
1-31K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19021580/Aqf3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 30-01-2020	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJJ 2631U	Veh. Inspected	SJV 7526U
Policy No.		Coverage (\$)	0.00
Claim No.	C10004820/JM	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	06/12/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MHRGB3860AJ090036	Colour	SILVER
Odometer	216466	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/12/2019	Inspection Date	10/12/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7526U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	DENTED	1,460.30	1,115.00
1	TAIL GATE LOGO	NECESSARY	72.30	72.30
1	TAIL GATE EMBLEM "FREED"	NECESSARY	76.40	76.40
1	TAIL GATE TOP LOCK	NOT NECESSARY	232.10	-
1	TAIL GATE WEATHERSTRIP	NOT NECESSARY	241.70	-
1	TAIL GATE WINDSCREEN MOULDING	NECESSARY	194.20	194.20
1	REAR BUMPER	DEFORMED	630.00	630.00
2	REAR BUMPER SIDE RETAINER @\$69.70	NECESSARY	139.40	139.40
1	REAR END PANEL (OUTER)	TO REPAIR SEE LABOUR	380.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	169.30	-
	LESS 20% DISCOUNT		-719.14	-445.46
			2,876.56	1,781.84
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET TAIL GATE INNER GARNISH CLIP (SN)	NOT NECESSARY	20.00	-
1	TAIL GATE WINDSCREEN INNER SEAL (SN)	NECESSARY	100.00	30.00
1	TAIL GATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	30.00
1	REAR END PANEL INSULATOR SEAL (OUTER)(SN)	NOT NECESSARY	120.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR FLOOR PANEL INSULATOR SEAL (SN)	NOT NECESSARY	150.00	-
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
			810.00	80.00
LABOUR				
	PANEL BEATING,WELDING,CUTTING,GRAZING ADJUST,KNOCK STRAIGHTEN.INCLUSIVE OF THE REPAIR OF REAR END PANEL (OUTER).		1,400.00	400.00
	TO PUTTY,SPRAY PAINT,POLISH,WAX.		1,400.00	400.00
	TO APPLY RUST PROOFING/UNDER COAT.	NOT NECESSARY	250.00	-
	WIRING,BULB CHECKING.		80.00	30.00
	REMOVE AND REFIX UPHOLSTERY,CUSHION SEAT TO FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	120.00

Report Ref No. CS/AGI19021580/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER TAIL GATE MECHANISM.		80.00	80.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING.	NOT NECESSARY	80.00	-
			3,760.00	1,030.00
GRAND TOTAL			7,446.56	2,891.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS/AGI19021580/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.