

SINOAI ONE OIVIE DEI ENOET ONG

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /2019	91209/0425	LOCATION OF FIRE: Along Ang Mo Kio Ave 6 towards Ang Mo Kio Ave 1 near bus stop number B04 Singapore	
FIRE REPORTED ON:	09 December 2019		
TIME OF CALL: 11:11:	34 hrs		
STATION COVERAGE : Ang Mo	o Kio Fire Station		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine compartment of a Audi car (SLX1805U).			
METHOD OF EXTINGUISHMENT: By SCDF crew using two hose reel jets from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine compartment of the car was damaged. The rear windscreen and exterior paintwork of the car were also damaged. The interior of the car sustained varying degrees of heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES

SUSTAINED

NIL

NIL

REPORT CERTIFIED TRUE AND CORRECT BY:

NIL

EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE

NIL

This is a computer generated Fire Report. No signature is required.