


SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along TPE towards PLE on the right lane of a 2-lanes, expressing. Suddenly near WPNO 21 F30, vehicle ahead of me jammed brake and stopped. Upon seeing, I applied brake accordingly. Due to the front cars suddenly jammed, and left lane was cleared, I turned to the left in order to avoid a head to rear collision. The split second later, vehicle (B) came from the rear and collided onto the rear portion of my vehicle. Upon the impact, my vehicle surged forward and the right front portion of my vehicle hit onto the rear left portion of vehicle (C).

A - SMT 6167D

B - SJR 9687x

C - SKA 7195P

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Rival
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, Goh MG S, Riquel, the owner of vehicle no. SMA 61670

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, NSI Automotive AC

Signed and Acknowledge by:

Riquel
Nric no. and signature of policyholder


Company Stamp

24/6/2019
Date


Accident Photo



Accident Photo




Accident Photo






Accident Photo



Accident Photo







Enquire Vehicle & Owner Information (Vehicle No. SMA6167D As At 24 Jun 2019 / 07:50:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: T140-110836-19

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S8406365G

Owner Name: GOH MIN SI, RIQUEL

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 113

Registered Street Name: PASIR RIS GROVE

Registered Unit No.: # 04 - 35

Registered Building Name: -

Registered Postal Code: 518171

Current Vehicle Details

Vehicle No.: SMA6167D

Make Description/Model: HYUNDAI / ELANTRA AD 1.6 GLS AT (AMS)

Insurance Company Name: AXA INSURANCE PTE LTD



Thank you

Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 04 Dec 2019, 14:04:36.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset IC	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SMA6167D	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	04 Dec 2019 / 14:05:07

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Business) of KK TRANSPORT SERVICES (53330096K)

Date: 02/03/2016

The Following Are The Brief Particulars of :

Name of Business	: KK TRANSPORT SERVICES
Former Name(s) if any	:
Date of Change of Name	:
Registration No.	: 53330096K
Registration Date	: 26/02/2016
Commencement Date	: 29/02/2016
Status of Business	: Live
Status Date	: 26/02/2016
Renewal Date	:
Expiry Date	: 26/02/2019
Renewal via GIRO	: NO
Constitution of Business	: Sole-Proprietor
Principal Place of Business	: 286B TOH GUAN ROAD #03-32 SINGAPORE (602286)
Date of Change of Address	:

Principal Activities

Activities (I)	: PASSENGER LAND TRANSPORT NEC (EG PRIVATE CARS FOR HIRE WITH OPERATOR) (49219)
Description	: 49219
Activities (II)	: PASSENGER LAND TRANSPORT NEC (EG PRIVATE CARS FOR HIRE WITH OPERATOR) (49219)
Description	: 49219

Particulars of Authorised Representative(s)

Name	ID	Nationality	Address	Address Source	Date of Appointment
Existing Sole-Proprietor(s) / Partner(s)					
Name	ID	Nationality/Place of Incorporation/Origin	Address	Address Source	Date of Entry Position

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Business) of KK TRANSPORT SERVICES (53330096K)

Date: 02/03/2016

Existing Sole-Proprietor(s) / Partner(s)

Name	ID	Nationality/Place of incorporation/Origin	Address	Address Source	Date of Entry Position
TAN KOCK KIONG	S1823978G	SINGAPORE CITIZEN	286B TOH GUAN ROAD #03-32 SINGAPORE (602286)	ACRA	26/02/2016 Owner

Withdrawn Partner(s)

Name	ID	Nationality/Place of incorporation/Origin	Address	Address Source	Date of Entry Position	Date of Withdrawal
------	----	--	---------	-------------------	---------------------------	-----------------------

Abbreviation

OSCARS - One Stop change of Address Reporting Service by Immigration & Checkpoint Authority.

PLEASE NOTE THE INFORMATION HEREIN CONTAINED IS EXTRACTED FROM FORMS/TRANSACTIONS FILED WITH THE AUTHORITY

FOR REGISTRAR OF COMPANIES AND BUSINESS NAMES
SINGAPORE

RECEIPT NO. : ACRA160302100031

DATE : 02/03/2016

This is computer generated. Hence no signature required.

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5088532375-02

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SKA7195P**
 Chassis Number : **JTDGG20W405001682**
2. Name of Policyholder : **KK TRANSPORT SERVICES**
3. Effective Date of Insurance : **28 Mar 2019**
4. Expiry Date of Insurance : **27 Mar 2020**
5. Persons or Classes of Persons entitled to drive#
 (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his/her permission.
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
 (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: TAN KOCK KIONG
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : CHESA INSURANCE AGENCIES PTE. LTD. (00000615068)


Date of Issue : 26 Feb 2019 10:00 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

DARWIN-51 CAR RENTAL PTE. LTD.

Company & GST Registration Number : 201407909C
2 Kaki Bukit Avenue 2 #02-12 Kaki Bukit Autohub Singapore 417921
Tel: 6842 5151 Fax: 6749 2851 email: darwin51@n51.com.sg

Invoice To

KK TRANSPORT SERVICES
BLK 286B TOH GUAN ROAD
#03-32
SINGAPORE 602286

TAX INVOICE

Invoice No. : D01280
Date : 03/07/2019
Terms : Cash

No. Days	Description	Rate	Amount
8	SLR9340Y - Car rental fee for period from 26/06/2019 to 03/07/2019 (ref. Vehicle SKA7195P) Tax collected on sales	150.00 7.00%	1,200.00 84.00
7% GST			\$84.00
Total Amount			\$1,284.00

DARWIN-51 CAR RENTAL PTE. LTD.

18
Authorised Signature



Note : Kindly make payable to " DARWIN-51 CAR RENTAL PTE. LTD." or by Bank-in/transfer to Maybank A/c No. 04211099668 (Bank Code 7302)

Invoice was created on a computer and is valid without the signature and seal

DARWIN-51 CAR RENTAL PTE. LTD.

Company Registration Number : 201407909C
2 Kaki Bukit Avenue 2 #02-12 Kaki Bukit Autohub, Singapore 417921
Tel: 6842 5151 Fax: 6749 2851 email: darwin51@n51.com.sg

SKA 7195P
(TC)

VEHICLE RENTAL AGREEMENT

VHA NO: 555

HIRER'S PARTICULAR

Name(as in I/C): KK TRANSPORT SERVICES
NRIC/PASSPORT No: 53330096K
Address(Res): BLK 286B TOH GUAN ROAD #03-32 SINGAPORE 602286
Occupation: Driving Exp:
Driving License No: 53330096K D/L Type: Local
Issue Date: 1985-04-23 Date of Birth: 1967-11-10
Tel: (HP) 65666452
Email:

ADDITIONAL DRIVER'S PARTICULARS

Name(as in I/C): TAN KOCK KIONG
NRIC/PASSPORT No: S1823978G
Address(Res): BLK 286B TOH GUAN ROAD #03-32 SINGAPORE 602286
Occupation: Driving Exp:
Driving License No: S1823978G D/L Type: Local
Issue Date: 1985-04-23 Date of Birth: 1967-11-10

Vehicle No: SLR9340Y

Make: TOYOTA

Model: PRIUS ALPHA

Year: 2017

Mileage Out:

OUT: Date 2019-06-26

NON-WAIVER EXCESS:

Section1: \$2000

Auto/Manual Group: Auto

Colour: BLACK

Time: 11:18

Section2: \$2000

CHARGES

Daily rate 150.00

PETROL-LEVEL

Out E 1/4 1/2 3/4 F E

In E 1/4 1/2 3/4 F E

Extension (Accessories) 0.00

Collection Service 0.00

Misc. 0.00

Security Deposit Collected 0.00

Rental Term Cash

Start Date 2019-06-26

End Date 2019-07-10

Rented out by: Joseph Tan

Hirer signature:

Addition Driver's Signature:




S1823978G
TAN KOCK KIONG 90664988

VEHICLE CHECKLIST

D - DENTS
S - SCRATCHES

INDICATE:
A - ACCIDENTS



RIGHT FRONT TOP LEFT

ACCESSORIES CHECK

- ☒ Camera Recorder
- ☒ Reverse Camera
- ☒ CD/ Radio Player
- ☒ Remote Control
- ☒ Reverse Sensor
- ☐ S/Tyre

I have read and agreed to the terms & conditions on both sides of this agreement. All information I have given DARWIN-51 CAR RENTAL PTE. LTD. in connection with this agreement is true.

IMPORTANT

- YOU HEREBY EXPRESSLY CONSENT AND AUTHORIZE DARWIN-51 CAR RENTAL PTE LTD AND GRABCAR TO DEDUCT FROM THE FARES GENERATED BY YOU AND/OR GRATUITY GRANTED TO YOU BY GRABCAR (IF ANY) FOR THE CAR RENTAL FEE AND ANY CHARGES PROVIDED HEREIN AND IN THE EVENT THAT THE FARES ARE INSUFFICIENT, ANY BALANCE SHALL BE PAID TO US IMMEDIATELY. THESE CHARGES SHALL INCLUDE BUT ARE NOT LIMITED TO CHARGES FOR 1. CAR RENTAL 2. COST OF INSURANCE EXCESS, REPAIRS, REPLACEMENT OF PARTS TO THE CAR AND/OR DAMAGE TO THIRD PARTY PROPERTIES WHERE THE DAMAGES ARE DUE TO YOUR ACTIONS OR LACK OF CARE. 3. ANY UNSETTLED SUMMONS, FINES, PARKING CHARGES AND TOLL.
- THE VEHICLE SHALL BE RENTED OUT ON A DAILY BASIS, WITH A MINIMUM RENTAL PERIOD OF SIX MONTH.
- IN THE EVENT THAT THE HIRER RETURN THE VEHICLE PRIOR TO THE END OF THE MINIMUM RENTAL PERIOD, THE HIRER WILL BE REQUIRED TO PAY THE FULL RENTAL FEE APPLICABLE FOR THE REMAINING PERIOD UP TO THE END OF THE MINIMUM RENTAL PERIOD.
- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT THE HIRER SHOULD REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- THE VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY DARWIN-51 CAR RENTAL PTE. LTD.
- AN ADDITIONAL EXCESS OF \$2000 OF ALL CLAIM WILL APPLY FOR VEHICLE USE OUTSIDE SINGAPORE AND \$3000 FOR AGE ABOVE 65.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
04/07/2019	15:45 HRS				



TERMS AND CONDITIONS FOR CAR RENTAL

DARWIN-51 CAR RENTAL PTE. LTD. (hereinafter) called the "owner" which expression shall where the context so admits include the owner's successors-in-title hereby agrees to let and the hirer named herein (therein-after called "the Hirer") agrees to take on hire the motor vehicle described herein (hereinafter called "the said vehicle") subject to the following terms and conditions:-

1. The said vehicle (and all tools and accessories therein) is the property of the Owner and the Hirer shall be a mere bailee thereof and no interest in it shall pass on to the Hirer.

2. The hiring shall commence on the date and at the time specified and shall continue for the period and end on the date and at the time stated unless extended or as expressly requested by the Hirer.

3. The Hirer shall pay in full the hire charge specified herein before the commencement of hiring. No part of such hire charge shall in any circumstances be refunded except at the discretion of the Owner. All credit return is subject to the approval of General Manager.

4. If the Hirer shall fail to return the said vehicle at the expiration of the period of hire, then without prejudice to the rights of the Owner, the Hirer shall pay to the Owner for every hour elapsing between the time of such expiration and the time the said vehicle is returned to the Owner, such further other charge in accordance with the Owner's current rate of hire charges or at such other rates as the Owner may in its absolute discretion thinks fit. All charges and amounts due which are not paid when due shall bear an interest of 1.5% per month until they are paid.

5. The said vehicle may only be driven by the Hirer or persons who have expressly designated and authorized therein (hereinafter called "the authorized driver"). The Hirer and the authorized driver must be in possession of a valid driving licence and shall at all times drive the said vehicle in a careful and skillful manner, observing the traffic regulations and laws and in the event of any breach thereof, the Hirer shall pay all fines, cost repairs and penalties which may be incurred and shall also answer all Police and Traffic Court Summonses, Notices and Inquiries in connection therewith. Particular attention is to be accorded to the following:-

(i) The Hirer shall not carry load or passengers in excess of the Motor Vehicle's Licensed carrying capacity (i.e. one driver and four passengers);

(ii) The Hirer shall not drive the said vehicle whilst under the influence of intoxicating liquor or drugs;

(iii) It is expressly forbidden to hire the said vehicle out to third persons or to let unauthorized persons or learners to use the said vehicle or to permit the said vehicle to be used for illegal purposes (for instance: in connection with theft, drug peddling or trafficking, smuggling or any other criminal activity) or the purposes of test or racing. Failure to comply may entail serious consequences as the Hirer assumes full responsibility and in the event of the said vehicle being seized, confiscated or forfeited as a result thereof, the Hirer shall indemnify the Owner for all losses incurred including the value of the said vehicle;

(iv) The Hirer and the authorized driver must be over 24 years of age and under 60 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be Borne by the Hirer.

6. The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$30.00 per trip.

7. The Hirer or authorized driver shall report all accidents involving the said vehicle to the Owner immediately and should there be bodily injuries also to the police not later than 24 hours after the accident. The Hirer or authorized driver shall not admit or compound any claim either partially or in full. Hirer is to secure the names and addresses of all witnesses as well as the registration number of all vehicles involved in the accident. All communications or letters received from the police or third parties are to be referred to the owner immediately. The Hirer shall not abandon the said vehicle without adequate provisions for safeguarding and security the same. Failure to comply with rule 5 and 7 will render Hirer liable for all cost and third party claims irrespective of CDW fee being paid.

8. The Owner shall not under any circumstances be liable to make any payment to the Hirer in respect of or to indemnify the Hirer against any loss,

injury or damage sustained by the Hirer or by any third party as result of the use of the said vehicle or as result of any defect therein and in taking delivery of the said vehicle the hirer shall be deemed to have satisfied himself that it is in all respects roadworthy and in a proper and safe condition.

9. If for any reason the vehicle described in the schedule of any other vehicle ordered by the Hirer prior to the commencement of the period of hire is not available at the time of such commencement, the Owner shall have the right to replace the said vehicle with an alternative vehicle of similar seating capacity and performance and if no such alternative vehicle is available or if the Owner shall decline to provide an alternative vehicle then the Hirer shall be repaid any hire charge and deposit (if any) paid by him after offsetting the rental charge and costs incurred but shall have no other claim of any kind whatsoever against the Owner. However if no deposit is paid, Hirer must pay for rental charges incurred on demand.

10. The Hirer shall pay for the cost of petrol during the period of hiring PROVIDED ALWAYS that the Hirer having taken delivery of the said vehicle with a full tank of petrol shall return it likewise failing which the Owner shall be entitled to refill the tank and the refilling cost including a S\$5 service charge thereof shall be recoverable from the Hirer.

11. The vehicle is NOT covered by a motor insurance policy covering personal accident insurance for the Hirer, his passenger or authorized driver and the Owner shall not be responsible for any liability claims, injuries or otherwise in connection with any accident death or the losses arising from the use of the vehicle. The Owner may at the request of the Hirer and upon payment of the requisite charges arrange for separate personal accident coverage for bodily injury or death.

12. The said vehicle shall be covered under a Vehicle Insurance policy, which contains an excess Clause as Stipulated / Stated in the current Owner's Car rental Standard Brochure Tariff. Paying the current premium rate per day for Collision Damage Waiver may reduce the excess Clause. For the category of vehicle hired Collision Damage Waiver does not cover Missing / Stolen vehicles' item.

13. On or prior to the expiration of the period of hire, the Hirer shall return the said vehicle together with all tyres, tools, accessories and equipment to the Owner at any of the Owner's designated stations in as good order and condition as the said vehicle was when collected by the Hirer from the owner.

14. No relaxation forbearance or indulgence by the Owner in enforcing any of the terms and conditions of this Agreement shall prejudice or affect the rights and powers of the Owner hereunder nor shall any waiver or any breach operate as a waiver of any subsequent or continuing breach.

15. The Hirer is responsible for obtaining the required cash card with sufficient balance prior entry into any roads within the ERP system.

16. In the breach of the terms and conditions of the agreement the Owner reserves the right to resume possession of the hired vehicle at anytime from the Hirer in the Owners' interest without prejudice.

17. The Owner shall not be liable to the Hirer or any person for any loss or damage whatsoever and howsoever caused or occasioned by reason of the Owner resuming possession of the vehicle nor shall the Owner be liable to any person for monies, goods, articles or things not belonging to the Owner which are in or alleged to be in the vehicle at the time the Owner resumes possession of the vehicle.

18. The Hirer shall not take the said vehicle outside mainland Singapore, Malaysia or any other territory outside Singapore without the written consent of the Owner. Failure to comply with this term may entail serious consequences and the Hirer shall assume personal and full responsibility and in the event of the said vehicle being damaged, seized, confiscated or forfeited as a result thereof, the Hirer shall indemnify the Owner for all losses incurred including the value of the said vehicle.

19. That in addition, the Hirer shall be deemed to have extended the period of hire by reason of the Hirer's failure to return the said vehicle or continued possession and / or continued use of the said vehicle upon the same terms and contained herein. The Hirer shall also be bound by these terms and conditions in respect of any replacement vehicle hired in lieu of the said vehicle by means of new Rental Agreement or Replacement Voucher.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KK TRANSPORT SERVICES
286B TOH GUAN ROAD #03-32
SINGAPORE 602286

Contact : 90664988

TAX INVOICE

Date : 07/11/2019
Date in : 26/06/2019
Vehicle Num. : SKA7195P
Make/Model : TOYOTA WISH 1.8 CVT-2011
Chassis/Eng# : JTDGG20W405001682/2ZRA680371
Accident Date : 24/06/2019
Claim No : CLM14599
Reference : JUN-44/2019
Policy No. : 5088532375-02 (27/03/2020)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0472-19-TCA DATED 21/10/2019
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$
7,300.00

E. & O.E.	Sub S\$:	7,300.00
	Add GST (7%) S\$:	511.00
	Total Amount S\$:	7,811.00



for TWINCAR AUTOMOTIVE PTE LTD

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0472-19-TCA

21 October 2019

KK Transport Services
Blk 286B Toh Guat Road #03-32
Singapore 602286

INVOICE No. 0472-19-TCA


Vehicle No. SKA7195P

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$662.00
Total amount payable		<u>\$662.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn No: 5298074L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax 645 36131.

Report No: 0472-19-TCA

21 October 2019

ACCIDENT VEHICLE SURVEY REPORT

KK Transport Services
Blk 286B Toh Guat Road #03-32
Singapore 602286

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SKA7195P	<i>Odometer:</i>	61396km
<i>Make & Model:</i>	Toyota Wish 1.8 CVT	<i>Colour:</i>	White
<i>Chassis number:</i>	JTDGG20W405001682	<i>Date of accident:</i>	24/06/2019
<i>Year of Regn.:</i>	28/03/2011	<i>Date inspected:</i>	28/06/2019
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	03/07/2019

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

P&R Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131

Report No: 0472-19-TCA

21 October 2019

ACCIDENT VEHICLE SURVEY REPORT

KK Transport Services
Blk 286B Toh Guat Road #03-32
Singapore 602286

VEHICLE INFORMATION:

Vehicle Reg No.:	SKA7195P	Odometer:	61396km
Make & Model:	Toyota Wish 1.8 CVT	Colour:	White
Chassis number:	JTDGG20W405001682	Date of accident:	24/06/2019
Year of Regn.:	28/03/2011	Date inspected:	28/06/2019
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	03/07/2019

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Continental	5mm/Continental	195/65R15
Rear:	5mm/Continental	5mm/Continental	195/65R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear LH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy**Parts and Labour Assessment****PARTS**

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BUMPER	1	squashed	480.20	480.20 ✓
REAR BUMPER END SEAL COVER LH	1	deformed	231.35	231.35 ✓ 167.19
REAR BUMPER REFLECTOR L/R	2	L-fractured	166.40	83.20 ✓
REAR BUMPER SIDE BRACKET L/R	2	L-bent	282.90	141.45 X SVC
REAR BUMPER SIDE RETAINER L/R	2	necessary	242.20	242.20 ✓
REAR END PANEL	1	buckled	581.40	581.40 ✓
REAR END PANEL INNER TOP GARNISH	1	fractured	38.55	38.55 X SVC
REAR LH FENDER	1	buckled	880.75	880.75 ✓
REAR LH FENDER GLASS WITH MOULDING	1	necessary	950.00	950.00 ✓ 184
REAR LH FENDER INNER AIR VENT	1	warped	161.50	161.50 ✓
REAR LH FENDER INNER TOOL BRACKET	1	buckled	298.00	298.00 X SVC
REAR LH FENDER INNER TRIM BOARD	1	deformed	681.40	681.40 ✓
REAR LH TAILLAMP	1	fractured	581.90	581.90 ✓
REAR LH TAILLAMP INNER BLACK GASKET	1	necessary	35.00	35.00 ✓
REAR TAILGATE WEATHERSTRIP	1	deformed	281.50	281.50 X SVC
Subtotal before discount			S\$ 5,893.05	S\$ 5,668.40
Percentage discount 25% and 25%			S\$ 1,473.26	S\$ 1,417.10
Sub-total 1			S\$ 4,419.79	S\$ 4,251.30
REAR BUMPER CLIPS - SET	1	necessary	100.00	100.00 30 ✓
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00 X SVC
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	50.00	50.00 X n1
REAR FLOOR PANEL INSULATOR MAT	1	necessary	300.00	300.00 X SVC
REAR LH FENDER GLASS SEALANT	1	necessary	100.00	80.00 40 ✓
REAR LH FENDER INNER TRIM BOARD CLIPS - SET	1	necessary	60.00	60.00 30 ✓
REAR LH FENDER PETROL LID RIVET - SET	1	necessary	40.00	40.00 X SVC
REAR LH TAILLAMP CLIPS - SET	1	necessary	30.00	30.00 X n1
Subtotal before discount			S\$ 1,030.00	S\$ 1,010.00
Sub-total 2			S\$ 1,030.00	S\$ 1,010.00
Parts-total			S\$ 5,449.79	S\$ 5,261.30

PAR Automotive Consultancy

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

120.00 60.00 30

To remove, reinstall tailgate windscreen (fender glass)

300.00 150.00 100

To remove, reinstall petrol tank. (to FR)

80.00 80.00 X

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00 120.00 100

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,100.00 1,000.00 600

To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.

2,000.00 1,750.00 1200

To apply anti-rust chemical on repaired and replaced panel.

120.00 90.00 50

To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.

100.00 80.00 X

Labour Total SS 3,960.00 SS 3,330.00


Parts & Labour Total SS 9,409.79 SS 8,591.30

2080

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 7,300.00
and the recommended number of working days for the repairs is within 8 day(s).


B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

P- 3058.98
M- 90
L- 2080
5228.98
L/S- 4183.18
= 4200

7 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19011216/Epa3s2-1	
C/O: VISION LAW LLC 133 NEW BRIDGE ROAD #18-01/02 CHINATOWN POINT SINGAPORE 059413		Date : 09-03-2020	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SMA 6167D	Veh. Inspected	SKA 7195P
Policy No.	P2145121	Coverage (\$)	0.00
Claim No.	AM-atv-INS-T140-110836-19	Excess (\$)	0.00
Assign From		Assign Date	10/12/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTDGG20W405001682	Colour	WHITE
Odometer	350917	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	5 mm
L/H Front Tyre	195/65 R15	DUNLOP	5 mm
R/H Rear Tyre	195/65 R15	DUNLOP	5 mm
L/H Rear Tyre	195/65 R15	DUNLOP	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	24/06/2019	Inspection Date	28/02/2020
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 7195P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	REPLACED	480.20	480.20
1	REAR BUMPER END SEAL COVER LH	REPLACED	231.35	167.10
2	REAR BUMPER REFLECTOR L/R	N/S REPLACED	166.40	83.20
2	REAR BUMPER SIDE BRACKET L/R	SERVICEABLE	282.90	-
2	REAR BUMPER SIDE RETAINER L/R	REPLACED	242.20	242.20
1	REAR END PANEL	REPLACED	581.40	581.40
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	38.55	-
1	REAR LH FENDER	REPLACED	880.75	880.75
1	REAR LH FENDER GLASS WITH MOULDING	REPLACED	950.00	184.00
1	REAR LH FENDER INNER AIR VENT	REPLACED	161.50	161.50
1	REAR LH FENDER INNER TOOL BRACKET	SERVICEABLE	298.00	-
1	REAR LH FENDER INNER TRIM BOARD	REPLACED	681.40	681.40
1	REAR LH TAILLAMP	REPLACED	581.90	581.90
1	REAR LH TAILLAMP INNER BLACK GASKET	REPLACED	35.00	35.00
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	281.50	-
	LESS 25% DISCOUNT		-1,473.26	-1,019.67
			4,419.79	3,058.98
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	REPLACED	100.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	350.00	-
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR FLOOR PANEL INSULATOR MAT (SN)	SERVICEABLE	300.00	-
1	REAR LH FENDER GLASS SEALANT (SN)	REPLACED	100.00	40.00
1	SET REAR LH FENDER INNER TRIM BOARD CLIPS (SN)	REPLACED	60.00	20.00
1	SET REAR LH FENDER PETROL LID RIVET (SN)	SERVICEABLE	40.00	-
1	SET REAR LH TAILLAMPS CLIPS (SN)	NOT NECESSARY	30.00	-
			1,030.00	90.00
LABOUR				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	30.00
	TO REMOVE, REINSTALL FENDER GLASS.		300.00	100.00
	TO REMOVE, REINSTALL PETROL TANK. (TO FR)	NOT NECESSARY	80.00	-

Report Ref No. CC4/ASM19011216/Epa3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	100.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,100.00	600.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		2,000.00	1,200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	50.00
	TO TRANSFER REAR TAILGATE INNER TRIM BOARD, WIPER MOTOR, MECHANISM LOCK OUTER HANDLE.	NOT NECESSARY	100.00	-
			3,960.00	2,080.00
	GRAND TOTAL		9,409.79	5,228.98
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CC4/ASM19011216/Epa3s2-1

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.