

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021722/KKA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100475624

Claimant
Vehicle No : GBF1515U **Insured Vehicle No :** SFC3306L

Date of Loss: 08/12/2019 Nature of Claim: TP Claim No: 7776279724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF1515U		
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Engine No:	1KD2609594
Reg. Date:	13/07/2016 (Man. Year: 2016)	Chassis No:	KDH2010195409
Colour:	Red	Odometer:	113973 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,321.22	5,622.52	1,698.70	23.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,830.00	1,190.00	39.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,341.22	7,452.52	2,888.70	27.93
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	10,341.22	5,900.00	4,441.22	42.95
+ GST 7.00/7.00% (S\$)	723.89	413.00	310.89	42.95
Nett Amount (S\$)	11,065.11	6,313.00	4,752.11	42.95
+ Car Rental (4.0 x S\$70.00/day + 7.00% GST) (S\$)		299.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,614.60		
Global Sum Settlement (S\$)		6,590.00		

INSPECTION

Date of Assignment: 09/12/2019

Date Inspected: 10/12/2019 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,248.50 FL	*1,248.50 FL
2	2		*FRONT RH DOOR HINGE	Repair	181.40 FL	*- FL
3	1		*FRONT RH DOOR INNER RUBBER	Serviceable	268.70 FL	*- FL
4	1		*FRONT RH DOOR INNER LOCK	Repair	381.50 FL	*- FL
5	1		*FRONT RH WHEEL TOP PANEL	Repair	681.50 FL	*- FL
6	1		*FRONT RH DOOR REAR PILLAR	Bent	891.50 FL	*891.50 FL
7	1		*FRONT RH DOOR REAR PILLAR INNER PANEL	Bent	781.50 FL	*781.50 FL
8	1		*REAR RH DOOR	Bent	1,718.50 FL	*1,718.50 FL
9	1		*REAR RH DOOR LOWER HINGE	Bent	281.50 FL	*281.50 FL
10	1		*REAR RH DOOR LOWER LOCK	Distorted	395.20 FL	*395.20 FL
11	1		*REAR RH DOOR AUTO MOTOR	Distorted / Jammed	1,258.50 FL	*1,258.50 FL
12	1		*REAR RH DOOR INNER RUBBER	Serviceable	278.50 FL	*- FL
13	1		*REAR RH DOOR INNER SENSOR RUBBER	Cut	781.50 FL	*781.50 FL
14	1		*REMOVE STICKER	Necessary	380.00 FS	*80.00 FS
15	1		*ROC STICKER	Necessary	80.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,608.30	7,461.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,287.08	1,839.18
Total Parts (\$\$)	7,321.22	5,622.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT FRONT RH DOOR GLASS	New	120.00	120.00
2	TUFFKOTE	New	150.00	90.00
3	WIRING	New	150.00	20.00
4	SPRAY PAINTING	New	1,200.00	800.00
5	LABOUR CHARGES	New	1,400.00	800.00
Gross Labour Cost (\$\$)			3,020.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >