

# NEW HOCK TECK MOTOR PTE LTD

Our Ref : SLD7327Z  
Your Ref : SJL7607Y  
Date : 10/12/2019

1 Kaki Bukit Ave 6  
Blk C @ Autobay, #01-43  
Singapore 417883  
Tel : (65) 6747 9241  
Fax : (65) 6741 7276

FWD SINGAPORE PTE LTD

**BY EMAIL**

[motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)

Attn : Motor Claims Department

Dear Sirs,

DATE OF ACCIDENT : **07 DEC 2019 @ 15:30 hours**

**NOTICE OF INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We act for **TAN ENG HOCK** who has appointed the undermentioned workshop  
to repair motor vehicle no. **SLD7327Z**

Please be informed that the said vehicle can be inspected at :

**NEW HOCK TECK MOTOR PTE LTD  
1 KAKI BUKIT AVE 6  
#01-43 BLK C @ AUTOBAY  
SINGAPORE 417883**

Contact Person : Office @ 6747 9241 (Reena / Sukyi)

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The said workshop will commence repairs thereafter without further reference to you.

Yours Faithfully

  
\_\_\_\_\_  
New Hock Teck Motor Pte Ltd

For Surveyor.

Please initial here after completion of  
Pre-repair inspection. Thank you

Surveyor Name :  
& signature

Date&Time :