

**Vic (LKKAUTO)**

---

**From:** Vic (LKKAUTO)  
**Sent:** Thursday, 27 February, 2020 10:01 AM  
**To:** Lee, Ming-Yao  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** <SEEK MANDATE> Your Ref: 9910128005SG - ACCIDENT INVOLVING VEHICLES SMP 4598C (OI) AND PC 3432L (TP) ON 09/12/2019 - LKK REF CC6/AIG19021737/Aha3

**Your Ref: 9910128005SG**  
**Our Ref: CC6/AIG19021737/Aha3**

Dear Ming Yao,

ACCIDENT INVOLVING VEHICLES SMP 4598C (OI) AND PC 3432L (TP) ON 09/12/2019

We refer to the subject matter.

It was reported that Insured vehicle had rear-ended TP vehicle.

A letter was sent out to the Insured and till date, no feedback received.

Summary to offer to repairer **NEW HOCK TECK MOTOR PTE LTD** is as follows:

TP CLAIMED		REVISED - TO OFFER
Cost of Repair (w/gst)	\$ 24,171.62	\$ 6,741.00
Loss of Use (\$350 x 9 days)	\$ 3,150.00	\$ 1,350.00 (\$150 x 9 days)
GIA Search Fee	\$ 2.00	\$ 2.00
<b>TOTAL</b>	<b>\$ 27,323.62</b>	<b>\$ 8,093.00</b>

Breakdown of days is as follows:

Recommended days	7 Days
Weekends / Downtime	2 Days
<b>TOTAL</b>	<b>9 Days</b>

Relevant supporting claim documents are uploaded in merimen for your perusal.

For your approval and/or further instruction please.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.